



BLACK LIQUOR RECOVERY BOILER

ADVISORY COMMITTEE

Meeting Minutes

Crowne Plaza Hotel/Atlanta Airport

Atlanta, Georgia

April 5, 6, & 7, 2004

OBJECTIVE

The objective of BLRBAC is to promote improved safety of chemical recovery boilers and their auxiliaries through the interchange of technical knowledge, experience, and data on past and any future recovery boiler incidents. *Bylaws - 2.1*

OFFICERS

Chairman: Dean Clay Tel: 513-248-6564
International Paper Fax: 513-248-6679
P. O. Box 7910 **dean.clay@ipaper.com**
Loveland, OH 45140-7910

Vice-Chairman: Karl Morency Tel: 404-652-4629
Georgia-Pacific Fax: 404-584-1466
P. O. Box 105605 **ktmorenc@gapac.com**
Atlanta, GA 30348-5605

Secretary: Mike Polagye Tel: 781-255-4730
FM Global Fax: 781-762-9375
P. O. Box 9102 **michael.polagye**
Norwood, MA 02062 **@fmglobal.com**

Treasurer: Ron Hess Tel: 706-484-1723
HSB Forest Products Group Fax: 706-485-5267
110 Cedar Cove Court **ronald_hess@hsb.com**
Buckhead, GA 30625

REGULAR MEMBERSHIP

Organizations operating, manufacturing, or insuring chemical recovery boilers are eligible.

ASSOCIATE MEMBERSHIP

Organizations having a direct interest or role in the safety of chemical recovery boilers are eligible.

CORRESPONDING MEMBERSHIP

A company residing outside of the United States which finds it impractical to attend meetings on a regular basis because of distance and expenses, but desires to be involved and informed of BLRBAC activities.

* * * * *

BLRBAC INTERNET ADDRESS: ---- www.blrbac.org
IRS Employer ID/Tax ID (IRS E.I.N.T./T.I.N) ---- #13-366-5137

EXECUTIVE COMMITTEE

Dean Clay
BLRBAC Chairman
 International Paper
 P. O. Box 7910
 Loveland, OH 45140-7910
 Tel: 513-248-6564
 Fax: 513-248-6679
dean.clay@ipaper.com

Mike Polagye
BLRBAC Secretary
 FM Global
 P. O. Box 9102
 Norwood, MA 02062
 Tel: 781-255-4730
 Fax: 781-762-9375
michael.polagye@fmglobal.com

Scott Moyer
BLRBAC Operator Representative
 Rayonier Performance Fibers
 P. O. Box 2070
 4470 Savannah Highway
 Jesup, GA 31598
 Tel: 912-427-5140
 Fax: 912-427-5008
scott.moyer@rayonier.com

Jimmy Onstead
BLRBAC Insurance Representative
 FM Global
 Granite Park One
 5800 Granite Parkway, Ste. 600
 Plano, TX 75024
 Tel: 972-731-1656
 Fax: 972-731-1820
jimmy.onstead@fmglobal.com

Karl Morency
BLRBAC Vice Chairman
 Georgia-Pacific
 P. O. Box 105605
 Atlanta, GA 30348-5605
 Tel: 404-652-4629
 Fax: 404-584-1466
ktmorenc@gapac.com

Ron Hess
BLRBAC Treasurer
 HSB Forest Products Group
 110 Cedar Cove Court
 Buckhead, GA 30625
 Tel: 706-484-1723
 Fax: 706-485-5267
ronald_hess@hsb.com

Preston Morgan
BLRBAC Manufacturing Representative
 Kvaerner
 3430 Toringdon Dr, Ste. 201
 Charlotte, NC 28227
 Tel: 704-414-3402
 Fax: 704-541-3683
preston.morgan@akerkvaerner.com

**Secretarial
 Services:**

Barbara Holich
 1005 59th Street
 Lisle, IL 60532

Tel: 630-512-0144
 Fax: 630-512-0155
 E-Mail: **fholich@aol.com**

BLRBAC SUBCOMMITTEES

<p>EMERGENCY SHUTDOWN PROCEDURES John Andrews -- Chairman MeadWestvaco Corp. P. O. Box 118005 Charleston, SC 29423-8005 Tel: 843-745-3212 Fax: 843-745-3229 jda6@meadwestvaco.com</p>	<p>FIRE PROTECTION IN DIRECT CONTACT EVAPORATORS Chris Jackson -- Chairman Global Risk Consultants Corp. c/o 12848 SW Thunderhead Way Beaverton, OR 97008 Tel/Fax: 503-671-9829 chris.jackson@globalriskconsultants.com</p>
<p>INSTRUMENTATION David Avery – Chairman Weyerhaeuser P. O. Box 678 Bennettsville, SC 29512 Tel: 843-479-0200, Ext. 458 or 335 Fax: 843-479-6603 Dave.avery@weyerhaeuser.com</p>	<p>MATERIALS & WELDING Dan Phillips – Chairman (new) Industra Service Corp. 4122 NE 185th Avenue Portland, OR 97230 Tel: 503-624-9100 Fax: 503-624-9994 dphillips@industrainc.com</p>
<p>PERSONNEL SAFETY Robert Zawistowski -- Chairman Power Specialists Associates, Inc. 531 Main Street Somers, CT 06071 Tel: 860-763-3241, Ext. 126 Fax: 860-763-3608 bob.zawistowski@psaengineering.com</p>	<p>PUBLICITY & NEWS RELEASE Craig Cooke -- Chairman FM Global 815 Byron Drive Oconomowoc, WI 53066 Tel: 262-567-7370 Fax: 847-430-7699 craig.cooke@fmglobal.com</p>
<p>SAFE FIRING OF AUXILIARY FUEL Dave Streit -- Chairman Buckeye Florida One Buckeye Drive Perry, FL 32348 Tel: 850-584-1402 Fax: 850-584-1717 dave_streit@bkitech.com</p>	<p>SAFE FIRING OF BLACK LIQUOR Len Erickson -- Chairman Boise Cascade P. O. Box 50 Boise, ID 83728-0001 Tel: 208-384-4933 Fax: 208-384-7637 lenerickson@boisepaper.com</p>
<p>WASTE STREAMS John Rickard -- Chairman Jacobs-Sirrine P. O. Box 5456 Greenville, SC 29606 Tel: 864-676-6393 Fax: 864-676-6005 john.rickard@jacobs.com</p>	

BLRBAC MEETING SCHEDULE

Fall	2004	--	October	4, 5, & 6
Spring	2005	--	April	4, 5, & 6
Fall	2005	--	October	3, 4, & 5
Spring	2006	--	April	3, 4, & 5

"Bring Operator(s). Give them a chance to hear first hand!"

■ Past Chairman Lon Schroeder

BLRBAC has created its own WEB Site which is:

www.blrbac.org

At this WEB site you will find a copy of the next Meeting Notice. Therefore, each Representative and Associate Representative is asked to inform their people of this WEB site and this is where they should obtain the following information for the BLRBAC meetings:

BLRBAC MEETING NOTICE**COVER LETTER**

General Information

REGISTRATION FORM

Print and mail to Said & Done with appropriate fees

CROWNE PLAZA HOTEL

Blocked room dates, pricing, address, hotel phone number, alternate hotel information, etc.

SCHEDULE

List of Subcommittee activities on Monday & Tuesday

AGENDA

Reports given to Joint BLRBAC Meeting on Wednesday

DELTA AIRLINE

Reduced rates and contact phone number, including discounted Avis rates for BLRBAC attendees.

OPERATING PROBLEMS:

Mail/e-mail completed forms back to Said & Done. These will be given to the Operating Problems Subcommittee Chairman. He will see that your concerns are brought up and discussed during the Operating Problems session at the next meeting.

Mrs. Barbara Holich
Said & Done
1005 59th Street
Lisle, IL 60532
fhholich@aol.com

BLRBAC Publications List

The following is the current status of the BLRBAC publications and are available at the **BLRBAC INTERNET ADDRESS:**

www.blrbac.org

Recommended Practices by BLRBAC

(Click on “Recommended Practices” on BLRBAC Home page)

Emergency Shutdown Procedure (ESP)

91kb (October 2003)

Fire Protection in Direct Contact Evaporators and Associated Equipment

162kb **(April 2004) – Revised**

Checklist and Classification Guide for Instruments and Control Systems

409kb (April 2002)

Personnel Safety

208kb **(April 2004) – Revised**

Post ESP Guidelines

139kb (October 2002)

Safe Firing of Auxiliary Fuel in Black Liquor Recovery Boilers

653kb (October 2002)

Safe Firing of Black Liquor in Black Liquor Recovery Boilers

728kb (March 2004)

Waste Stream Incineration

374kb (April 2002)

Mike Polagye
BLRBAC Secretary
FM Global
P. O. Box 9102
Norwood, MA 02062

Phone: 781-255-4730
Fax: 781-762-9375
michael.polagye@fmglobal.com

EMERGENCY SHUTDOWN PROCEDURES SUBCOMMITTEE

John Andrews* -- Chairman
 MeadWestvaco Corp.
 P. O. Box 118005
 Charleston, SC 29423-8005
 Tel: 843-745-3212; Fax: 843-745-3229
jda6@meadwestvaco.com

<p>Dean Clay* International Paper P. O. Box 7910 Loveland, OH 45140-7910 Tel: 513-248-6564 Fax: 513-248-6679 dean.clay @ipaper.com</p>	<p>Jack Clement* Clement Consulting, Inc. 563 Beaverbrook Drive Akron, OH 44333-2818 Tel: 330-865-9779 Fax: 330-865-6960 clementcon @cs.com</p>	<p>James Franks* GE GAP Services 855 Dogwood Road Somerville, TN 36068 Tel: 901-465-0771 Fax: 888-964-7348 james.franks @gegapservices.com</p>
<p>Chris Gore* Weyerhaeuser P. O. Box 678 Bennettsville, SC 29512 Tel: 843-479-0200, Ext. 420 Fax: 843-479-9481 chris.gore @weyerhaeuser.com</p>	<p>Ralf Holm* Andritz, Inc. 10745 Westside Parkway Alpharetta, GA 30004 Tel: 770-640-2614 Fax: 770-640-2521 ralf.holm @andritz.com</p>	<p>John Kulig* Babcock & Wilcox P. O. Box 351 Barberton, OH 44203-0351 Tel: 330-860-6438 Fax: 330-860-9427 Jakulig @babcock.com</p>
<p>Mark LeBel* Alstom Power P. O. Box 500, 1112-2406 Windsor, CT 06095-0500 Tel: 860-285-2238 Fax: 860-285-5078 mark.lebel @power.alstom.com</p>	<p>Karl Morency* Georgia-Pacific P. O. Box 105605 Atlanta, GA 30348-5605 Tel: (404) 652-4629 Fax: (404) 654-4748 Ktmorenc @gapac.com</p>	<p>Robert Norton* Norske Canada P. O. Box 2000 (Elk Falls) Campbell River, BC V9W 5C9 Canada Tel: (250) 287-5344 Fax: (250) 287-5399 bob.norton @norskecanada.com</p>
<p>Bo Oscarsson Fluor Daniel Forest Products 100 Fluor Daniel Dr., 106-B Greenville, SC 29607-2762 Tel: (864) 281-5010 Fax: (864) 676-7479 bo.oscarsson @fluor.com</p>	<p>David Parrish* FM Global P. O. Box 9102 Norwood, MA 02062 Tel: 781-255-4734 Fax: 781-762-9375 david.parrish @fmglobal.com</p>	<p>John Weikmann* Aker Kvaerner 3430 Toringdon Way, Suite 201 Charlotte, NC 28277 Tel: 704-414-3431 Fax: 704-541-7128 john.wikmann @akerkvaerner.com</p>

* = Attended 04/04 Meeting

INSTRUMENTATION SUBCOMMITTEE

David Avery* – Chairman

Weyerhaeuser Company

P. O. Box 678

Bennettsville, SC 29512

Tel: 843-479-0200, Ex.458 or 335; Fax: 843-479-6603

david.avery@weyerhaeuser.com

<p>Richard Pothier* - Sec. RiNan, Inc. 44 Glen Drive Peabody, MA 01960 Tel: 978-535-2520 Fax: 978-535-3502 rinan44 @aol.com</p>	<p>Bill McQuillan* SAPPI (S.D. Warren Company) RR #3, Box 1600 Skowhegan, ME 04976 Tel: 207-238-3219 Fax: 207-238-3479 bill.mcquillan @na.sappi.com</p>	<p>J. C. Browning, Jr.* Alabama River Pulp Co., Inc. P. O. Box 100 Perdue Hill, AL 36470 Tel: 334-743-8336 Fax: 334-743-8332 Johnb @ariver.com</p>
<p>William Camp* International Paper Co. 100 Jensen Road Prattville, AL 36067 Tel: 334-361-5620 Fax: 334-361-5619 bill.camp @ipaper.com</p>	<p>Michael Fay* Simpson Tacoma Kraft Co. P. O. Box 2133 Tacoma, WA 98421 Tel: 253-596-0250 Fax: 253-596-0160 mfay @simpson.com</p>	<p>Alan Laflamme Eastern Paper 50 Katahdin Avenue Lincoln, ME 04457 Tel: 207-794-6721, Ext. 291 Fax: 207-794-3964 alaflam @easternpaper.com</p>
<p>Gail Lance* Babcock & Wilcox P. O. Box 351 Barberton, OH 44203 Tel: 330-860-2628 Fax: 330-860-2220 gjance @babcock.com</p>	<p>Rick Matarrese* FM Global 655 Engineering Dr, #300 Norcross, GA 30092 Tel: 770-777-3684 Fax: 770-777-0414 rick.matarrese @fmglobal.com</p>	<p>Dan Mott* Irving Pulp & Paper Ltd. P. O. Box 3007, Station B Saint John, NB, E2M 3H1 Canada Tel: 506-632-4149 Fax: 506-633-5598 mott.dan @irvingpulp.com</p>
<p>Roger Smith* Georgia-Pacific Corp. P. O. Box 105605 Atlanta, GA 30303 Tel: 404-652-4264 Fax: 404-584-1466 resmith @gapac.com</p>	<p>Jari Sopenen* Andritz, Inc. 10745 Westside Parkway Alpharetta, GA 30004 Tel: 770-640-2528 Fax: 770-642-9057 jari.sopenen @andritz.com</p>	

* = Attended 04/04 Meeting

MATERIALS & WELDING SUBCOMMITTEE**Dan Phillips – Chairman (new)**

Industra Service Corp.
4122 NE 185th Avenue
Portland, OR 97230
Tel: 503-624-9100; Fax: 503-624-9994
dphillips@industrainc.com

ORBITAL WESCO
Welding Engineering Services Co.
Tel./Fax: 503-720-9270
phillipsdan@comcast.net

<p>James G. Dixon-Vice Chair* Weyerhaeuser Highway 10 E., P.O. Box 336 Pine Hill, AL 36769 Tel: 334-963-2481 Fax: 334-963-2761 jim.dixon @weyerhaeuser.com</p>	<p>Mike Barry 2000 Dayhill Road Windsor, CT 06095 Tel: 860-285-3920 Fax: 860-285-5078 mike.barry @power.alstom.com</p>	<p>George Bodman* 13 Kingwood Villas Court Kingwood, TX 77339 blrelgdr @aol.com</p>
<p>Buddy Brown Alstom Power 1119 Riverfront Parkway Chattanooga, TN 37402 Tel: 423-752-2200 Fax: 423-752-2660 richard.a.brown @power.alstom.com</p>	<p>James Duncan* FM Global 111 Frontier Drive, Apt. 500G Staunton, VA 24401 Tel: 540-886-2743 Fax: N/A james.duncan @fmglobal.com</p>	<p>David K. Fuhrmann* International Paper 6285 TriRidge Blvd Loveland, OH 45140 Tel: 513-248-6954 Fax: 513-248-6679 dave.fuhrmann @ipaper.com</p>
<p>Michael Garfield* Hartford Steam Boiler 191 Tannery Road Lowell, ME 04493 Tel: 207-732-5168 Fax: 207-732-5168 michael_garfield @hsb.com</p>	<p>Richard J. Godin SAPPI (S. D. Warren Company) P. O. Box 1600 Skowhegan, ME 04976-9512 Tel: 207-238-7685 Fax: 207-238-7530</p>	<p>Fabian Henriques* MeadWestvaco 232 8th Street Chillicothe, OH 45601 fah1 @meadwestvaco.com</p>

* = Attended 04/04 Meeting

MATERIAL & WELDING SUBCOMMITTEE (Cont.)

<p>Dennis Hollenbach* Alstom Power 2000 Dayhill Road Windsor, CT 06095 Tel: 860-285-9214 Fax: 860-285-5078 dennis.hollenbach @power.alstom.com</p>	<p>Lasse Koivisto Andritz Relanderinkatu 2 78200 Varkaus, Finland Tel: 358-17-578-211 lasse.koivisto @andritz.com</p>	<p>Dave Lang* FM Global 400 Interpace Pkwy Bldg. C Parsippany, NJ 07054-1196 Tel: 973-541-6868 Fax: 973-402-1070 david.lang @fmglobal.com</p>
<p>Tom Lezzer* Appleton Papers, Inc. 100 Paper Mill Road Roaring Spring, PA 16673 Tel: 814-224-6450 Fax: 814-224-6661 tlezzer @appletonideas.com</p>	<p>Ron McCarty P. O. Box 1559 Sandia Park, NM 87047-1559 Tel: 505-286-7888 Fax: 505-286-7887 bobronmac @worldnet.att.net</p>	<p>Del McKamey* Industra 1122 NE 185th Avenue Portland, OR 97224 Tel: 603-624-9100 Fax: 603-624-9994 dmckamey @industrainc.com</p>
<p>Stephen L. Meiley M&M Engineering 300A Lake Street Ramsey, NJ 07446 Tel: 201-785-9229 Fax: 201-785-9555 steve_meiley @mmengineering.com</p>	<p>Max D. Moskal* Mechanical & Materials Engrng 11020 W. 72nd Street Indian Head Park, IL 60525 Tel: 708-784-3564 Fax: 708-784-3612 max_moskal @mmengineering.com</p>	<p>Steve Osborne* Babcock & Wilcox 20 S. Van Buren Avenue Barberton, OH 44203 Tel: 330-860-1229 Fax: 330-860-9319 slosborne @babcock.com</p>
<p>Bob Patrick MeadWestvaco P. O. Box 757 Escanaba, MI 49825 Tel: 906-786-1660 Fax: 906-786-3558 rap @meadwestvaco.com</p>	<p>Ed Rambo* Sage of America 4907 Old Lee Highway Doltervale, TN 37363 Tel: N/A Fax: N/A ed @sageofamerica.com</p>	<p>Pat Rank Pope & Talbot P. O. Box 400 Halsey, OR 97348 Tel: 541-369-1167 Fax: 541-369-1192 pat_rank @poptal.com</p>

* = Attended 04/04 Meeting

MATERIAL & WELDING SUBCOMMITTEE (Cont.)

<p>Mark Schwartz MeadWestvaco 3131 Newmack Drive Miamisburg, OH 45327 Tel: 937-495-5360 Fax: 937-495-5333 MES8 @meadwestvaco.com</p>	<p>David Stasuk* Stasuk Testing Ltd. 7642 Winston Street Burnaby, BC Canada Tel: 604-410-4433 Fax: N/A dstasuk @nde.com</p>	<p>Robert P. Sullivan* The National Board of Boiler & Pressure Vessel Inspectors 1055 Crupper Avenue Columbus, OH 43229 Tel: 614-888-8320 Fax: 624-847-1828 rsullivan @nationalboard.org</p>
<p>W. Kirk Thomas Packaging Corp. of America P. O. Box 1048 Valdosta, GA 31603-1048 Tel: 912-559-2301 Fax: 912-559-2338</p>	<p>John Vanden Hoek GE GAP Services 87 Charters Road Brampton, Ontario L6V 2S8 Canada john.vandenhoeck @gegapservices.com</p>	<p>Billy Walker* C.N.A Risk Control 4701 Porchaven Lane Apex, NC 27539 Tel: 919-773-8001 Fax: 919-773-8090 billywalker @cna.com</p>
<p>Tom Watkins Nova Resourcing Group 8559 Bellingrath Road Theodore, AL 36582 Tel: 334-653-9277 Fax: 334-653-7504 twatkins @nrggroupinc.com</p>	<p>Mike Welch* Welding Services, Inc. 2225 Skyland Court Norcross, GA 30071 Tel: 678-728-9275 Fax: 770-209-0639 mwelch @wsi.aquilex.com</p>	<p>Roy Williams Hartford Steam Boiler 12925 Chets Creek Road Jacksonville, FL 32824 Tel: 904-992-8430 Fax: 904-992-8430 roy_williams @hsb.com</p>
<p>Jim Young* CIMS Ltd. 5355 Parkwood Place Richmond, BC V6V 2N1 Canada Tel: 604-274-9065 Fax: 604-274-9095 jyoung @cimsltd.com</p>		

* = Attended 04/04 Meeting

PERSONNEL SAFETY SUBCOMMITTEE

Robert E. Zawistowski* - Chairman
 Power Specialists Associates, Inc.
 531 Main Street
 Somers, CT 06071
 Tel: 860-763-3241, Ext. 126; Fax: 860-763-3608
bob.zawistowski@psaengineering.com

<p>Fred Able* AXA Corporate Solutions Assurance Rhone-Alpes 235, cours Lafayette 69006 Lyons, France Tel: +33 4 72 83 29 41 Fax: +33 4 72 83 29 40 frederic.abel@axa-corporatesolutions.com</p>	<p>Ken Baker Smurfit-Stone Container Corp. P.O. Box 100544 Florence, SC 29501-0544 Tel: 843-662-0313, Ext. 279 Fax: 843-269-0167 kbaker@smurfit.com</p>	<p>George Barr Weyerhaeuser Kamloops Mail Stop 101 P. O. Box 800 Kamloops, BC, Canada Tel: 250-851-7860 Fax: 250-828-7745 george.barr@weyerhaeuser.com</p>
<p>Jim Dickinson* Babcock & Wilcox Company 20 S. Van Buren Avenue Barberton, OH 44203-0351 Tel: 330-860-1229 Fax: 330-860-9319 jadickinson@babcock.com</p>	<p>Thomas (Rick) Durham Georgia Pacific Corporation 133 Peachtree St., NE (30303) P. O. Box 105605 Atlanta, GA 30348-5605 Tel: 404-652-5990 Fax: 404-584-1466 trdurham@gapac.com</p>	<p>David Fuhrmann International Paper Company 6285 Tri-Ridge Road Loveland, OH 45140-7910 Tel: 513-248-6954 Fax: 513-248-6679 dave.fuhrmann@ipaper.com</p>
<p>David Gadai* Alstom Power, Inc. 2000 Day Hill Road Windsor, CT 06095-0500 Tel: 860-285-4297 Fax: 860-285-5078 dave.gadai@power.alstom.com</p>	<p>Ronald Hess HSB Forest Products Group 110 Cedar Cove Court Buckhead, GA 30625 Tel: 706-484-1723 Fax: 706 485-5267 ronald_hess@hsb.com</p>	<p>Daryl Hoffman* FM Global 601 108th Avenue SE, Ste.1400 Bellevue, WA 98004 Tel: 425-637-2363 Fax: n/a daryl.hoffman@thebest.net</p>

* = Attended 04/04 Meeting

PERSONNEL SAFETY SUBCOMMITTEE (Cont.)

<p>Marko Kvist Andritz Services, Inc. 10745 Westside Parkway Alpharetta, GA 30004 Tel: 770-640-2516 Fax: 770-640-2455 marko.Kvist @andritz.com</p>	<p>Larry Lindsey* MeadWestvaco P.O. Box 940 Phenix City, AL 36868-0940 Tel: 334-855-5024 Fax: 334-855-5172 GLL1 @meadwestvaco.com</p>	<p>Jamison Manion MeadWestvaco 35 Hartford Street Rumford, ME 04276 Tel: 207-369-2479 Fax: 207-369-2813 JJM11 @meadwestvaco.com</p>
<p>Preston Morgan* Kvaerner 3430 Toringdon Dr, Ste 201 Charlotte, NC 28227 Tel: 704-414-3402 Fax: 704-541-3683 preston.morgan @akerkvaerner.com</p>	<p>Len Olavessen* Buckman Laboratories International 1256 North McLean Blvd. Memphis, TN 38108-1241 Tel: 800-282-5626 Fax: 901-272-6451 lrolavessen @buckman.com</p>	<p>Lynn Rawls* GE GAP Services 200 College Avenue Charlotte, NC Tel: 601-928-9420 Fax: 601-928-9420 lynn.rawls @gegapservices.com</p>
<p>Rick Spangler Rick Spangler, Inc. 310 John Shaw Road St. Simons Island, GA 31522 Tel: 912-638-1324 Fax: 912-634-9697 spangler @thebest.net</p>	<p>Robert P. Sullivan The National Board of BPVI 1055 Crupper Avenue Columbus, OH 43229-1183 Tel: 614-888-8320 Fax: 614-847-1828 rsullivan @nationalboard.org</p>	

* = Attended 04/04 Meeting

PUBLICITY & NEW RELEASE SUBCOMMITTEE

Craig Cooke* - Chairman
FM Global
815 Byron Drive
Oconomowoc, WI 53066
Tel: 262-567-7370; Fax: 262-567-7370
craig.cooke@fmglobal.com

* = Attended 04/04 Meeting

SAFE FIRING OF AUXILIARY FUEL SUBCOMMITTEE

Dave Streit* – Chairman

Buckeye Florida
One Buckeye Drive
Perry, FL 32348

Tel: 850-584-1402; Fax: 850-584-1717

dave_streit@bkitech.com

<p>Allen L. Ray – Sec. Barron Industries, Inc. 105 19th Street South Birmingham, AL 35210 Tel: 205-956-3441 Fax: 205-956-2265 allen_ray @barronind.com</p>	<p>John Alesandrini Babcock & Wilcox Co. P. O. Box 351 Barberton, OH 44203-0315 Tel: 330-860-6001 Fax: 330-860-2220 jmalesandrini @babcock.com</p>	<p>Scott Crysel* FM Global 5800 Granite Pkwy., Ste. 600 Plan, TX 75024 Tel: 972-731-1658 scott.Crysel @fmglobal.com</p>
<p>Robert DeCarrera Georgia-Pacific Corp. 133 Peachtree St. N.E. Atlanta, GA 30303 Tel: 404-652-4686 Fax: 404-654-4746 rdecarre @gapac.com</p>	<p>Lino DiLeonardo* GE GAP Services d/b/a GE Canadian IRI P. O. Box 166 Toronto, ON M5V 3C7 Tel: 416-217-5530 Fax: 416-217-5531 lino.dileonardo @industrialrisk.com</p>	<p>Bruce Knowlen Weyerhaeuser Company WTC 1B22 P. O. Box 9777 Federal Way, WA 98063 Tel: 253-924-6434 Fax: 253-924-4380 bruce.knowlen @weyerhaeuser.com</p>
<p>Jim Quandt (Alt.) Weyerhaeuser Company P. O. Box 275 Springfield, OR 97477 Tel: 541-741-5428 Fax: 541-741-5895 jim.quandt @weyerhaeuser.com</p>	<p>Ivan Semyanko, PE ABB Alstom Power, Inc. CEP Code 1017-2406 2000 Day Hill Road Windsor, CT 06095 Tel: 860-285-3953 Fax: 860-285-4020 ivan.semyanko @us.abb.com</p>	

* = Attended 04/04 Meeting

SAFE FIRING OF BLACK LIQUOR SUBCOMMITTEE**Len Erickson, Chairman***

Boise Paper Solutions

P. O. Box 50

Boise, ID 83728-0001

Tel: 208-384-4933; Fax: 208-384-7637

lenerickson@boisepaper.com

<p>Mark Sargent -- Co-Chair* International Paper 6285 Tri-Ridge Blvd. Loveland, OH 45140-7910 Tel: 513-248-6086 Fax: 513-248-6679 mark.sargent@ipaper.com</p>	<p>Larry Hiner Babcock & Wilcox P. O. Box 351 Barberton, OH 44203-0351 Tel: 330-860-6525 Fax: 330-860-9295 lahiner@babcock.com</p>	<p>Majed Ja'arah* Inland Paperboard & Packaging 1750 Inland Road Orange, Texas 77632 Tel: 409-746-7315 Fax: 409-746-7249 mjarah@iccnet.com</p>
<p>Brian Lemay* FM Global 165 Commerce Valley Dr. West,#500 Thornhill, ON L3T 7V8 Tel: 905-763-5683 Fax: 905-763-5622 brian.lemay@fmglobal.com</p>	<p>Brad Merritt GE GAP Services 200 S. College St., Ste. 1630 Charlotte, NC 28202 Tel: (704) 353-6468 Fax: (704) 376-2928 bradley.merritt@gegaps.com</p>	<p>Scott Moyer* Rayonier Performance Fibers Box 2070,4470 Savannah Hwy Jesup, GA 31598 Tel: 912-427-5140 Fax: 912-427-5008 scott.moyer@rayonier.com</p>
<p>Doug Murch* MeadWestvaco 3475 Newmark Drive Miamisburg, OH 45342 Tel: 937-495-9237 Fax: N/A douglas.murch@meadwestvaco.com</p>	<p>Arie Verloop* Jansen Comb. & Blr. Tech. 12025 115th Ave. NE, Ste.250 Kirkland, WA 98034-6943 Tel: 425-825-0500 Fax: 425-825-1131 arie.verloop@jansenboiler.com</p>	<p>Richard Wiseman Weyerhaeuser 100 Center Street Johnsonburg. PA 15857 Tel: 814-965-6223 Fax: 814-965-6413 richard.wiseman@weyerhaeuser.com</p>
<p>Rick Young* Alstom Power 1119 Riverfront Parkway Chattanooga, TN 37402 Tel: 423-752-2603 Fax: 423-752-2660 frederick.young@power.alstom.com</p>		

* = Attended 04/04 Meeting

**FIRE PROTECTION IN DIRECT CONTACT EVAPORATORS
AND ASSOCIATED EQUIPMENT**

Chris Jackson* -- Chairman

Global Risk Consultants Corp.
c/o 12848 SW Thunderhead Way
Beaverton, OR 97008
Tel/Fax: 503-671-9829

chris.jackson@globalriskconsultants.com

<p>Randy Baker Buckeye Technologies One Buckeye Drive Perry, FL 32348 Tel: 850-584-1380 Fax: 850-584-1738 randy_baker @bkitech.com</p>	<p>Craig Cooke* - Co-chairman FM Global 815 Byron Drive Oconomowoc, WI 53066 Tel: 262-567-7370 Fax: 847-430-7411 craig.cooke @fmglobal.com</p>	<p>John Lisenby International Paper P. O. Box 950 Vicksburg, MS 39180 Tel: 601-631-8371 Fax: 601-631-8392 john.lisenby @ipaper.com</p>
<p>Joseph Lynch (Secretary) GE GAP Services 1105 Sanctuary Pkwy., Ste 200 Alpharetta, GA 30004-4741 Tel: 770-569-7091 Fax: 888-964-7348 joe.lynch @ge.com</p>	<p>Nick Merriman, sappi Forest Products Tugela Republic of South Africa Tel: +27 (0) 32 456 1433 Fax: N/A nick.merriman @sappi.com</p>	<p>Steve Osborne* Babcock & Wilcox 20 S. Van Buren Ave. Barberton, OH 44203 Tel: 330-860-1686 Fax: 330-860-9023 slosborne @babcock.com</p>
<p>George Orme Allianz 7480 Cason Circle Gladstone, OR 97207 Tel: 503-657-8530 Fax: N/A gorme @aic-allianz.com</p>		

* = Attended 04/04 Meeting

WASTE STEAMS SUBCOMMITTEE

John Rickard -- Chairman
 Jacobs Engineering
 P. O. Box 5456
 Greenville, SC 29606
 Tel: 864-676-6393; Fax: 864-676-6005
john.rickard@jacobs.com

<p>Craig J. Aderman* sappi (S. D. Warren) P. O. Box 1600 Skowhegan, ME 04976-9512 Tel: 207-238-3177 Fax: 207-856-3675 craig.aderman @sappi-na.com</p>	<p>Henry Beder Weyerhaeuser WTC 2G25 P. O. Box 9777 Federal Way, WA 98003 Tel: 253-924-4242 Fax: 253-924-5920 hank.beder @weyerhaeuser.com</p>	<p>Mark E. Cooper* FM Global Key Center 601 108th Ave., NE, Ste. 1400 Belluvue, WA 98004 Tel: 425-709-5084 Fax: 425-454-7847 mark.cooper @fmglobal.com</p>
<p>E. Scott Crysel FM Global Granite Park One Plano, TX 75024 Tel: 972-731-1658 Fax: 972-731-1820 scott.crysel @fmglobal.com</p>	<p>Ned Dye* Jansen Combustion &Boiler Technologies 12025 115th Ave. NE, Ste. 250 Kirkland, WA 98034-6935 Tel: 425-825-0500, Ext. 125 Fax: 425-825-1131 ned.dye @jansenboiler.com</p>	<p>Jerry Garner BE&K Engineering P. O. Box 12607 Birmingham, AL 35202-2607 Tel: 205-972-6432 Fax: 205-972-6300 garnerj @bek.com</p>
<p>Arnie Iwanick* Harris Group, Inc. 1750 NW Naito Parkway Portland, OR 97209-2530 Tel: 503-345-4516 Fax: 503-228-0422 arnie.iwanick @harrisgroup.com</p>	<p>Brian Kaufmann Kimberly-Clark 1400 Holcomb Bridge Rd. Roswell, GA 30076-2199 Tel: 770-587-7230 Fax: 770-587-7736 bkaufmann @kcc.com</p>	<p>Olli Kujanpaa* Andritz 10745 Westside Parkway Alpharetta, GA 30004 Tel: 770-640-2571 Fax: 770-640-2455 olli.kujanpaa @andritz.com</p>

* = Attended 04/04 Meeting

WASTE STREAMS SUBCOMMITTEE (Cont.)

<p>John Lewis* Fluor Daniel Forest Products 100 Fluor Daniel Drive Greenville, SC 29607-2762 Tel: 864-281-8535 Fax: 864-676-7630 john.lewi @fluordaniel.com</p>	<p>Wayne Macintire* International Paper P. O. Box 7910 Loveland, OH 45140-7910 Tel: 513-248-6834 Fax: 513-248-6679 wayne.macintire @ipaper.com</p>	<p>Rob Orender* Georgia Pacific Corp. 133 Peachtree St., 18th floor Atlanta, GA 30303 Tel: 404-652-4606 Fax: 404-584-1466 rhorende @gapac.com</p>
<p>Winston "Jerry" Pate* Smurfit Stone Container Corp. P. O. Box 709 Brewton, AL 36427 Tel: 251-867-8371 Fax: 251-867-1153 wpate @smurfit.com</p>	<p>Jean-Claude Patel A. H. Lundberg Assoc., Inc. 406 Sagebrush Road Naperville, IL 60565 Tel: 630-355-5120 Fax: 630-355-5120 jc.patel @lundbergassociates.com</p>	<p>Paul Seefeld* A. H. Lundberg Assoc., Inc. 4577 Pebble Brook Drive Jacksonville, FL 32224-7643 Tel: 904-223-4147 Fax: 904-223-4146 paul.seefeld @lundbergassociates.com</p>
<p>H. Bentley Sherlock* Babcock & Wilcox 2302 Parklake Dr.,NE, Ste.300 Atlanta, GA 30345 Tel: 770-621-3947 Fax: 770-621-3922 hbsherlock @babcock.com</p>	<p>Michael D. Sides* GE GAP Services 1105 Sanctuary Pkwy, Ste.200 Alpharetta, GA 30004-4741 Tel: 770-569-7123 Fax: 888-964-7348 michael.sides @gegaps.com</p>	<p>B. K. Wadhvani Coen, Inc. 1510 Rollins Road Burlingame, CA 94010 Tel: 650-686-3271 Fax: 650-686-5655 bwadhvani @coen.com</p>

* = Attended 04/04 Meeting

Registered for the meeting were:

Abitibi-Consolidated

Gustafson, Larry, Fort Frances, ON

Alabama River Pulp

Browning, John, Perdue Hill, AL
 Edwards, Bobby, Perdue Hill, AL
 Gornto, Bruce, Perdue Hill, AL
 Needham, Chris, Perdue Hill, AL
 Newton, Carlos, Monroeville, AL
 Standridge, Tim, Perdue Hill, AL
 Thomas, Anthony, Perdue Hill, AL
 Timothy, Eugene, Perdue Hill, AL
 Wilson, Joe, Perdue Hill, AL

Alert Systems, Inc.

Borsje, Henk, Duxbury, MA

Alstom Power

Barry, Mike, Charlotte, NC
 Gadai, David, Windsor, CT
 Grasso, Bob, Vancouver, WA
 Holbrook, John, Sykesville, MD
 Hollenbach, Dennis, Windsor, CT
 Kistka, Gerry, Jacksonville, FL
 LeBel, Mark, Windsor, CT
 Quinlan, Michael, Chattanooga, TN
 Young, Frederick, Chattanooga, TN

AMEC E&C Inc.

Dresser, Bob, Alpharetta, GA
 Dunlap, Bill, Greenville, SC

American Forest & Paper Assoc.

Grant, Thomas, Yonkers, NY

Andritz, Inc.

Collins, Peter, Alpharetta, GA
 Holm, Ralf, Alpharetta, GA
 Kujanpaa, Olli, Alpharetta, GA
 Lindh, Timo, Alpharetta, GA
 Phillips, John, Alpharetta, GA
 Sapanen, Jari, Curitiba, Brazil
 Treger, Glen
 Alpharetta, GA

Appleton Papers

Lezzer, Tom, Roaring Spring, PA

Automation Applications

Vigeant, Marc, Fort Mill, SC

AXA Corporate Solutions

Abel, Frederic, Lyon, France

Babcock & Wilcox

Blair, Michael, Atabaster, AL
 Dickinson, Jim, Barberton, OH
 Kittel, David, St. Marys, CA
 Kulig, John, Barberton, OH
 Lance, Gail, Barberton, OH
 Osborne, Steve, Barberton, OH
 Sherlock, H. Bentley, Atlanta, GA
 Yash, John, Atlanta, GA

Blue Ridge Paper Products

Hennessy, Kevin, Canton, NC
 Holland, Brook, Canton, NC

Boise Cascade

Erickson, Leonard, Boise, ID
 Nease, Scott, DeRidder, LA
 Schlieff, Scott, Wallula, WA
 Stensberg, Paul, International Falls, MN
 Zavadoski, Greg, St. Helens, OR

Bowater

Hitch, Tony, Calhoun, TN
 Moses, Roger, Calhoun, TN

Buckeye Technologies

Streit, David, Perry, FL

Buckman Laboratories

Graham, Jim, Memphis, TN
 Olavessen, Len, Memphis, TN

C.N.A. Risk Control

Walker, Billy, Apex, NC

Registered for the meeting were:

Chaddick Consulting, Inc.

Chaddick, Louis, Wando, SC

ChemTreat

Kanney, Mike, Glen Allen, VA

CIMS Ltd

Young, Jim, Richmond, BC

Clement Consulting

Clement, Jack, Akron, OH

Coen Company

Wadhvani, B.K., Burlingame, CA

Cooperheat - MQS

O'Connor, Shawn, North Augusta, SC

CORR System, Inc. (TTS)

Ruiz de Molina, Eladio, Birmingham, AL

Delta National Kraft

Taylor, Lynn, Pine Bluff, AR

Diamond Power

Abdallah, Rami, Lancaster, OH
Kaminski, Bob, Lancaster, OH
Tavares, Alarick, Lancaster, OH
Whitehead, Brian, Lancaster, OH

Dynamic Energy Systems

McClain, Cliff, St. Albert, MO

Electron Machine Corp., The

Jarrett, Gordon, Umatilla, FL
Vossberg, Carl III, Umatilla, FL
Vossberg, Carl IV, Umatilla, FL

Environmental Elements

Bringman, Lewis, Baltimore, MD
Elam, Stan, Hot Springs, VA
Hug, Don, Baltimore, MD
Shelton, Jeff, Baltimore, MD

FLS - Airtech

Shanahan, Dennis, Pensacola, FL
Brown, Mike, Jacksonville, AL

Fluor Daniel Forest Products

Lewis, John, Greenville, SC

FM Global

Cloutier, Guy, Montreal, QU
Cooke, Craig, Oconomowoc, WI
Cooper, Mark, Bellevue, WA
Crysel, Scott, Plano, TX
Hoffman, Daryl, Bellevue, WA
Janusauskas, Paul, Montreal, QU
Lamb, Ron, Parsippany, NJ
Lang, David, Bedminster, NJ
Lemay, Brian, Thornhill, ON
Matarrese, Rick, Alpharetta, GA
Onstead, Jimmy, Plano, TX
Parrish, David, Norwood, MA
Polagye, Mike, Norwood, MA

G&M Consultadores, Ltda

Schreiber, Guido, Canoinhas, Brazil

GA Dept. of Labor

Everett, Earl, Atlanta, GA
Hancock, Gerry, Atlanta, GA

Gaylord Container

Villarrubia, David, Bogalusa, LA

GE GAP Services

DiLeonardo, Lino, Toronto, ON
Franks, James, Somerville, TN
Rawls, Lynn, Perkinston, MS
Sides, Michael, Ocoee, FL

General Reinsurance Corp.

Freeman, Stuart Jr., Atlanta, GA

Registered for the meeting were:

George H. Bodman, Inc.

Bayse, Michael, Kingwood, TX
Bodman, George, Kingwood, TX

Georgia-Pacific

Andrews, Jimmy, Pennington, AL
Burney, S. L., Atlanta, GA
Emerson, Randy, Ashdown, AR
Morency, Karl, Atlanta, GA
Orender, Robert, Atlanta, GA
Phillips, Tony, Palatka, FL
Smith, Roger, Atlanta, GA
Tenbrunsel, Robert, Atlanta, GA
Yarbrough, Lonnie, Palatka, FL

Global Risk Consultants

Jackson, Christopher, Beaverton, OR
Smith, Andy, Atlanta, GA

Gulf States Paper

Duckworth, Marty, Demopolis, AL

Harris Group

Iwanick, Arnie, Portland, OR

Hartford Steam Boiler

Garfield, Michael, Lowell, ME
Hess, Ron, Buckhead, GA

Hercules

Bowen, Glenn, Glenwood, NY
Gaus, Jeff, Shreveport, LA

HSB Professional Loss Control

DeBeer, Thomas, Woodstock, GA

Industra

McKamey, Del, Portland, OR
Phillips, Dan, Portland, OR

Inland Paperboard & Packaging

Ja'arah, Majed, Orange, TX

Inst. of Paper Science & Tech.

Verrill, Chris, Atlanta, GA

International Paper

Camp, Bill, Prattville, AL
Clay, Dean, Loveland, OH
Fuhrmann, Dave, Loveland, OH
MacIntire, Wayne, Loveland, OH
Sargent, Mark, Loveland, OH

Interstate Paper Corp.

Crosby, Phillip, Riceboro, GA

Irving Pulp & Paper

Murray, Trevor, Saint John, NB
Savoy, Dave, Saint John, NB

Jansen Technologies

Drottar, Jerry, Kirkland, WA
Dye, Ned, Kirkland, WA
Verloop, Arie, Kirkland, WA

John E. Cover Engineering, Inc.

Cover, John, Birmingham, AL

Kimberly-Clark

Chiasson, Mike, New Glasgow, NS
Kaufmann, Brian, Roswell, GA
Sponagle, David, New Glasgow, NS

K-Patents, Inc.

Hamalainen, Arto, Naperville, IL
Pyorala, Keijo, Naperville, IL

Kvaerner Pulping

Abrams, Larry, Charlotte, NC
Campbell, Craig, Charlotte, NC
Christiansen, Gene, Charlotte, NC
Geedey, Jim, Charlotte, NC
King, Dave, Charlotte, NC
McKinney, Carolyn, Charlotte, NC
Morgan, Preston, Charlotte, NC
Sherrod, Hank, Charlotte, NC
Wasson, Eric, Charlotte, NC
Weikmann, John, Charlotte, NC

Registered for the meeting were:

Liquid Solids Control

Sweeney, Michael, Upton, MA

Longview Fibre

Berg, Greg, Longview, WA

Marsh, Inc.

Hyche, Dwight, Meridian, MS

MeadWestvaco

Andrews, John, Charleston, SC
Lindsey, Larry, Phenix City, AL
Long, Rick, Charleston, SC
Murch, Douglas, Miamisburg, OH
Williams, Jimmy, Phenix City, AL

Mechanical & Materials Engrg.

Moskal, Max, Indian Head Park., IL

Nalco

Totura, George, Naperville, IL

National Board of BPVI

Sullivan, Robert, Columbus, OH

Norske Skog

Norton, Bob, Campbell River, BC

P. H. Glatfelter Co.

Gentzler, Bill, Spring Grove, PA

Packaging Corp. of America

Farris, Mike, Counce, TN
Ferrell, Larry, Valdosta, GA
Hilgendorf, Joe, Tomahawk, WI
Jelinek, Bob, Tomahawk, WI
Stelling, John, Tomahawk, WI

Potlatch

Bliss, Dave, McGehee, AR
Hartley, Chuck, North Las Vegas, NV

Power Specialists Assoc. Inc.

Bernard, Ron, Somers, CT
Blaylock, Tommy, Somers, CT
Madersky, Lee Anne, Somers, CT
Madersky, Tom, Somers, CT
Popielnicki, Ted, Somers, CT
Zawistowski, Bob, Somers, CT

Process Equipment

Nolen, Ken, Pelham, AL
Ray, Allen, Pelham, AL

PROSWECO

Thorslund, Gunnar, Brazil

Rayonier

Goober, Glynn, Jesup, GA
Moyer, Scott, Jesup, GA
Roberts, Willie, Jesup, GA
Wingate, Danny, Jesup, GA
Yeomans, Scott, Jesup, GA

Rigesa Celulose

Klitzke, Rudimar, Tres Barras, Brazil

RiNan, Inc.

Pothier, Richard, Peabody, MA

RMR Mechanical

Roy, Bob, Cumming, GA

Sage of America

Rambo, Edward, Onetewak, TN

SAPPI Forest Products

Aderman, Craig, Westbrook, ME
Luedtke, Scott, Cloquet, MN
McQuillan, Bill Skowhegan, ME

Simpson Tacoma Kraft Co.

Fay, Michael, Tacoma, WA

Registered for the meeting were:

Smurfit Carton de Colombia

Cubillos, Jairo, Cali, Colombia
Franco, Daniel, Cali, Colombia

Smurfit-Stone Container

Allard, Andre-Benoit, New Richmond, QU
Craig, David, Hodge, LA
Dykes, Phillip, Panama City, FL
Dykes, Tommy, Panama City, FL
English, Phil, Jacksonville, FL
Fuster, Pedro, Panama City, FL
Jones, Robert, Stevenson, AL
Mills, Drexel, Missoula, MT
Morin, Nathalie, Latuque, QU
Pate, Jerry, Brewton, AL
Phelps, Bob, Hopewell, VA
Wynn, Doug, Stevenson, AL

Southern Environmental

Cotton, Rick, Pensacola, FL
Hayes, Charles, Pensacola, FL

SRV Associates

van der Veen, Steve, Boston, MA

Stasuk Testing & Inspection Ltd.

Stasuk, David, Burnaby, BC

Tembec

Terrell, Carl, St. Francisville, LA
Thornton, Jeff, St. Francisville, LA

Teck Cominco

Pistner, Peter, Trail, BC
Reiter, Brian, Trail, BC

Temple-Inland Forest Products

Scoggins, Jim, Sugarland, TX

Utilities Project Mgt., Inc.

Osthoff, James, Ray, OH

Welding Services, Inc.

Welch, Mike, Norcross, GA

Weyerhaeuser

Avery, David, Bennettsville, SC
Cooley, Mark, Bennettsville, SC
Dixon, Jim, Pine Hill, AL
Gore, Chris, Bennettsville, SC
Harrison, Danny, Pine Hill, AL
Keech, Randy, Bennettsville, SC
Larrimore, Brad, Pine Hill, AL
Touchton, Robert, Oglethorpe, GA
Worsham, Jesse, Bennettsville, SC

INTRODUCTION

BLRBAC's Chairman, Dean Clay, called the meeting to order at 8:00 a.m. on Wednesday, April 7th.

CHAIRMAN: I'd like to welcome all of you to the spring meeting. This is the BLRBAC Main Committee Meeting. We do have a published agenda and will attempt to follow the agenda this morning. We want to thank you for your continued support and attendance.

OLD BUSINESS

ACCEPTANCE OF MINUTES OF FALL 2004 – Dean Clay

The first item of our business meeting is to approve the Minutes from the fall 2003 meeting. These Minutes are posted on the BLRBAC.ORG Web site. That has been our procedure now for the last year or two. Hopefully, the new Minutes will be available on-site within two months after the conclusion of the meeting. We are still attempting to e-mail the members and attendees with a Notice that the Minutes have been posted. We are no longer mailing out Meeting Minutes. So again, they are all available on the BLRBAC WEB site. The voting members should have a red ribbon. So when I call for a vote, please just have the voting members respond. There should be one member per company. So I now would entertain a motion from the voting members to approve the Minutes from the fall 2003 meeting. Could I have a second? Okay. All in favor please raise your hand. Opposed? The Minutes stand approved.

NEW BUSINESS

1. NEW MEMBERS/REPRESENTATIVE CHANGES REPORT – Mike Polagye

Last night at the Executive Committee Meeting eight applications for membership in BLRBAC were reviewed and approved. Those included:

NEW REGULAR MEMBERSHIP

None at this time.

1. NEW MEMBERS/REPRESENTATIVE CHANGES REPORT (Cont.)

NEW ASSOCIATE MEMBERSHIPS

Applied Technical Services (ATS), Marietta, GA -- Providing NDE services for recovery boilers.

Rodney Thomas designated as Associate Representative

Mark Elrod designated as Alternate Associate Representative

Boiler Tek, Saraland, AL -- Providing mechanical repair for recovery boilers.

O. T. Moody designated as Associate Representative

Fred L. Pace designated as Alternate Associate Representative

Diffusion Technologies, Saraland, AL -- Providing erosion/corrosion coating application services for recovery boilers.

Fred L. Pace designated as Associate Representative

O. T. Moody designated as Alternate Associate Representative

F. L. Smidth Airtech, Inc., Bethlehem, PA -- Providing electrostatic precipitators for recovery boilers and other boilers.

Dennis Shanahan designated as Associate Representative

Mike Brown designated as Alternate Associate Representative

Prosweco AB, Stockholm, Sweden -- Providing technical services for recovery boilers.

Gunnar Thorslund designated as Associate Representative

Peter Aspgrén designated as Alternate Associate Representative

Sage of America Company, Collegedale, TN -- Providing technical services for recovery boilers.

Marcio Gerep designated as Associate Representative

Edward Rambo designated as Alternate Associate Representative

To each of these, as well as our other current Associate members offer services that support recovery boiler operation and safety; we welcome you as new Associate members to BLRBAC. We encourage and solicit your participation on our subcommittee work, especially addressing issues that are related to your areas of expertise. Again, the primary focus of BLRBAC is recovery boiler safety. We look forward to all of you, the operating companies, the boiler manufacturers, the insurance companies and our Associate members, to help us by maintaining our Recommended Practices and providing us with the best information that we can have in there so that we achieve our goal of recovery boiler safety.

1. NEW MEMBERS/REPRESENTATIVE CHANGES REPORT (Cont.)

CORRESPONDING MEMBERSHIP

Propal Pulp & Paper, Columbia, South America. They operate two recovery boilers.

Alfonso Ocampo designated as Corresponding Representative

Moises Castillo designated as Alternate Corresponding Representative

PT Lontar Papyrus Pulp & Paper Industry, Jakara, Indonesia. Operating two recovery boilers.

Hasrul Khaidir designated as Corresponding Representative

Richard Stonebridge designated as Alternate Corresponding Representative

REGULAR REPRESENTATIVE CHANGES

Georgia-Pacific

Karl Morency replaces Jules Domingues as Representative

Rick Durham replaces Karl Morency as Alternate Representative

Smurfit-Stone

Phil English replaces Hollis Elder as Representative

ASSOCIATE REPRESENTATIVE CHANGES

AMEC E&C Services, Inc.

N. W. Dunlap, Jr. designated as Associate Representative

Don Sorenson designated as Alternate Associate Representative

Universal Dynamics, Ltd.

Dale Roskob replaces Eddie Koyama as Alternate Associate Representative

MEMBERSHIP COMPANY NAME CHANGE

AMEC E&C Services, Inc.

Previously Simons Engineering

2. EXECUTIVE COMMITTEE REPORT – Dean Clay

We met in closed session on Tuesday afternoon with all seven members present. As noted in our fall Minutes, Joan Barna passed away on October 26, 2003. Joan had been a member of the Executive Committee and Chairman of the Materials & Welding Subcommittee. We miss Joan both personally and professionally. To allow us to continue on, we have appointed Preston Morgan of Kvaerner to the Executive Committee as the Boiler Manufacturers' Representative.

2. EXECUTIVE COMMITTEE REPORT (Cont.)

I'd like to quickly review the Executive Committee members. The current composition is:

I'm the Chairman of BLRBAC. Karl Morency from Georgia-Pacific is the Vice-Chairman. Mike Polagye of FM Global is our Secretary. Ron Hess of HSB Forest Products is the Treasurer. Scott Moyer of Rayonier Performance Fibers is the Operator Representative. As noted, Preston Morgan of Kvaerner is the Boiler Representative. Jimmy Onstead is the Insurance Representative.

BLRBAC was formed by those three groups: insurance, operators and boiler manufacturers. That's the reason we always maintain a representative from each group on the Executive Committee. Every two years we vote on a new slate of officers. The next vote is schedule to be held in the Main Committee Meeting on Wednesday, October 6, 2004. Per our procedures, we have selected a Nominating Committee to present a proposed list of candidates for the members to vote on. Ron Hess has agreed to head up that committee. Dave Streit and Mark Sargent will be on the committee also. If you have any input, please feel free to contact any of them. As a note, the membership up for vote will be Chairman, Vice-Chairman, and then the three Representatives: Insurance Representative, Operators Representative and Boiler Manufacturers Representative. The Secretary and Treasurer positions are nominated positions by the Executive Committee. We will also accept nominations from the floor at the time of the vote.

Dan Phillips of Industra, who was the Co-chairman of Materials & Welding, has agreed to become the Chairman of that Subcommittee. We thank you for that Dan.

We have reviewed the work of the Subcommittees and we are going to have two changes to our Recommended Practices to vote on this morning. There are also several additional changes to be presented to the Executive Committee for our review. If we agree with the changes, those will be posted on our WEB site for membership review. We encourage everyone to look at the WEB site and read through the proposed changes. It's important, if members disagree or can find a better way to do it, they should feed this information back to the Subcommittee. Usually we don't get much feedback. So, we are assuming that we are doing good work, but we would encourage you to read it. It may have some impact on you in the future.

We have also agreed to support a joint AF&PA/BLRBAC Seminar on Water Treatment. This kind of follows a progression of seminars on no particular schedule. We had some on Materials & Corrosion, Welding, etc. Currently we intend to do this following the spring 2005 meeting. The seminar will start Wednesday afternoon, after lunch, and conclude Thursday, probably at 5:00 p.m. We are still finalizing it. We will be publishing information on that seminar.

2. EXECUTIVE COMMITTEE REPORT (Cont.)

Last night we had a jointly sponsored BLRBAC-supplier hospitality function sports night downstairs across from the pool. We encourage you to provide us with any feedback as to whether that is something we should continue to do or not.

Another announcement, the TAPPI Steam & Power Energy Management Committee meetings will be held following BLRBAC today.

Finally, and I think Len Erickson will mention this also, there is a March 2004 revision to the Safe Firing of Black Liquor Guidelines document currently posted on the WEB site. If any of you had downloaded the previous version, we found some errors in that document. The current version is dated March 2004 and is the correct version.

3. TREASURER'S REPORT -- Ron Hess

We had 182 Advance registrations for this meeting. Thirty-one people chose to register At-Door. That represented 28 paper companies; seven insurance companies, four manufacturers, 34 Associate member companies and we had five guests. Our foreign visitors, we have two from Colombia; two from Brazil; and one from Sweden. That comprises the population for this particular meeting.

On the financial side, the organization has two financial accounts. We have a checking account used for operations. The balance of that account is approximately \$34,000.00, before we pay the bills for this event. We also have a CD with a balance is right at \$15,000.00. So the increase in membership fees has helped give us a little bit of cushion on the side for the financial operations. We had a financial audit performed of the books in 2003. I'm still here, so it was a successful audit.

Attached to the e-mail that announces these Meeting Minutes are posted on the Web site will be a short member survey/questionnaire for you to give us some feedback. We encourage you to give us the requested information. It can be returned electronically or by hard copy back to Barbara Holich. It is pretty short, trying to get some information from you; how you attend and why you attend; things of that nature. We are trying to get a handle on the fluctuation of membership and things that we can do differently to try to maintain member participation.

As Dean indicated, everything is driven off your e-mail address. So again, to repeat to you, please keep your e-mail address current and try to advise us of any changes. You can do it on the back of your luncheon ticket or you can just send Barbara an e-mail. Your e-mail address is our link to you. So if your e-mail address changes we no longer have a direct means to communicate with you. It is kind of a two-way street and we need your help to maintain a working database.

3. **TREASURER'S REPORT** (Cont.)

As Dean also indicated, I'll be working on the Nominating Committee. If anyone has an interest or has some questions, please contact us. We hope to have more participation.

CHAIRMAN: Yes, we are always open for your feedback. As Ron noted, the attendance has been gradually declining. We have no particular number goals. We are here to serve our members. If you have any comments on how we could improve what we do and make it more valuable to you, we would be more than happy to address any suggestions.

4. **SECRETARY'S REPORT** – Mike Polagye

Dean and Ron already stole my thunder. I was going to remind everybody that BLRBAC's means of communication is through e-mail and to keep your e-mail current. Dean said that and Ron said that, and I guess now I've said it. That's my message, thank you.

SECRETARIAL SERVICES REPORT -- Barbara Holich

It is recommended that each Regular Member Company (boiler insurers, boiler operators and boiler manufacturers – voting members) have a designated Representative and Alternate Representative, preferably someone who attends BLRBAC at least occasionally.

If you are your organization's designated Representative or Alternate Representative but you have not been receiving e-mail notices from me, then I have no working e-mail address listed for you. Anyone who wishes to be added to the BLRBAC e-mail list, please e-mail me (fhholich@aol.com) your address.

I need someone to take the initiative and advise me of any member company name changes, mergers, etc. so that the BLRBAC database can be properly maintained.

No changes are made to the database until written (e-mails are acceptable) notification is received. I keep a file folder for each member company that includes correspondence naming the Representative and Alternate for each organization. These letters usually contain the e-mail addresses I must have in order to maintain the BLRBAC address book. Therefore, be sure that I have your current working e-mail address. BLRBAC notices of meetings and meeting minutes will only be sent via e-mail. If an e-mail address is not working properly, it will be discarded from the BLRBAC database.

If you are a designated Representative or Alternate Representative for your organization and something happens wherein you will no longer be functioning in this capacity, such as, retirement, occupational change, downsizing, etc., please let me know or supply me with the name and e-mail address of whomever will fill your vacated position within BLRBAC.

5. SUBCOMMITTEE REPORTS

5.1 ESP SUBCOMMITTEE REPORT – John Andrews (See *Appendix A* – Incident List)

The ESP Subcommittee met in closed session on Monday April 5th with 12 of 13 members represented. Two new members, Dean Clay of International Paper and Chris Gore of Weyerhaeuser, were accepted into the Subcommittee. The Subcommittee met in open session on Tuesday morning April 6th with 12 of the 13 members represented and about 190 guests.

The Subcommittee received 46 incident reports from North America and 8 International reports. The 46 incidents were the largest number ever reported at a single meeting. Of the 46 incidents, one was a dissolving tank explosion. Twelve (12) were critical incidents and 32 were non-critical incidents. An ESP was performed in 24 of the incidents including 8 of the critical incidents and 16 of the non-critical. One spout leak was reported.

The basic definitions of Explosions, Critical Incidents and Non-Critical Incidents were re-established by the Executive Committee in September 1999. They are summarized as follows:

Explosions: Only if discernible damage has occurred. This does not include incidents where there is only evidence of puffs or blowback alone. With the new emphasis on damage, more attention will be given to the extent of damage and the amount of downtime for the damage repair (as opposed to total downtime that includes other activities).

Critical Incidents: All cases where water in any amount entered the recovery unit forward of isolating baffles (and therefore would be a similar criterion to the need to perform an ESP). This includes leaks of pressure parts of all sizes. Since small leaks often wash adjacent tubes to failure, this category is important to our learnings. This new definition will result in more entries for the Critical Incident list. (This new category is being re-titled Critical Incidents, rather than Critical Exposures, since we are not restricting the cases only to “exposure” of smelt to water, as in the past.)

Non-Critical Incidents: Those cases that did not admit water to the boiler cavity defined above.

5. SUBCOMMITTEE REPORTS (Cont.)

5.1 ESP SUBCOMMITTEE REPORT (Cont.)

Incident Locations

The general locations of the leaks for boilers in North America are shown in Figure 1, which displays a typical boiler, not representing any particular style or model. The yellow marks are the non-critical incidents and the red were listed as critical incidents. The leaks locations are summarized as follows:

- 17 – Economizer
- 13 – Superheater
- 9 – Wall Tubes
- 4 – Generating Bank
- 1 – Screen Tube
- 1 – Dissolving Tank Explosion with Damage
- 1 – Smelt Spout

Root Cause

The determination of the root cause is somewhat of a subjective determination by the Subcommittee based on information in the reports. The breakdown is listed below:

- 19 – Fatigue
- 2 – Corrosion Fatigue or Stress Assisted Corrosion
- 6 – Weld Failure
- 14 – Corrosion
- 2 – Erosion
- 1 – Improper Material
- 1 – Overheat

How Discovered

Operator observations during boiler walkdowns continue to be the prevalent method of detecting leaks and accounted for identification of 33 of the leaks. Twelve (12) of the leaks were identified by the control room indications. Of the incidents reported, 11 had leak detection systems installed and two mills reported that the leak detection system confirmed the leak. Several of the reports commented that the leaks were so small they were probably below the sensitivity of the detection system. It is important that mill operations be familiar with the capabilities and the shortcomings of any leak detection system installed.

5. SUBCOMMITTEE REPORTS (Cont.)
5.1 ESP SUBCOMMITTEE REPORT (Cont.)

Incident Review

Appendix A contains a summary of the incidents reviewed during the meeting. There were two incidents that were noted to provide a learning experience. Incident 41 involved a partial blockage of a tube by a foreign material and it highlighted the need for proper design and utilization of “downcomer covers” to prevent foreign objects from entering the boiler water circuit during maintenance outages. Also the incident was significant in that the mill spent over 30 hours to locate and remove the foreign object that turned out to be the lid of a can. Incident 42 involved a unit with a “flash-to-sky” rapid drain system. The decision to rapid drain the unit was made after the boiler had been off line for some time and the pressure was about 170 psi. Total level indicator and floor tube thermocouple data showed that the unit drained in to about 10 feet in 82 minutes and to 8 feet in 168 minutes. The mill had added low point drains to the rapid drain flash-to-sky lines in 2003.

Figure 2 shows the critical incidents reported each year. The 12 critical incidents reported this meeting represents half a year and would represent an annual rate of 24 that is above the recent average.

Figure 3 shows that the predominance of explosion history for the recent past has been dissolving tank explosions with four explosions last year and one so far this year. Fortunately, there have been only four smelt-water explosions or other explosions in the last 10 years.

Figure 4 shows the five year running average of smelt water explosions and gives a good indication of the progress that has been made in reducing smelt water explosions with only two incidents reported in the last 5 years.

Figure 5 is a plot of explosion history per 100-boiler operating years. The smelt water explosion experience is continuing to trend down over time, but the total explosions seem to be starting to level out just under 1.2 explosions per 100 boiler years. That includes all causes combined, and is being driven by the recent dissolving tank explosions. We all need to continue the making the efforts to try to get that trending back down. Effort should be focused in developing better procedures to handle heavy smelt runs and plugged spouts.

5. SUBCOMMITTEE REPORTS (Cont.)
5.1 ESP SUBCOMMITTEE REPORT (Cont.)

Eight-Foot Rapid Drain Level

There were several incident reports submitted that included the floor tube thermocouple data. Thermocouple data submitted with several incidents indicated that, within two to twelve hours after the ESP, the floor temperatures started coming back up, indicating that the floor may be dry. Tom Grace has reviewed bed-cooling mechanisms and estimated that the time to properly cool the bed will increase by about 50% if the floor tubes do not contain water.

The Subcommittee is still soliciting data on that to try to further evaluate if there should be a change in that 8 ft. level. The Post ESP Procedures document posted on the Web site at shows the technique to determine the water level in the lower furnace after an ESP. This is a simple system that can only be used after it is safe to reenter the building and there is no pressure on the boiler. Please report any information on floor tube temperatures or actual water level measurements after an ESP on the ESP Questionnaire. Jack Clement will maintain an archive of information submitted on floor water level information following an ESP.

Recommended Change to ESP Document

Clarification of Fuel(s)

The consensus was to expand two articles in the ESP document to make it clear that the fuel(s) to be isolated from the furnace is all encompassing. These changes are:

Chapter 1

Proposed Language:

•Stop All Fuels

Immediately stop firing all fuels and ensure positive isolation of fuels from boiler. Shut off the auxiliary fuel supply at a remote location, manually or automatically.

3.6 All Fuel

The system should prove that all fuels, including black liquor, NCG and other waste fuels have stopped entering the furnace. One method is to obtain positive feedback from valve proof-of-closure or position indicator switches. Liquor firing systems recirculating to a pressurized tank require an automated shutoff valve in the recirculation line.

5. SUBCOMMITTEE REPORTS (Cont.)
5.1 ESP SUBCOMMITTEE REPORT (Cont.)

Clarification of 'Local Test' Switches for valves other than RDV's

The Subcommittee approved the revision of Section 3.13 of the ESP Recommended Procedure

3.13 ESP Valve Local Selector Switch

The actuators on the rapid drain valves and all other valves that operate during an ESP should be wired to move the valves to the ESP position upon initiation of the ESP system regardless of the position of any local selector switch on the valve actuators.

It was noted that this statement is not applicable for dampers.

ESP Reset Timer

The ESP Recommended Practice in Section 3.21 and the Post ESP Procedure in Chapter 4 should incorporate the same statement. The Subcommittee is recommending that the language of Chapter 4 should be adopted, with one change of the final word 'heater' to 'heater(s)', The Subcommittee has adopted the following paragraph for both Sections:

3.21 System Reset

The ESP system should not be reset until reentry to the area is permitted. The ESP system reset logic/procedures may result in automatic movement of controls to undesired positions. Proper caution should be taken to position controls where intended. Examples of valves that may need isolation or manual positioning prior to reset include the feedwater to economizer and the steam-to-steam coil air heater(s).

Floor Thermocouples-Clarification of Language

The Subcommittee approved the proposed wording of Section 3.23 of the ESP Recommended Procedure

3.23 Thermocouples

Recovery boilers should be equipped with floor thermocouples. The thermocouple readings should be monitored and recorded during an ESP as a means to evaluate potential floor tube overheating damage.

5. SUBCOMMITTEE REPORTS (Cont.)
5.1 ESP SUBCOMMITTEE REPORT (Cont.)

The intent is that the floor should be inspected if the thermocouple data, in combination with other information or observations, indicates there could have been damage. Thermocouple data indicating the floor was boiled dry is one indication of possible damage. Most floors do become dry as the result of an ESP and total information needs to be considered.

The preceding four proposed revisions to the ESP document were submitted to the Executive Committee on April 5, 2004. *{Secretary's Note: The Executive Committee approved the document for membership review and comment and a draft mark-up of the ESP document is posted on the Web site. Comments should be sent to John Andrews, chairman of the ESP Subcommittee.}*

Revised ESP Questionnaire

The Subcommittee has been working on a revision of the ESP questionnaire. The form has been simplified so that it will be easier to fill out and is more interactive. You will fill out certain sections depending upon the type of incident and the form contains a table that tells you which sections you need to fill out and which sections you can leave blank. The final revision is posted on the Web site. We would appreciate any comments on it, if you find it simpler or not and any suggestions for further revision.

Whenever you need to fill out an ESP Questionnaire please go into the BLRBAC Web site www.blrbac.org and pull up the latest copy of the form. The form can be filled in electronically and sent in by e-mail to jlclement3315@sbcglobal.net or it can be printed out and filled in by hand and mailed in. Either way is appreciated. Just be sure to fill it out and send it in. **Note that Jack Clement has a new email address.**

5. SUBCOMMITTEE REPORTS (Cont.)
 5.1 ESP SUBCOMMITTEE REPORT (Cont.)

Spring 2004




Figure 1

5. SUBCOMMITTEE REPORTS (Cont.)
5.1 ESP SUBCOMMITTEE REPORT (Cont.)

KRAFT RECOVERY BOILER CRITICAL INCIDENTS

North America Pulp and Paper Industry




Figure 2

(Critical Incident Classification Began in 1995)

5. SUBCOMMITTEE REPORTS (Cont.)
5.1 ESP SUBCOMMITTEE REPORT (Cont.)




Figure 3

5. SUBCOMMITTEE REPORTS (Cont.)
5.1 ESP SUBCOMMITTEE REPORT (Cont.)




Figure 4

5. SUBCOMMITTEE REPORTS (Cont.)
5.1 ESP SUBCOMMITTEE REPORT (Cont.)




Figure 5

5. SUBCOMMITTEE REPORTS (Cont.)

5.2. INSTRUMENTATION SUBCOMMITTEE – Dave Avery

The Instrument Subcommittee met in two open sessions on Monday. Eleven members and eight guests were in attendance at the morning session. Work began with a review of current projects and their status for all members in attendance. The "Functional Testing" draft that is a revision for chapters one and three was submitted last fall to the Executive committee for posting and comments were reviewed. We discovered that the posted version on the web site for member comments was an incomplete unedited version. We have requested it be returned to subcommittee for revision.

The correct draft version was found and reviewed again for content and clarity:

Proposed changes:

“Chapter 1 page 5”

“All subsequent changes to the system should be authorized by at least the department superintendent or their designee and the documentation shall be upgraded. A hazard evaluation should be made prior to any system changes. **Functional testing should be done any time modification work has been performed.**”

“Chapter 3.13 Functional Testing draft”

“Functional testing of safety instrumented systems is intended to provide the recovery boiler owners and operators with confidence that the system will operate as designed. Functional testing should be conducted within the scope and frequency outlined in the following recommended good practices: Emergency Shutdown Procedures, Safe Firing of Auxiliary Fuels, Safe Firing of Black Liquor and Thermal Oxidation of Waste Streams. Functional Logic test plans should be developed for each boiler based on the starting permissive and tripping interlock block diagrams from the recommended good practices referenced above. Functional testing should be done any time a modification or work has been performed on a safety-instrumented system that might reasonably affects its integrity. All testing should be documented and dated with detailed records maintained on file.

Functional testing should verify that the safety systems field devices, wiring, hardware and logic are in sound conditions (i.e. no jumpers, bridges or forces in place, no plugged sensing lines, no broken actuators nor stuck valves or dampers, no damaged instruments nor burnt or corroded wiring, no inadvertent undocumented and/or improper software changes, etc.)

A “complete” trip/interlock test incorporates a signal test from the sensing line (or initiating device for manual trips) through all associated circuitry and logic, and includes actuation of the final elements (valves, pumps, dampers, etc.) being interlocked. It should create or simulate, as safely as possible, the actual conditions being monitored at the sensing lines.

5. SUBCOMMITTEE REPORTS (Cont.)

5.2 INSTRUMENTATION SUBCOMMITTEE (Cont.)

Note: Provided that a complete test through a common output (e.g. MFT) is performed, a test of the remaining individual trip conditions, to just that common output, is acceptable.

While boiler start up, following a shutdown, provides the most feasible time for these tests, it is perfectly acceptable to conduct such tests throughout the year, when possible. This would be applicable for auxiliary fuel and waste stream systems and possibly others depending on operating arrangements of the unit. Any unscheduled trips occurring during boiler start-up or operation may be applied toward meeting the intent of testing for that particular trip or permissive, provided the event is properly documented and the first out system is provided verifies the source of the trip.”

The editing review revealed that two new definitions were needed for inclusion in Chapter 2 Terms and Definitions of the "Instrumentation Checklist and Classification Guide". The definitions for 'Modification' and 'Functional Test' were deferred until the afternoon session.

The afternoon session had eleven members and three guests present. Work was completed for the two definitions:

Modification - "A change or alteration that results in a deviation from the original design specifications or criteria.”

Functional Test - “A method of proving all elements of a system operate as designed.”

A package containing the Chapters one and three addendums along with the new definitions has been submitted to the Executive Committee for review and posting for membership comments. Our goal is to have these changes ready for voting at the fall meeting. *{Secretary’s note: The Executive Committee has approved the proposed changes for membership review and comment and a mark-up of the existing document showing these changes is posted on the BLRBAC Web site.}*

Additional work included a request for the “Safe Firing of Black Liquor Committee” to review their definition for ‘Interlock’:

(Interlock: A device that senses a limit or off-limit condition or an improper sequence of events. It causes shutdown of the offending or related piece of equipment, or it prevents proceeding in an improper sequence, to prevent a hazardous condition. Direct signals rather than transmitted signals shall be used wherever possible to actuate interlocks.)

We are proposing to remove the last sentence (“Direct signals rather than transmitted signals shall be used wherever possible to actuate interlocks”) in that definition.

The sentence deletion would allow current reliable technology to be applied while maintaining original intent of the definition. Note: This does not reduce the number of devices required, i.e. if conditions now require a measurement and a separate interlock device then two devices are still required.

5. SUBCOMMITTEE REPORTS (Cont.)

5.2 INSTRUMENTATION SUBCOMMITTEE (Cont.)

Next fall our morning meeting will be closed to review desktop refractometers as a possible device for Off-Line Field Measurement Technique for routine checking of the continuous in-line refractometers. This is a request from the “Safe Firing of Black Liquor” Subcommittee. The subject will be reviewed with a written assessment returned to “Safe Firing of Black Liquor”. The afternoon session will be open to the membership.

5.3 MATERIALS & WELDING SUBCOMMITTEE – Dan Phillips (new)

The Welding and Materials Subcommittee met in two separate sessions Monday. The morning session was a closed working session with approximately 14 members present (5 Recovery Owners, 3 Insurance Reps., and 6 Contractors/Vendors.) The afternoon meeting was an open session, with 10 additional guests. Total attendance was 24.

Meetings were opened with once-around-the-table introductions. Members reviewed which task groups they had been on, if any, and their areas of specialty and interest.

The morning session proceeded into review the current subcommittee status. With the passing of Joan Barna since the last meeting, the draft document and procedures and assignments were reviewed. An outline summary of the subcommittee morning session includes:

- Jim Dixon of Weyerhaeuser was asked to serve as Vice Chair of this committee, he accepted. Dan Phillips will serve as Chair.
- Reviewed assignments, task group participants, and contributors of guidelines to date.
- Fabian Henriques of Mead and Michael Welch of WSI will remain as editors and comment gatherers. Technical review will include Max Moskal, Jim Young, and Dennis Hollenbach. Bob Sullivan, Dave Lang, and Mike Garfield will head code review.
- Collectively, the group wrote a General Forward for the Document. This will be reviewed and finalized by Jesse Worsham, Mike Welch, Dave Fuhrmann, and Dennis Hollenbach. This is to be sent to Fabian for review, editing, and subcommittee distribution.
- Established a task group for generating a “Forward” to the Welding portion of the document covering some of the common issues for many of the welding procedures guidelines. Dave Fuhrmann & Dave Lange will head up this with the help of Mike Welch, Fabian Henriques, Robert Sullivan, Jessie Worsham, and Max Moskal. This is to be sent to Fabian for review, editing, and subcommittee distribution.
- Consolidation and formatting of Section 10 “Welded Handhole Caps” by Dan Phillips and Jim Dixon, with Jim Young and Mike Garfield doing technical review. This will be the first guideline procedure submittal to the full Subcommittee at the next meeting.

5. SUBCOMMITTEE REPORTS (Cont.)

5.3 MATERIALS & WELDING SUBCOMMITTEE (Cont.)

Current status of the Draft Document:

The current 31-page draft document contains an index with 10 procedure guidelines. These have not received final approval by the subcommittee. It was agreed by the subcommittee not to submit this for Executive Committee review and approval at this time.

The goal for submittal to the Executive Committee for the upcoming October session includes:

1. Forward to Welding and Materials Document
2. General Welding Guidelines forward
3. Welded Handhole Caps Guidelines & Procedure(s).

Additional comments & general suggestions:

There were many guest and committee requests for a topic session or presentation “show and tell.” Many suggested the topic period be approximately 15 minutes. This could be followed with discussion on specific welding or materials considerations. Several members also had interesting projects they would be able to summarize on rebuilds, specific repair welding, etc... This will be considered as a part of the agenda at each meeting, provided support efforts allow.

Max Moskal expressed interest in the Document Guidelines including an article on root cause analysis of failures.

Mike Welch expressed interest in continued surveys of the general membership on a regular basis with topics to be suggested.

Sage of America provided initial information on stud welding products and technical data they provide. Studded tube repairs are of obvious interest and will be included at some point as a guideline procedures section.

Robert Sullivan shared that the National Board has recently submitted a revised Section RB 5602, Black Liquor Recovery Boilers for inclusion in the next revision of the National Board Inspection (NBIC). Dave Parish has had a hand in this. The National Board is reaching out to the industries to identify unique industrial needs for Code Repair guidelines. They are trying to parallel those specific needs and solutions within the framework of the NBIC. He encourages this effort and offered continued support.

Karl Morency of Georgia Pacific attended a portion of the morning session. He offered input on the approach to writing this document and added that many times prior to making the repair, the initial consideration needs to be to decide whether to save the failed piece for analysis or repair weld it and save no sample. He also recommended that a list of references to related publications, i.e. TAPPI, AF&PA, EPRI, etc, be included at the end of the document. Both items will be considered.

5. SUBCOMMITTEE REPORTS (Cont.)

5.3 MATERIALS & WELDING SUBCOMMITTEE (Cont.)

Timetable for Submittals:

Introduction Forward – final draft	July 30, 2004
Forward to Welding “Welding General Guidelines”	August 30, 2004
Handhole Cap Consolidation	July 30, 2004
Review – comment – approval	September 15, 2004

Next Meeting:

For the next meeting, the aforementioned submittals will be made to the Executive Committee and the procedure guideline and format for a repair sections will be on the agenda. A welding related topic will be presented at the start of the open meeting, followed by general comments on the next procedure guideline draft.

It was agreed that the next several meeting will have a closed morning working session, and an open session in the afternoon, with a special topic related to one of the guideline procedures.

5.4 PERSONNEL SAFETY – Robert Zawistowski

The Personnel Safety Subcommittee met in an "open" session on Monday, April 5, 2004. There were nine members and 16 guests in attendance during the meeting.

Representation at our meeting by regular members and guests included original equipment manufacturers ALSTOM Power, Babcock & Wilcox, Diamond Power, and Kvaerner Power. Representation from insurance and insurance service companies included AXA Corporate Solutions, FM Global, and GE-GAP Services. Operating company representation included, Boise Paper, Georgia Pacific, Kimberly-Clark Nova Scotia, MeadWestvaco, Packaging Corporation of America, Rayonier, Smurfit-Stone, Teck Cominco, and Weyerhaeuser. Water treatment company representation included Buckman Laboratories International. Consultant representation included Brazilian Recovery Boiler Safety Committee and Power Specialists Associates, Inc.

We had one member change since the last meeting. Daryl Hoffman of FM Global is now serving on our subcommittee replacing Jimmy Onstead of FM Global who is now on the Executive Committee.

We had one request for information clarification since the last meeting. This inquiry was reviewed along with our responses.

5. SUBCOMMITTEE REPORTS (Cont.)

5.4 PERSONNEL SAFETY (Cont.)

The Personal Safety document was posted on the web site this past winter for membership review. Only a few comments were received between the time of the posting and spring meeting. These comments were reviewed and a final edit of the document was completed during our morning meeting. As the changes were minor, a final edited copy was submitted to the Executive Committee for review on Monday afternoon. The edits were accepted by the Executive Committee. The members took a vote Wednesday morning and the updated document was approved. It will be posted on the web shortly.

The Personal Safety document was posted on the web site this past winter for membership review. Only a few comments were received between the time of the posting and spring meeting. These comments were reviewed and a final edit of the document was completed during our morning meeting. As the changes were minor, a final edited copy was submitted to the Executive Committee for review on Monday afternoon. The edit was completed and accepted by the Executive Committee.

One committee member briefly discussed a boiler explosion that occurred recently. The boiler explosion was a recovery boiler that had been converted to a power boiler. The explosion was natural gas related. The root cause of the explosion is under investigation and very little information was available at this time. More information should be available by the fall meeting and this topic will be discussed in greater detail at that time.

In the Executive Committee meeting Monday afternoon we learned of an incident where a man was seriously burned by hot black liquor when disconnecting a hose from a ring header. Only one valve was closed and pressure had not been bled off the line. There was an incomplete transfer of information to the treatment facility (hospital), which resulted in improper treatment for a chemical burn. The resulting injury was more serious than if it had been treated differently at the hospital by neutralizing the chemical. This incident will be discussed in greater detail during the fall subcommittee meeting.

We received information that BLRBAC guidelines do not comment on normal water wash guidelines during the October 2003 meeting. The committee agreed that this was an important function that can have a direct impact on personnel safety at that time. As we were finalizing the updated draft of the Personnel Safety document during the spring 2004 session, I tabled this item until the Fall 2004 meeting.

During our meeting we discussed that it takes a significant amount of time for a bed to cool before molten smelt has solidified and there are many variables that affect the cooling process. There was discussion that there should be consideration given to clearing the building of personnel before water is first introduced into the furnace. This will be discussed further in our subcommittee meeting during the fall.

5. SUBCOMMITTEE REPORTS (Cont.)

5.4 PERSONNEL SAFETY (Cont.)

We have noted that there are a growing percentage of non-users on our subcommittee. Personnel Safety receives some of its best input from operating people in the development of our guidelines. We would like to encourage more users of recovery boilers to become involved in this and other subcommittees.

CHAIRMAN: As he noted, the subcommittee has rewritten the document and it has been posted on the WEB site. They made a few minor wording changes to it. The Executive Committee reviewed the changes and did not feel those were substantial. So what we would like to do is to put that document to a vote, but first does anyone have any comments on the document as posted? Could I have a motion to put the document to a vote by the members? Second? Okay. Thank you. All the members in favor of approving the Revised Personnel Safety Guidelines please raise your hand. Okay. Those opposed? The Motion is approved. We will post the new document on the WEB site for your use. *{Secretary's note: The new document has been posted.}*

Next we will have a report from Craig Cooke on Press Release & Publicity Subcommittee. He is the sole member of that committee.

5.5 PRESS RELEASE & PUBLICITY SUBCOMMITTEE REPORT – Craig Cooke

Yes, my committee met late into the night last evening. I'm responsible for providing news releases to ten trade magazines and newsletters. The most important issue is getting them to publicize future meeting dates. Most recently I was successful in getting BLRBAC on the TAPPI Calendar of Events. On the TAPPI WEB site there is a nice summary of BLRBAC as an organization, the latest meeting and information on how to register.

5.6 SAFE FIRING OF AUXILIARY FUEL REPORT – Dave Streit

The Auxiliary Fuel Subcommittee met in open session on Monday afternoon in the Valentino room. There were three members/alternates and six guests present at the meeting.

There was no meeting conducted during Fall 2003, therefore no agenda items carried over from the previous meeting.

One agenda item was listed for this meeting. This related to when the electrostatic precipitator should be energized when starting-up a cold recovery boiler using oil burners.

There was significant discussion regarding the subject from all present. Two of the guests present represented environmental equipment suppliers and had a number of comments regarding the risks involved in energizing the precipitators during cold start-up based on their unique knowledge and experience of precipitators.

5. SUBCOMMITTEE REPORTS (Cont.)

5.6 SAFE FIRING OF AUXILIARY FUEL REPORT (Cont.)

It is believed there is little risk of an explosion due to energizing the precipitator, as the amount of excess air from the 30% MCR minimum air flow requirement and the low firing rate during start-up would result in a very lean fuel concentration, even with relatively poor combustion, and would be below the lower explosive limit (LEL).

There is the possibility for high LOI/carbon ash being collected on the plates that could be a fire hazard, but most thought the risk to be low.

The manufacturers do not recommend the units to be energized during start-up, but recognize most do energize their units. It was stated that at one location, energizing the recovery boiler precipitator is an environmental permit requirement prior to firing the unit, and is included in the start-up permissives.

The performance of the precipitators will be negatively affected if a coat of soot residue is collected on the plates. This may result in higher than normal opacity when firing liquor. The plate area will clean itself over time, but this may require up to a week. It was suggested that during start-up only a limited number of fields be energized to limit this potential.

From a safety perspective, it was suggested that the power control to the fields be placed in manual vs. automatic, and the power level be limited to reduce the risk/amount of sparking. This would reduce the potential for a fire.

It was stated that there are many electrostatic precipitators successfully in use on oil fired utility boilers. These units are much larger the recovery boiler units for the same firing rate, and are not risk free. There are occasional issues, but issues are not the norm.

It was stated there is no loss history for recovery boiler precipitators due to fire or explosion caused by oil firing.

It was the opinion of the members and guest present that the risk of fire and/or explosion due to energizing precipitators during cold start-up of recovery boilers is not significant risk and does not need to be addressed in the auxiliary fuel document. Each plant should evaluate its own risk relative to environmental requirements and decide how to operate their unit.

5.7 SAFE FIRING OF BLACK LIQUOR REPORT – Len Erickson

On Monday, April 5th, a closed morning meeting was held with eight of eleven members present. An additional 35 guests attended the open afternoon meeting. The following items were discussed and acted on during the sessions:

5. SUBCOMMITTEE REPORTS (Cont.)

5.7 SAFE FIRING OF BLACK LIQUOR REPORT (Cont.)

- a) The Fall 2003 minutes were reviewed and approved.
- b) A proposed change to Chapter 6 that would allow the use of a bench top refractometer for field solids determination was reviewed. The Safe Firing Subcommittee is concerned that “similar physical principles” would be used to verify an online measurement. The proposed language was reviewed and is being forwarded to the Instrumentation Subcommittee for further evaluation and comment.
 - Note: this change would allow the use of a bench top refractometer as an acceptable method in addition to a solids cook and microwave test.
- c) Logic had been proposed to add the black liquor pumps and steam sources as items that also trip in addition to closing the black liquor header valve and opening the divert valve in SFBL Figure 4 “Black Liquor Tripping Logic”. The subcommittee reviewed the proposed logic change and decided to include it in the revision being worked on for a lower furnace wash switch rather than submitting as a separate item for membership vote.
 - Note, the revised Figure 4 had been previously approved by the subcommittee and submitted to the Executive Committee. It was out for membership review. No comments had been received from the membership.
- d) The Revision to SFBL providing for the use of a keyed interlock switch for water washing the lower furnace has been combined with a review of the SFBL starting & tripping logic diagrams, (Figures 2 & 4). A new figure 2A will be added. Figure 2A will be titled “Black Liquor header Wash and Lower Furnace Wash Permissives”. Figure 2A includes both the ring header wash and the lower furnace wash logic.

The proposed revision will also include:

- A revision to Fig 2 showing the opening of the black liquor header valve and closing of the divert valve to be an operator initiated action. This is stated in the document, however it has not been shown as such in the logic.
- A requirement for an automatic closing valve in the recirculation line to “*pressurized storage tanks*”. This is to prevent systems with pressurized storage tanks from back feeding the ring header in the case of a divert.
- The inclusion of a requirement for a dissolving tank level and smelt spout cooling water flow permissive.
- The addition of a definition of the lower furnace wash switch

5. SUBCOMMITTEE REPORTS (Cont.)

5.7 SAFE FIRING OF BLACK LIQUOR REPORT (Cont.)

d) Cont.

- The removal of a sentence from chapter two, “*Direct signals rather than transmitted signals shall be used wherever possible to actuate interlocks*”. This is at the request of the Instrumentation Subcommittee to make the documents consistent.

(Secretary’s Note: A mark-up of the March 2004 version of the document showing the above proposed changes has been reviewed by the Executive Committee and has been approved for membership review and comment. It is posted on the BLRBAC Web site.)

- e) Since the Fall 2003 meeting, the SFBL Subcommittee was advised that several errors had been found in the on-line version of SFBL. The document revisions were checked, corrected, proofed & has been reposted on the BLRBAC web page. The Document on the web page that has a date of “March 2004” is the correct current version. Previous versions are incorrect & should be discarded.
- f) No requests for clarifications were received since the Fall 2003 meetings.
- g) The subcommittee received a report of an operator injury that resulted from a failed Ball-valve stem. (Twisted). The membership is encouraged to review their SOP’s to ensure the ring header isolation valve and the liquor gun valves are closed and the drain valve and pressure gauge valves are open. The intent of this design is to ensure all pressure is relieved from the liquor gun assembly.
- h) The subcommittee is looking for an E&I person to add to the subcommittee membership. Please contact Len Erickson or Mark Sargent.
- i) In light of the increase in dissolving tank explosions being reported, operating locations are encouraged to review Chapters 9 & 10 of Safe Firing of Black Liquor. These sections were recently updated. Had the recommendations in Chapters 9 & 10 been followed, some of the dissolving tank incidents may have been prevented.

Contact:

Len Erickson at 208-384-4933, e-mail lenerickson@boisepaper.com, or Fax 208-384-7637, with questions or comments, or

Mark Sargent at 513-248-6086, e-mail mark.sargent@ipaper.com, or fax 513-248-6679 with questions or comments.

5. SUBCOMMITTEE REPORTS (Cont.)

CHAIRMAN: As Len noted, they are reviewing and will be proposing again some changes to the safety logic and I know most of you, hopefully all of you, have safety systems set up based on BLRBAC logic. Just be aware that we are making some proposed changes that will hopefully cause you to change your logic. We encourage you to look at those. If you feel we shouldn't be doing this, now would be the time to get your thoughts to Len and his subcommittee. One of the changes being posted includes tripping the black liquor firing pumps as part of a black liquor trip. I got some verbal feedback on why would we want to do that. Again, the Subcommittee had been reviewing this and they believe there are safety reasons to consider this. If you have input otherwise, I encourage you to provide it to Len and the subcommittee.

5.8 FIRE PROTECTION IN DIRECT CONTACT EVAPORATORS REPORT – Chris Jackson

The Subcommittee held an open session Monday morning with three members and ten guests present.

Currently there are eight active members of the subcommittee. This spring we welcomed a new member, Nick Merriman, of SAPPI's Tugela mill in South Africa. He is one of only four who represent the owners and users. It is a concern of the subcommittee that we do not have more representation by the owners and users of the equipment we are writing guidelines for.

If you own and operate Cyclone or Cascade Evaporators, we would ask that you consider participating as a member of our committee. I have had people come up and say, I won't be attending regularly, but someone from our mill will be. I would suggest that you consider designating a permanent member, and an alternate. The member's designee will be more than welcome to sit and deliberate with the subcommittee.

Last October we proposed a change to the guideline that allows more latitude in the design of steam suppression systems. That change has been posted on the web for comments and is now ready for vote by the membership. We will get to that right after this report.

Since October, we have received reports of two fires, both in Cascade Evaporators. Craig Cooke and I will each present one of these reports to you. Even if you do not have any responsibility for a Direct Contact Evaporator, I hope you will still find these incidents interesting.

2004-APRIL-DCE Incident 01

On December 4th, 2003 International Paper's Roanoke Rapids mill was preparing to restart the No. 6 Recovery boiler after an outage. This boiler has two Cascade Evaporators with liquor flow in series and flue gas flow in parallel. They had been washed during the outage.

The length and scope of the outage was not reported. The boiler was lit-off on No. 6 oil at 11 PM on the 4th. Sometime thereafter, a paper machine line shaft broke and the decision was made at 1 PM on December 5th to shut down the boiler.

5. SUBCOMMITTEE REPORTS (Cont.)

5.8 FIRE PROTECTION IN DIRECT CONTACT EVAPORATORS REPORT (Cont.)

The boiler was re-lit on oil at 4:40 PM on December 6th, and ran for four hours and twenty minutes before a High Temperature trip. The trip took down the boiler and activated the automatic steam suppression system. The operators manually closed the dampers at the inlet and the outlet of the precipitator. They also flooded the Cascades with water and the precipitators with dilute black liquor. Fire damage was confined to the upper part of the Cascades and the inlet to the precipitator.

It was reported that no liquor had been put into the Cascades since the time that they had been washed during the outage. They only lost 17 hours and 40 minutes due to the need to replace expansion joint material. No other damage was reported.

The response of the automated suppression system and perhaps the low volume of combustibles kept the damage to a minimum.

2004-APRIL-DCE Incident 02

The No. 2 Recovery Boiler at Stora Enso's Wisconsin Rapids Pulp Mill was built in 1976 with a single Cascade Evaporator equipped with an automatic steam suppression system. The ID fan is located between the Cascade and the Precipitator.

On June 22nd, 2002 the mill was going into an outage. The No. 2 Recovery Boiler was under load burning black liquor when a power outage tripped off the entire mill. All instrumentation and control of the recovery unit was lost as there was no electricity or steam. All fuels tripped and the Cascade wheel stopped turning. Thirty minutes later someone noticed black smoke coming from the recovery boiler stack and alerted the control room.

Immediately the operators covered the FD fan inlets and closed the precipitator dampers. Mill personnel used small hose streams to fight the fire and received backup from the local Fire Department. A hole was opened in the side of the Cascade near where the fire was presumed to be most intense. It required one and a half hours to extinguish the fire.

A hot smelt bed and a natural draft dried out the Cascade wheel and unwashed casing. The fire appeared to have originated at the outlet of the cascade, adjacent to the right wall above the rear shelf. The fire intensified and appeared to spread up the duct, igniting liquor deposits on the duct walls and at the ID fan. Liquor deposits downstream of the ID fan were reported to be minimal, but indications were that severe overheat was experienced between the ID fan discharge and the precipitator inlet dampers.

The power outage hamstrung the steam suppressions system. Without any source of steam, manual fire fighting was the only option.

5. SUBCOMMITTEE REPORTS (Cont.)

5.8 FIRE PROTECTION IN DIRECT CONTACT EVAPORATORS REPORT (Cont.)

The need for reliable suppression media or back up water supplies that are expected to be available under all plant conditions was reinforced by these incidents. These incidents were reviewed by the subcommittee and it was determined that the current document addressed the root causes of both these fires.

INCIDENT QUESTIONNAIRE

At the last meeting Craig Cooke was asked to lead a Task Group to redesign the incident reporting form. Presently, this form is the last nine pages of the guideline and is not a separate document. The goal is to make information about incidents as easy as possible to report to the membership. This includes:

- Shortening the form.
- Making it a discrete document that will be posted in the same way the ESP Incident form is posted on the BLRBAC Web site.
- Making it more intuitive to complete.

Craig brought a three-page version of the new questionnaire to the subcommittee that was reviewed and additional changes were discussed. This document will be sent to the subcommittee members not present during this meeting and it is expected that we will submit it to the Executive Committee in October for review and consideration. *{Secretary's note: The incident questionnaire will not need Executive Committee review and can be posted when ready by mailing to the Secretary.}*

That constitutes the work done by the subcommittee this meeting. With a new document, and reports of incidents starting to come in, the subcommittee expects to have its hands full in the months ahead. Just today I heard an anecdotal report about a Cyclone fire. I look forward to documenting that incident and discussing it at the next meeting. We encourage owners and users of Direct Contact Evaporators to let us know of any other incidents involving their DCE fire protection systems and to send us their questions and concerns. Thank you for your attention. Before we vote on the proposed change, are there any questions?

5. SUBCOMMITTEE REPORTS (Cont.)

5.8 FIRE PROTECTION IN DIRECT CONTACT EVAPORATORS REPORT (Cont.)

PROPOSED CHANGE

The subcommittee reviewed and discussed the installation of steam nozzles as part of an automatic steam suppression system, and decided upon the following revision to the Fire Protection for DCE document:

Proposed Wording Change to Section 4.2.2 Steam, Fourth Bullet:

Delete **“Provide one nozzle for every 10-ft. length of enclosure or duct.”**

Insert **“Steam nozzles should be sized and positioned in order to assure proper distribution of steam throughout the volume to be protected.”**

This change was reviewed by the Executive Committee, and posted for review last October. No comments were sent to the Subcommittee Chair, and the change is offered to the membership for vote.

CHAIRMAN: Chris, can you briefly review again what we are going to be voting on.

CHRIS: Yes. Our document was taken by SAPPI Fine Paper as a guide to revamp their own steam suppression system at a mill and they came across this requirement to provide one nozzle of steam dispersion for every ten feet length of duct and because of the long ductwork they had, this was going to put a real burden on them. They came back to the Subcommittee and asked us if this was truly a value added effort. After review, we decided that this was too restrictive. So currently the words say in Section 4.2.2, “Provide one nozzle for every 10-ft. length of enclosure or duct.” We propose that we remove that and insert instead, “Steam nozzles should be sized and positioned in order to assure proper distribution of steam throughout the volume to be protected.”

CHAIRMAN: Thank you. Could I have a motion to vote on the changed wording? Thank you. Second? All those in favor please raise your hand. Opposed? Thank you. The change has been approved.

{Secretary’s note: The revised document is posted on the BLRBAC Web site with an April 2004 revision date.}

5. SUBCOMMITTEE REPORTS (Cont.)

5.9 WASTE STREAMS REPORT – John Lewis -- Co-Chairman for John Rickard

The Waste Streams Subcommittee met in closed session Monday morning, April 5, with 12 members present and in open session Monday afternoon with 12 members and 11 guests present. One new member joined our subcommittee on Monday—Jerry Pate of Smurfit-Stone.

In our closed meeting on Monday morning we worked on finalizing Chapter 6 of our “Recommended Good Practice for the Thermal Oxidation of Waste Streams in a Black Liquor Recovery Boilers.” Chapter 6 addresses liquid waste streams blended into black liquor. The subcommittee gave its final input to the document including adding logic diagrams for the blending of methanol, soap, tall oil and spent acid with black liquor after the point of final concentration. Chapter 6 will be submitted to the executive committee within the next couple of weeks and with their approval will be submitted to the BLRBAC membership for comments. *{Secretary’s note: The Executive Committee did not approve this proposal for review and comment by the membership. Executive Committee comments will be forwarded to the subcommittee for their consideration.}*

In our open meeting on Monday afternoon we began work on Chapter 7, which will address thermal oxidation of liquid waste streams in dedicated burners in recovery boilers. Two of our members, Olli Kujanpaa and Bentley Sherlock, had done some preliminary work for this chapter and this was reviewed. A table of contents for the chapter was developed, and several members will be working on the different sections in the coming months. They will submit their sections to our subcommittee chairman John Rickard by August 15, and he will compile the sections to be reviewed at the October meeting. The meeting on Monday afternoon had almost as many guests as members present, and the input of our guests was very helpful and appreciated.

6. AMERICAN FOREST & PAPER ASSOCIATION REPORT – Tom Grant

The AF&PA Recovery Boiler Program is continuing in its efforts to produce greater awareness of safe practices and improvement in the operation, maintenance, safety and efficiency of recovery boilers.

Membership

Currently, we have 28 companies in the Program including three non-AF&PA member companies. We are continuing to contact and encourage those other companies with recovery boilers, who are not in the Program, to join with the current members in the cooperative efforts for safe operation and research to improve the reliability of the recovery boilers. All companies operating recovery boilers gain directly from the benefits of the Program.

6. AMERICAN FOREST & PAPER ASSOCIATION REPORT (Cont.)

Operational Safety Seminars

In 2002 we had the lowest attendance at the Operational Safety Seminars. In 2003 we almost reached a record high of 148 operators for the three seminars held. Was that due to the two explosions that occurred in 2002? The Risk Management presenter at the Annual Conference pointed out the need for the continued attention to training and cited the seminars as a very good tool. In 2004 we had 44 people at the March 23 - 24th seminar in Atlanta. We had 44 people at the Portland OR seminar March 29 - 30th. We have one seminar remaining for the year, that is May 25 - 26th here in Atlanta. As of today, 55 registrations have been received which leaves us with about 11 spots open.

Explosion Monitor

Mr. Jack Clement continues in his role as the AF&PA explosion monitor. He is also working with the BLRBAC ESP Subcommittee on collecting, reporting and tracking recovery boiler incidents.

Training Program

The Organization and Training Subcommittee is reviewing the uses of the AF&PA Recovery Boiler Training Program. At its February meeting, proposals were reviewed from two vendors to consider converting the AF&PA Training Program to use for computer-based training (CBT). The Subcommittee will decide whether to go forward on this.

Recovery Boiler Char Bed Cooling following an ESP

The final report on the **Recovery Boiler Char Bed Cooling following an ESP** project was completed and copies were distributed to Program members.

Damage Mechanism

The “**Damage Mechanism**” project sponsored by the R&D Subcommittee through the Pressure Vessel Research Council (PVRC) of the Welding Research Council (WRC) to create a document on damage mechanisms for fitness-for-service has been finalized. This document defines and describes various damage mechanisms for API-579. We have been informed that copies of the report will soon be published and distributed to the Program members. (We have been waiting for this completion date for a while.)

Overheat Floor Tube Failures

The R&D Subcommittee is evaluating the need for further research into the **Overheat Floor Tube Failures in Chemical Recovery Boilers**. You may recall that the study to investigate the experiences into the failures was completed earlier this year. Work had been done in this area by various sources, but had not been published. The Subcommittee has been encouraging the publication of those studies to further the project.

6. AMERICAN FOREST & PAPER ASSOCIATION REPORT (Cont.)

Non-Destructive Technologies for Detecting Waterside Deposits

Phase I of the study to identify potential **non-destructive technologies for detecting waterside deposits in recovery boiler furnace wall tubes**, sponsored by the R&D Subcommittee, was completed and distributed to the Program members. Mr. Evans of International Paper and Mr. Clark of BWXT presented this report at the Annual Conference. The Subcommittee is reviewing the recommendations to investigate 9 technologies in Phase II of the study and will work with EPRI and/or a consortium to move forward. Plans are to possibly have a vendor in the project to take it to commercialization. The AF&PA Advisory Group of members, vendors and manufacturers will oversee this project.

Chemical Cleaning

The survey conducted by AF&PA of the members concerning decisions as to the timing of chemical cleaning was discussed in the study of the “Non-Destructive Technologies for Detecting Water-Side Deposits in Recovery Boiler Furnace Wall Tubes.” This information will be reviewed further.

Joint Seminar with AF&PA and BLRBAC Planned

We are in the planning stages for a joint seminar for AF&PA and BLRBAC for water treatment. It is scheduled following the Spring 2004 meeting of BLRBAC. Mr. Conley of Bowater is heading up the Task Group for the seminar. Details will be distributed when we have more information.

Agenda 2020

AF&PA is continuing to work with the US Department of Energy in the Agenda 2020 program to develop projects with a vision for the future. There are a number of projects currently underway with funding from DOE including gasification.

Study for Review Analysis of Economizer Tube Failures

With the increased number of economizer tuber leaks reported, AF&PA decided to sponsor a study of these. The R&D Subcommittee is reviewing a proposal from Jack Clement and Tom Grace to study this situation. The BLRBAC reports of these failures may not be complete enough to indicate the reasons for the economizer leaks. They will try to best qualify the major causes of these leaks, i.e., design, expansion, etc. The investigators are requested to point out ways to locate the root causes of the leaks. The investigators may need to visit some mills and manufacturers to obtain detail information. We ask for cooperation from our members to help them in the study. We anticipate that the study will be underway shortly and will take about a year to complete. All funding for this study will be from AF&PA.

7. AMERICAN FOREST & PAPER ASSOCIATION REPORT (Cont.)

Other Research Projects Under Review

The Committee is also reviewing a proposal to study “High Temperature Protective Coatings to Simplify Inspection of Wall Tubes in Chemical Recovery Boilers.” The Committee is looking at various sources to avoid overlap and/or possible additional funding.

The Committee is also considering the possible study on smelt spouts and testing of ribbed tubes. We hope to have further information on these studies later this year.

Annual Meetings and Conference

AF&PA’s annual Recovery Boiler meetings and Conference was held February 3rd and 4th in Atlanta. The Conference is open to all operating companies, insurers and manufacturers. Presentations included reports on the projects currently sponsored by the AF&PA Recovery Boiler Program and subcommittee reports on their accomplishments. The object of the Conference is to keep not only the members advised, but also the remainder of the recovery boiler community, as well. We had good attendance and we hope that many of you will plan to attend next year’s Conference.

CHAIRMAN: As Tom noted, almost all of us from the operating companies, are supporting the AF&PA effort on recovery boilers, so we are spending your money. It is funded by a system of dues based on production. If your company is a supporting member, all the information Tom has referred to, the reports published, etc. is going to someone in your company. So, if you can’t find it and you think you need it, see Tom. He can tell you who in your company might actually be receiving the material. If you wish to participate on any of our subcommittees in AF&PA, you are certainly welcome to attend and participate.

7. TAPPI RECOVERY BOILER SUBCOMMITTEE REPORT – Karl Morency

No report given.

8. NATIONAL BOARD OF BOILER & PRESSURE VESSEL INSPECTORS' REPORT – Bob Sullivan

As with most organizations, the National Board has been quite busy in the past few months. A driving force is communications with all whom we serve and, to reach as many with as much information as possible. This, of course, reeks of the Internet. Hopefully, you have been served by our attempt to increase information availability. I’m told the National Board is in the top 10% of the most visited web site worldwide. We thank you.

I had mentioned last October that we were developing another web-based training course. An informational course on “Controls and Safety Devices for Automatically Fire Boilers” (CSD-1) has been completed and is now available on our web site. CSD-1 is an ASME standard for boiler input of less than 12,500,000 Btu/hr. Registration can be made on-line by opening the National Board web site, clicking on “Register for CSD-1” in the gold block to the right and completing the requested information. By the way, we have a big sale on this course until the end of May!

8. NATIONAL BOARD OF BOILER & PRESSURE VESSEL INSPECTORS' REPORT (Cont.)

A new edition of the “Rules and Recommendations for the Design and Construction of Boiler Blowoff Systems” will be published by July 2004. The new edition will provide the blowoff system designer more detailed information, such as expanded tables for various pipe size flows and formulas. This should prove to be clearer and easier to use. The work is being reviewed and final touches made. I expect the title will be simplified.

The next meeting is scheduled for August 17-19, 2004 in Milwaukee, Wisconsin, at the Wyndham Milwaukee Center. Subcommittee meetings will be held the 17th and 18th followed by the NBIC Committee on August 19th. Details of the meeting location and hotel will be on the National Board web site.

NBIC Committee Action

The following items, which I feel are of the most interest to BLRBAC members, were approved by the NBIC Committee at their January 15, 2004 meeting. All changes will be published on the National Board web site by May 1, 2004 for comments. The final approved addendum will be published in December 2004.

- As mentioned in October 2003, the inspection section of NBIC included a proposal to rewrite the paragraph on Recovery Boilers. RB-5062 has been revised. It addresses inspection of Black Liquor Recovery Boilers. References to inspection procedures of American Forest & Paper Association Reference Manual, BLRBAC Recommended Practices, and TAPPI Guidelines have been added. The NBIC Committee thanks those who submitted comments.
- Revision of RB-1030 – Stamping - Provides a reasonable method for authorization to restamp or replace damaged or illegible information on the Code stamped nameplate. This separates the data contained in the stamping from the Code symbol stamp. I have copies of these changes.

8. NATIONAL BOARD OF BOILER & PRESSURE VESSEL INSPECTORS' REPORT (Cont.)

Interpretations

The following interpretations are those I felt have the most interest to BLRBAC members. All interpretations have been published or are listed on the National Board web site under "NBIC".

Interpretation 01-30

Subject:

RC-1050(c)

Fabrication and Installation by "R" Stamp Holder

2001 Edition with 2002 Addendum

Question 1:

When ASME is the original code of construction, does RC-1050(c) permit an owner holding an "R" Stamp to fabricate replacement parts and have the parts installed in the owner's boiler by another "R" Stamp holder?

Reply 1:

No. RC-1050(c) requires these replacement parts to be fabricated by an ASME Certificate Holder.

Question 2:

When ASME is the original code of construction, does RC-1050(c) permit an owner holding an "R" stamp to fabricate replacements parts and document those parts by stamping with the owner's "R" symbol, a unique serial number, and complete a Form R-3?

Reply 2:

No. RC-1050(c) requires replacement parts to be documented on an ASME Manufacturer's Partial Data Report by an ASME Certificate Holder.

Interpretation 01-32

Subject:

Introduction

2001 Edition with 2002 Addendum

Question:

Does reference of a code or standard in the Introduction to the National Board Inspection Code (NBIC) imply it is always acceptable for use?

Reply:

No. The jurisdiction retains the responsibility to decide which codes or standards to adopt for use.

8. NATIONAL BOARD OF BOILER & PRESSURE VESSEL INSPECTORS' REPORT (Cont.)

Interpretation 01-36

Subject:

RC-1020(b)

Requirement to know code of construction prior to repair

2001 Edition with 2002 Addendum

Question:

In order to apply the "R" stamp to a vessel that was repaired or altered, must that vessel first be constructed in accordance with the ASME code or some other recognized code or standard?

Reply:

No.

9. WESTERN CANADA BLRBAC REPORT – Bob Norton

The fall meeting was held in Vancouver on November 5, 2003. There were 30 people in attendance for the meeting. This was the 40th anniversary of the WCBLRBAC committee. Four incidents were reviewed,

September 10/03

Floor tube adjacent to #12 sidewall tube in RH rear corner. The boiler was ESP'd.

The operator inspecting port rodder operation noticed unusual burning condition in the area

Root cause; the leak was on the crown of the floor tube adjacent to the right rear sidewall. It appears to have been initiated by an impact-chipping hammer. The sidewall seal (scallop bar) was replaced 2 years prior and chipping hammers had been used at times to remove the smelt bed in this area.

May 26,2003

Tube 17 row 3 above the lower header left hand side rear economizer.

Water was observed in the ash hopper conveyor. The boiler operator did not perform an ESP.

Root cause: 1/16" pinhole at butt-weld approximately 24' above the bottom header. This was replaced by a 26" pup.

September 17,2003

Leak at top of the bull nose. A pinhole leak had wash two adjacent tubes creating a leak in both of them.

The boiler was not ESP'd.

The operator making a round noticed water and steam leaking from the casing. The boiler was on fossil fuel at the time of the incident.

Root Cause: Weld on seal block behind the baffle had cracked. Leak developed and washed out baffle plate and two adjacent tubes and seal blocks. Three pinhole leaks as well as wash of one lower superheater bend.

9. WESTERN CANADA BLRBAC REPORT (Cont.)

October 22, 2003

Economizer handhole crack

Leak noticed on an operator walk down of the boiler.

Handhole was ground out and replaced.

Technical Papers presented

- Aker Kvaerner, Electric Port Rodders.
 - No external moving parts, providing a safe work environment
 - Operation costs are low compared to pneumatic port rodders.
- Alstom,
 - Enhancing boiler floor tube protection with smelt guard tiles
 - Igniters
 - Nozzles
- Andritz, Envirocare
 - Scrubber upgrades for a dissolving tank
- Babcock and Wilcox, Air system upgrades
 - Comparing air systems in today's industry

The spring meeting was held in Duncan, B.C. on April 6 and 7, 2004.

10. ACTIVITIES OUTSIDE NORTH AMERICA REPORTS

10.1 REPORT FROM BRAZIL – Guido Schreiber (See Appendix B – PowerPoint Slide Presentation)

11. OPERATING PROBLEMS SESSION REPORT – Karl Morency

- a) *Energizing Electrostatic Precipitator during start-up and shutdown when burning oil for auxiliary fuel.* Many mills energize the precipitator before firing the oil burners. Washington State requires energization before the fans are started. Energizing the precipitator eliminates opacity excursions during start-up/shut-down and normally does not affect collection efficiency when firing liquor. This may not work as well on older precipitators. The concern with doing this is the potential for fire and the potential for loss of collection efficiency when firing black liquor because of oil soot coating the electrodes. An alternative procedure to minimize the potential for oil soot reducing collection efficiency is to only energize one or two fields when firing auxiliary fuel. To reduce the potential for having a fire, the energization level can be reduced to prevent arcing. There were no reports of any significant problems with energizing the precipitator to control opacity when firing auxiliary oil burners.
- b) *If not all precipitator fields are energized, which ones should be used?:* One mill advised that they used the outlet field(s). Another mill preheats the oil to 170 F to reduce incomplete combustion and soot information; then sequentially brings up six of 12 fields that are operated at reduced voltage.

11. OPERATING PROBLEMS SESSION REPORT (Cont.)

- c) **Black Liquor burn/chemical hazard:** While disconnecting a liquor gun hose, an operator got sprayed with hot black liquor even though he was wearing the appropriate personnel protective equipment. The incident was due in part to the fact that the stem on the 316SS isolation (ball) valve had been over-torqued and twisted 45° so that the valve was actually half open when the handle was in the closed position. The problem with the valve stem was corrected by changing metallurgy of the stem from 316SS to higher strength 17-7 SS material. The mills SOP for changing out the liquor guns was also revised to reduce the potential for a recurrence. The operator that was burned was taken to a local hospital, treated for burns and released. The hospital did not recognize that he had suffered chemical burns and the burns were not neutralized. The burns continued to get worse and the operator had to readmit himself to the hospital for additional treatment.
- d) **Use of ball valves for rapid drain valves:** No code issues were identified that would prevent use of ball valves for rapid drain valves. The choice of actuator should take into account the need for controlling the rate of valve opening and closing in order to prevent problems with water/steam hammer. Various questions were asked regarding conformance to BLRBAC, need for tight seal, opening torque, and manual operation, but no significant issues were identified.
- e) **Burning of NCGs in BLRB:** 7 of the approximately 30 mills represented burn NCGs in their recovery boiler. One boiler (now shut down) had 25 years experience. During that time, they did experience an explosion as the result of air in-leakage into the CNCG system but explosion vents in the system were sufficient to relieve the force of the explosion. Knockout pots are required to remove condensate – failure to remove presents a serious explosion hazard. Steam stripper fouling resulted in frequent steam stripper flooding and siphoned water into the decanter and NCG line. An intermediate drain back to condensate tank collected condensate because of 30' vertical in the air duct. Separate nozzles were used to inject CNCGs and SOGs. The current BLRBAC guideline addresses these design issues.
- f) **Average bed burnout time and methods to speed up process:** 4-10 hours is typical. No advice on how to speed up process, but shutting off primary air and raising liquor supply temperature will help.
- g) **On-line green liquor density analyzers:** On one boiler the analyzer was moved to the recirculation line to reduce scaling problems and there has been good success with only monthly cleaning required. On another boiler it's right in the main line and there have been no issues. It has been in use for over a year. An in-line refractometer device is being used.
- h) **Unplugging spouts: How to control rod when using a sledgehammer?** Some use natural gas torches instead and is much safer – would not go back to rod. Can use a 4 ft. wrench to hold driven end in place. Another mill has a custom device with handles to hold rod in place, but doesn't allow use of sledgehammers. They use a weighted section of pipe with handles to drive the rods.
- i) **ESP Test of pre-1980 unit:** BLRBAC recommends a one-time test to verify drain time is a maximum of 15 – 20 minutes. The specific issue of doing to an older unit is not addressed by BLRBAC.
- j) **Ring Header or Nozzle Pluggage:** Two mills advised that they had problems. Use of a gorator may solve the problem. It can be caused by solubility limits of salts in liquor tank.

11. OPERATING PROBLEMS SESSION REPORT (Cont.)

- k) **Where is salt cake from ClO₂ generator added to cycle:** Weak black liquor tank; suction of weak liquor pump to multiple-effect evaporators; oxidation tank.
- l) **Anything being done to neutralize the salt cake:** Caustic or white liquor added to raise the pH. Base-load caustic addition regardless of pH value
- m) **At what level should chlorides in the black liquor be controlled to in order to minimize boiler pluggage:** Six report purging precipitator salt cake to control chlorides and others report the ability to run a full year without controlling chlorides. Mills that control chlorides generally limit them to ½% or less in the as fired liquor. One mill reported running at 2% without plugging. Cost of purging can be a deterrent. One method of reducing chloride input to the system is to buy a higher grade caustic. If purging is used, it is done most effectively at the precipitator where chloride concentration is highest.
- n) **Choice of material for floor tubes and lower sidewalls:** For high-pressure boilers, the general standard is to use Sanicro-38 (825 material) composite or weld-overlaid Inconel 625 for the lower walls to above the primary air ports and then 304 SS composite to at least the tertiary level. Choice of material for the floor will depend on whether it is a sloped or decanting bottom. Sanicro 38, weld-overlaid 625 or carbon steel with chromized studs are common options for sloped floors. One of these materials or bare carbon steel are options for decanting hearths. Chromized tubing is another option for corrosion protection. Multi-lead ribbed tubes are sometimes used in combination with weld-overlaid 625 to provide extra circulation margin in floor tube applications although there isn't general consensus on the benefit of MLR.
- o) **Best method for unplugging insertable spouts:** A propane torch is considered the best and safest method.
- p) **Use of computer modeling to improve performance of direct contact evaporators:** Modeling of cascades has been done but the proposed changes have not been implemented yet.
- q) **Suggestions for eliminating steam hammer from steam coil air heater condensate collection systems:** Each coil should be individually trapped. An orificed bypass directly from the high pressure steam supply to the flash tank worked at one location.
- r) **Regulating steam header pressure for oil atomization:** Use a valve specifically designed for controlling atomizing steam differential pressure.
- s) **Bearing failures in dry-bottom precipitators – mean time between failures:** One mill reported good success using graphiloy bearings.
- t) **Use of lubrication systems for precipitator sleeve-type bearings:** One mill that used it reported that it is easy to over-lubricate. They reported that they didn't think it worked as well as graphiloy bearings and is not very forgiving. It works okay if carefully controlled.

11. OPERATING PROBLEMS SESSION REPORT (Cont.)

- u) ***Smelt-spout restrictor designs:*** One mill reported designing their own spout restrictor consisting of an arm on a pivot point with a head that fills a good part of the opening. It is suspended from a cable and swings down into opening when needed. A modification of the mini-hood was needed to accommodate, but mill seems pleased with it. It is operated from the floor above the spouts.
- v) ***Predicting full pressure rapid drain from a partial pressure test:*** Calculations used by the manufacturers must be fairly reliable because there have been no/few reports of re-work as a result of failed test. One of the main restrictions is the rapid drain valve, so valve port diameter and number of valves in series is a major factor.
- w) ***Flexible hoses for oscillating liquor gun nozzles:*** This is currently being done by at least two mills and a number of mills have done it in the past. No one could come up with the name of a supplier or a brand name. The hose should have a stainless steel outer braid and a good PM program is necessary to monitor hose condition. Make sure purpose and the fact of steam out is known to supplier. Other mills reported that they continue to use OEM type joints for full oscillation. The majority of the mills reported using stationary firing.
- x) ***Corrosion of roof tubes near steam drum:*** One mill has found significant rapid corrosion/thinning. Can only be checked by internal NDE/UT. Source/cause not known, but loose tube seats can spray and cause this. Can also be the result of wetness during shutdowns or air in-leakage during operation.
- y) ***Problems with keeping primary air ports open and use of automatic port rodders vs. injury with manual rodding:*** Two-thirds or the mills have automatic port rodders. Injuries with manual rodding can be a real concern especially with an aging work force. Port rodders require high maintenance, but they do prevent injuries and do work well provided they are maintained. Electric drives seem to give best service but have highest first cost.
- z) ***Lighting off auxiliary fuel burners from the control room:*** BLRBAC recommends that an operator be present at the burner front to light off the burners.
- aa) ***Which type of drum level trips work best – level gauge or conductivity probe?*** Aquarians work well most of the time. Clark-Reliance Eye-Highs have proven effective and have no fouling issues with weekly blowdown of water columns.
- bb) ***Stacked Air System:*** One mill converted to a stacked air system a year ago. It has eliminated the need for monthly chill & blow and water washes and both reduction efficiency and boiler efficiency have increased. It also improved turndown and increased throughput. They gave it a rave review! Anthony-Ross did the upgrade.
- cc) ***Experience operating smelt spouts longer than one year:*** Dry spouts have been operated up to two years. One mill increased spout life by lowering cooling water temperature and pulled more air into doghouse to reduce humidity. Another mill reported operating chromized spouts for 3 ½ years. Annual NDE is used to confirm remaining thickness. Another mill has gone to two-year change-out with chromized spouts. If chromized layer wears off in a local area, galvanic corrosion causes quite rapid thinning.

CHAIRMAN'S CLOSING COMMENTS: To make sure I didn't miss anything, do we have anyone else with an offshore report? We were not made aware of any, but I want to be sure. Well, that then concludes our main committee meeting. As Karl noted, after the break we will be picking back up with a technical session. We will probably try for a 15-minutes break. Again, we thank you for your attendance. There is a handout here from the National Board if you want a copy.

TIME & PLACE OF NEXT MEETING: The next meeting will be held on October 4, 5, & 6, 2004, at the Crowne Plaza Hotel/Atlanta Airport, in Atlanta, Georgia.

ADJOURNMENT:

CHAIRMAN: I'd like to adjourn the meeting. Again, the Technical Presentations will start up at 10:00 a.m. Everyone have a safe trip home and we hope to see you all in the fall!

TECHNICAL SESSION:

“Site-Specific Recovery Boiler Leak Detection Training Using Scenario Simulation”

presented by Ron Bernard of Power Specialists Association, Inc.

“A Detailed Study of Recovery Boiler Waterside Deposition”

presented by George Totura of Nalco Company

**APPENDIX A
SUMMARY OF RECOVERY BOILER INCIDENTS**

<p>2004 April - 1 Location: Unit: Size: Incident Date: Leak/Incident Loc: Downtime hrs due to leak/total: ESP? Classification: How discovered: Leak detection: Sequence of events: Bed cooling: Wash adjacent tube: Repair procedure: Root cause: Future prevention: Last full inspection:</p>	<p>Critical Incident No. 582 Western Pulp Ltd., Squamish, British Columbia CE Contract No. 84101. Startup 1986 3.4 million ppd solids. 550,000-lb/hr steam flow. Operating @ 600 psig & 750F. Design @ 800 psig. 2 drum boiler/large economizer/cross flow economizer with no baffles. December 2, 2003 Economizer – hole 1" x 1/8" on furnace side of tube 17 at 1/2" below upper header. Tube thickness surrounding hole 0.170" and no evidence of a crack Total outage time – 35 hours ESP performed. Critical Incident Operator walkdown of the Unit None installed Operator noticed discoloration of hopper ash. Sootblowers stopped and condensation observed on side of the hopper. Started going off liquor when a loud sound was heard on the 9th floor. Door opened and water spraying everywhere including toward the boiler bank. ESP initiated. No cooling enhancement used No Tube x-rayed and thickness checked before and after repair. Repair area preheated to 300F and overlaid with 7018 rod No information Failure area thoroughly checked by Canspec. No other findings of concern. Inspected April 2003. No information on chemical cleaning.</p>
---	--

<p>2004 April – 2 Location: Unit: Size: Incident Date: Leak/Incident Loc: Downtime hrs due to leak/total: ESP? Classification: How discovered: Leak detection: Sequence of events: Bed cooling: Wash adjacent tube: Repair procedure: Root cause: Future prevention: Last full inspection:</p>	<p>Weyerhaeuser, Hawesville, Kentucky No. 4 recovery boiler. Ahlstrom Contract No. 400019. Startup 1997 2.7 million ppd solids. 422,600-lb/hr steam flow. Operating @ 1250 psig & 850F. Design @ 1550 psig. Single drum boiler/large economizer. January 30, 2004 Economizer – circumferential crack ~ 3/4" long x 1/8" wide in west most feeder tube to lower header of last platen in No. 2 economizer (feedwater inlet). Leak ~ 3" from main distribution header (not in a weld or heat affected zone). Total downtime 23.5 hours No ESP Non-critical Incident Recovery helper on boiler walkdown found water running out of the ash hopper. DCS instrumentation did not show other signs of a leak. None installed Operator found water running out of No. 2 economizer hopper. Considering location well removed from furnace, boiler operated from Friday to Sunday and then shutdown in normal fashion. Not applicable No Crack ground out and welded No information Last inspection May 2003. Boiler acid cleaned with HCl in September 1997.</p>
---	---

APPENDIX A
SUMMARY OF RECOVERY BOILER INCIDENTS

<p>2004 April – 3 Location: Unit: Size: Incident Date: Leak/Incident Loc: Downtime hrs due to leak/total: ESP? Classification: How discovered: Leak detection: Sequence of events: Bed cooling: Wash adjacent tube: Repair procedure: Root cause: Future prevention: Last full inspection:</p>	<p>MeadWestvaco, Mahrt Mill, Phenix City, Alabama No. 2 Recovery Boiler. Tampella Contract No. 337. Startup 1990. 3.5 million ppd solids. Steam Flow-561, 000 lb/hr. Operating @ 890 psig & 790F. Design @ 1100 psig. Single drum boiler/large economizer November 15, 2003 Economizer – ~ 1/4" circumferential crack at termination weld of square-cut fin on Tube No. 1 in rear bank (tube at top of inclined header, 4th element from left wall, ~ 1" from header.) Total downtime – 30.4 hours/30.4 hours due to leak. No Non-critical Incident Operator discovered water in conveyor during walkdown No leak detection system. Water was dripping from hopper conveyor onto collection conveyor. Bed was burned out and fire pulled. Leak observed with mirror. Boiler cooled and economizer section washed for repair. Not applicable No Crack repaired and dye penetrant tested Mechanical stress resulting from original design as well as vibration of tubes due to failed stitch weld at fins. 5 leaks in Economizer I since startup. Last NDT inspection September 2003. Chemically cleaned with inhibited HCl in 1990 when started up.</p>
--	---

<p>2004 April – 4 Location: Unit: Size: Incident Date: Leak/Incident Loc: Downtime hrs due to leak/total: ESP? Classification: How discovered: Leak detection: Sequence of events: Bed cooling: Wash adjacent tube: Repair procedure: Root cause: Future prevention: Last full inspection:</p>	<p>MeadWestvaco, Mahrt Mill, Phenix City, Alabama No. 2 Recovery Boiler. Tampella Contract No. 337. Startup 1990. 3.5 million ppd solids. Steam Flow-561, 000 lb/hr. Operating @ 890 psig & 790F. Design @ 1100 psig. Single drum boiler/large economizer January 19, 2004 Economizer – ~ 1/4" circumferential crack at fin 1.5 in. below roof in Front Economizer Bank II, from which FW discharges to the steam drum. Tube 7 from front of bank, 23rd element from left wall. Total downtime – 51 hours/ 29.7 hours due to leak No Non-critical Incident Boiler was being shut down for a chill and blow and very little bed remained. During inspection, a door was opened in sootblower lane of Economizer II and water observed spraying. There has been no previous indication of a leak No leak detection system. Walkdowns during operation heard no unusual noises and no moisture in ash conveyors. Boiler walkdowns are every two hours; Iks are shut off once a day during a walkdown No No Tube removed by cutting near headers and plugging at the headers. Mechanical stress resulting from original design when the economizer tubes supported ash hopper. Believe broken stitch welds between fins permits vibration during sootblowing. 27 leaks in front bank (Economizer II) since startup; 10 in the last 4 years. Support had been modified earlier. Last NDT inspection September 2003. Chemically cleaned with inhibited HCl in 1990 when started up.</p>
--	--

APPENDIX A
SUMMARY OF RECOVERY BOILER INCIDENTS

<p>2004 April - 5 Location: Unit: Size: Incident Date: Leak/Incident Loc: Downtime hrs due to leak/total: ESP? Classification: How discovered: Leak detection: Sequence of events: Bed cooling: Wash adjacent tube: Repair procedure: Root cause: Future prevention: Last full inspection:</p>	<p>MeadWestvaco, Mahrt Mill, Phenix City, Alabama No. 2 Recovery Boiler. Tampella Contract No. 337. Startup 1990. 3.5 million ppd solids. Steam Flow-561, 000 lb/hr. Operating @ 890 psig & 790F. Design @ 1100 psig. Single drum boiler/large economizer January 23, 2004 Economizer – leak at crack in plug used during repair of Economizer II on January 19 shutdown. Tube No. 7, 23rd element from left wall. Total downtime – 36.5 hours due to leak No Non-critical Incident Boiler was being inspected after the boiler tripped due to a loss of instrument air No leak detection system. During outage inspection, water was observed through an open door to be running down the economizer (Economizer II) tube. No unusual noises and no moisture in ash conveyors during boiler walkdowns preceding incident. Boiler walkdowns are every two hours; IKS are shut off once a day during a walkdown No No Plug was replaced Poor plug quality Type of plugs being used were not exactly like the OEM plug. Mill has changed to OEM style plug. Last NDT inspection September 2003. Chemically cleaned - inhibited HCl in 1990 when started up.</p>
--	--

<p>2004 April - 6 Location: Unit: Size: Incident Date: Leak/Incident Loc: Downtime hrs due to leak/total: ESP? Classification: How discovered: Leak detection: Sequence of events: Bed cooling: Wash adjacent tube: Repair procedure: Root cause: Future prevention: Last full inspection:</p>	<p>MeadWestvaco, Mahrt Mill, Phenix City, Alabama No. 2 Recovery Boiler. Tampella Contract No. 337. Startup 1990. 3.5 million ppd solids. Steam Flow-561, 000 lb/hr. Operating @ 890 psig & 790F. Design @ 1100 psig. Single drum boiler/large economizer February 11, 2004 Economizer - ~ ½" circumferential crack at fin 1.5 in. below roof in Economizer II. Tube No. 9, 23rd element from left wall. Total downtime – 42.4 hours No Non-critical Incident Boiler was being inspected after the boiler was shutdown for water wash No leak detection system. During outage inspection, water was observed through an open door to be spraying across the sootblower cavity of Economizer II. No unusual noises and no moisture in ash conveyors during boiler walkdowns preceding incident. Boiler walkdowns are every two hours; IKS are shut off once a day during a walkdown No No Tube removed by cutting the tube near the headers and plugging at the headers through a window in the header wall. Mechanical stress resulting from original design when the economizer tubes supported ash hopper. Also, vibration of tubes due to failed stitch weld at fins. 29 leaks in front bank (Economizer II) since startup; 12 in the last 4 years. Support had been modified earlier for support by the sidewall casing. Plant considering removing a row of economizer tubes to provide access into the sootblower cavity for repair of stitch welds and tube repairs. Sootblower poppet valve pressure reduced to 200 psig in this area. Last NDT inspection September 2003. Chemically cleaned - inhibited HCl in 1990 when started up.</p>
--	---

**APPENDIX A
SUMMARY OF RECOVERY BOILER INCIDENTS**

<p>2004 April – 9 Location: Unit: Size: Incident Date: Leak/Incident Loc: Downtime hrs due to leak/total: ESP? Classification: How discovered: Leak detection: Sequence of events: Bed cooling: Wash adjacent tube: Repair procedure: Root cause: Future prevention: Last full inspection:</p>	<p>MeadWestvaco, Charleston, South Carolina B&W Contract PR-206. Startup 1984. 4.5 million ppd solids. Steam flow 691,000 lb/hr. Operating @ 1450 psig & 880F. Design @ 1725 psig. Two drum/large economizer August 8, 2003 Economizer- longitudinal crack in each of two welds of the 13th tube from rear wall in the 36th and 38th platen header from the right hand sidewall. Total downtime 45.5 hours No Non-critical Incident Operator on routine walkdown found wet saltcake in the economizer ash conveyor. Acoustic leak detection system in operation did not detect the leak After finding leak, oil burners placed in operation and liquor guns removed. Doors at economizer opened for inspection and leak observed. Boiler then shutdown. None used No Repair by grinding crack and welding the defect Crack showed some indication of corrosion but appeared to be caused primarily by fatigue propagated from the internal surface of the tube. Investigation in progress to evaluate whether root cause of initial crack formation in the header is a result of manufacturer not following specified weld detail. Continue to evaluate tube and header measurements in rear economizer bank, cost of replacing all rear economizer lower headers, or replacing at bottom of economizer the lower elevation of headers and plugging the higher elevation of headers Inspection March 20, 2003. Last chemical cleaning September 25, 2002, with HCl</p>
---	---

<p>2004 April – 10 Location: Unit: Size: Incident Date: Leak/Incident Loc: Downtime hrs due to leak/total: ESP? Classification: How discovered: Leak detection: Sequence of events: Bed cooling: Wash adjacent tube: Repair procedure: Root cause: Future prevention: Last full inspection:</p>	<p>International Paper Company, Texarkana, Texas Recovery Boiler 2. B&W Contract PR-186. Startup 1976. 4.55 million ppd solids. Steam flow 763,000 lb/hr. Operating @ 1050 psig & 813F. Design @ 1200 psig. Two drum boiler/large economizer November 28, 2003 Economizer – 1/2 " crack in hand hole weld on lower header of primary economizer located at a lower elevation than the mud drum Total downtime 46 hours No Non-critical Incident Liquor solids to burners at 72% noticed to drop to 68% and then recover to 72%. Investigation found water gurgling out of the cleanout for the south hopper ash discharge line that was plugged None installed Boiler shutdown in normal manner. The line had unplugged to allow some water to enter the mix tank and drop the solids, and then the line plugged up again Not applicable No Old cap removed, seat repaired and new hand hole cap welded in place Economizer scheduled for replacement in 2005. Last inspection April 2003. Boiler acid cleaned with HCl in 1996</p>
--	---

APPENDIX A
SUMMARY OF RECOVERY BOILER INCIDENTS

<p>2004 April – 11 Location: Unit: Size: Incident Date: Leak/Incident Loc: Downtime hrs due to leak/total: ESP? Classification: How discovered: Leak detection: Sequence of events: Bed cooling: Wash adjacent tube: Repair procedure: Root cause: Future prevention: Last full inspection:</p>	<p>Critical Incident No. 583 Smurfit-Stone Container Corporation, Missoula, Montana No. 4 Recovery Boiler. B&W Contract PR-147. Startup 1972. 3.0 million ppd solids. Steam flow 485,000 lb/hr. Operating @ 600 psig & 750F. Design @ 950 psig. Two drum/ large economizer December 29, 2003 Economizer – Tube sheared completely (jagged circumferential tear) 3 to 4 inches below upper header. Tube was 2nd row of 6-row module and 25th row from LHSW. Generating bank is crossflow with no baffles. Total downtime 43.1 hours. ESP performed. Minimum waiting period to enter building of 5 hours for incident with no water-entering furnace. Critical Incident- the leak location could result in water entering the furnace as there were no baffles between sheared tube and the furnace Control room indication of severe positive furnace draft followed by increased feedwater flow and loss of drum level. None installed Drum level decrease caused low drum level alarm. Operator immediately initiated ESP. Post ESP re-entry to building confirmed leak at top of economizer. Wash pattern from leak confirmed water did not enter the furnace. No No Removed tube and plugged header Undetermined. Two areas around the circumference at the failure appeared to have considerable thinning of tube wall. No indication of blistering, swelling or fish mouth rupture Last inspection September 2003. Acid cleaned in August 1981 with 65% HCl acid</p>
--	---

<p>2004 April – 12 Location: Unit: Size: Incident Date: Leak/Incident Loc: Downtime hrs due to leak/total: ESP? Classification: How discovered: Leak detection: Sequence of events: Bed cooling: Wash adjacent tube: Repair procedure: Root cause: Future prevention: Last full inspection:</p>	<p>Eastern Paper, Lincoln, Maine No. 2 Recovery Boiler. B&W Contract PR-151. Startup 1972. Furnace rebuilt by B&W 1995 1.6 million ppd solids. Steam flow 235,000 lb/hr. Operating @ 600 psig & 650F. Design @ 750 psig. Two drum boiler/large economizer October 31, 2003 Economizer – crack on top of 2" drain line from center lower header Total downtime 33.5 hours No Non-critical Incident 1st Assistant Operator discovered leak during rounds when he opened the hopper door to check for pluggage and noticed a small amount of water running down the hopper wall None installed Operator notified Liquor Cycle Foreman & supervisor. Observation determined feedwater/steam differential & refractometer solids unaffected. At bottom economizer, water coming from inside insulation. Doors opened, but salt cake and fume prevented observation. As a precaution, mix tank bypassed. Over ~ 2 hrs, liquor flow reduced and oil guns inserted for bed burndown. Leak could then be observed. Not applicable No Crack ground and NDT'd. No propagation found. Area ground full circle around elbow & rewelded. Seal of pipe penetrating casing did not allow sufficient expansion, and caused stress on pipe as economizer expanded. Over time, pipe installed in 1995 cracked. Seal enlarged for proper expansion. Seal on other side modified also. Boiler and economizer inspected 9/5/2003. Acid cleaned 1999 with Inhibited Intensified HCl, Chelant passivation</p>
---	--

APPENDIX A
SUMMARY OF RECOVERY BOILER INCIDENTS

<p>2004 April – 13 Location: Unit: Size: Incident Date: Leak/Incident Loc: Downtime hrs due to leak/total: ESP? Classification: How discovered: Leak detection: Sequence of events: Bed Cooling: Wash adjacent tube: Repair procedure: Root cause: Future prevention: Last full inspection:</p>	<p>International Paper Company, Vicksburg, Mississippi B&W COntract PR-105. Startup 1967. B&W supplied economizer in 1985 3.0 million ppd solids. 509,700-lb/hr steam. Operating @ 1020 psig & 825F. Design @ 1200 psig. Two drum boiler/DCE. Leak discovered August 31, 2003. Shutdown September 3, 2003 Economizer – leak in a lower header handhole cap seal weld. Handhole in north end of southwest module of the six modules. Total downtime 32 hours. No Non-critical Incident Leak discovered by routine operator walkdown None installed Management considered leak location and decision made to operate until a scheduled outage was planned. The planned and orderly shutdown took place two days after the leak was verified. No No Leak repaired per ASME Section I using WPS RMR-11212 The original 1986 seal weld of the cap to the header was determined to be defective because only two weld passes were applied. Manufacturer recommends three passes. All economizer hand hole cap welds will be visually and dye penetrant tested during the April 2004 yearly maintenance outage Last inspection 2003. Boiler acid cleaned in 2000 using standard process</p>
---	--

<p>2004 April – 14 Location: Unit: Size: Incident Date: Leak/Incident Loc: Downtime hrs due to leak/total: ESP? Classification: How discovered: Leak detection: Sequence of events: Bed cooling: Wash adjacent tube: Repair procedure: Root cause: Future prevention: Last full inspection:</p>	<p>International Paper Company, Kaukauna, Wisconsin No.8 Recovery Boiler. B&W Contract S-9759. Startup 1952 0.75 million ppd solids. 128,000-lb/hr steam flow. Operation @ 600 psig & 700F. Design @ 650 psig. Two drum boiler/economizer/tubular air heater. Boiler bank is two pass with a rear wall baffle, followed by integral economizer. December 3, 2003 Economizer – First leak a 1.5” circumferential crack at rear wall buckstay attachment at the rear row of tubes, 3rd tube from right sidewall. Second leak observed when boiler filled with demineralized water. This 0.75” circumferential attachment crack was in the rear row, tube 22 from left hand sidewall, ¾” above lower header. Total downtime 26 hours No Non-critical Incident (both leaks) Leak discovered during shutdown when water observed on exterior of boiler casing None installed Boiler operating staff determined no evidence that water was reaching the furnace and noted the baffles between the leak area and the furnace cavity. The leak appeared to be in the economizer right sidewall section & was spraying on tubes above the tubular air heater. The bed had been burned out prior to discovering the leak to complete planned repairs. Fire was now removed from the boiler 35 minutes after leak discovery. Not applicable No Welds were repaired. 1st leak believed to be fatigue failure. 2nd appeared to be result of tube thinning from tube expanding during construction. These were 1st attachment leaks on rear wall; several earlier sidewall leaks Economizer on capital list for replacement within two years. Last inspection October 2003. Acid cleaned October 2002</p>
---	--

APPENDIX A
SUMMARY OF RECOVERY BOILER INCIDENTS

<p>2004 April – 17</p> <p>Location:</p> <p>Unit:</p> <p>Size:</p> <p>Incident Date:</p> <p>Leak/Incident Loc:</p> <p>Downtime hrs due to leak/total:</p> <p>ESP?</p> <p>Classification:</p> <p>How discovered:</p> <p>Leak detection:</p> <p>Sequence of events:</p> <p>Bed cooling:</p> <p>Wash adjacent tube:</p> <p>Repair procedure:</p> <p>Root cause:</p> <p>Future prevention:</p> <p>Last full inspection:</p>	<p>International Paper Company, Roanoke Rapids, North Carolina</p> <p>No. 7 Recovery Boiler. B&W Contract PR-168. Startup 1973.</p> <p>2.6 million ppd solids. Steam flow 460,000 lb/hr. Operating @ 850 psig & 825F. Design @ 1000 psig. Two drum boiler</p> <p>November 12, 2003</p> <p>Economizer – 1” crack in the rear lower header handhole cap weld (not the same cap as Incident 16)</p> <p>Total downtime due to leak 34.5 hours</p> <p>No</p> <p>Non-critical Incident</p> <p>First helper saw water in the 5th floor economizer hopper</p> <p>Champion Intl Mass Balance System in operation neither detected nor confirmed leak</p> <p>Close examination indicated water probably coming from a handhole. Sootblowers stopped and exact location pinpointed. Bed burned out and organized outage conducted.</p> <p>No</p> <p>No</p> <p>Weld ground out and repaired</p> <p>Porosity in an old weld at the point where it started and stopped.</p> <p>Kvaerner replacement economizer installed April 2004. Look into reliability of mass balance system</p> <p>Last inspection June 2003. Acid cleaned in 1998 with 7.5% inhibited HCl/traditional method of soak and surge with alkaline pre-flush</p>
--	--

<p>2004 April – 18</p> <p>Location:</p> <p>Unit:</p> <p>Size:</p> <p>Incident Date:</p> <p>Leak/Incident Loc:</p> <p>Downtime hrs due to leak/total:</p> <p>ESP?</p> <p>Classification:</p> <p>How discovered:</p> <p>Leak detection:</p> <p>Sequence of events:</p> <p>Bed cooling:</p> <p>Wash adjacent tube:</p> <p>Repair procedure:</p> <p>Root cause:</p> <p>Future prevention:</p> <p>Last full inspection:</p>	<p>Georgia Pacific, Palatka, Florida</p> <p>No. 4 Recovery Boiler. ABB-CE Contract CE22974. Startup 1976. Alstom revamp Contract 22974 V2R in 1993.</p> <p>4.6 million ppd solids. Steam flow 740,000 lb/hr. Operation @ 1250 psig & 850F.</p> <p>December 6, 2003</p> <p>Superheater – tube sheared off just above the high crown seal and adjacent tube had a circumferential crack in a previous weld repair. These were 2 of 4 tubes in a section of crossover tubes from drum to element #17 of rear superheater bank. This is original superheater</p> <p>Total downtime 58 hours</p> <p>ESP was performed. Irrevocable policy is to stay out of recovery area 12 hours</p> <p>Non-critical Incident</p> <p>Vapor observed venting from penthouse on November 30.</p> <p>Boiler water chemistry system did not detect a leak in the superheater</p> <p>. Observation with doors removed and of different methods for leak determination did not confirm a leak and operation continued with every shift inspection. Vapor showed each night & cleared up about noon. On Dec. 6, considerable vapor observed coming from a 9th floor wall opening & DCS indicated beginnings of feedwater/steam separation with steam flow dropping. Liquor diverted & feedwater valve was closed. Because of history of roof tube failures, ESP was initiated.</p> <p>No</p> <p>No</p> <p>Section of both tubes replaced and welded from inside penthouse and from below the roof</p> <p>Tube fatigue. Tube sent off for additional analysis</p> <p>Tubes to be replaced during major shutdown in April and May 2004. Incident reviewed with all boiler operators to emphasize vapor from penthouse indicative of probable SH leak. Indicators of other types leaks also reviewed.</p> <p>Inspected May 2003. Acid cleaned May 2003.</p>
--	--

**APPENDIX A
SUMMARY OF RECOVERY BOILER INCIDENTS**

<p>2004 April – 19 Location: Unit: Size: Incident Date: Leak/Incident Loc: Downtime hrs due to leak/total: ESP? Classification: How discovered: Leak detection: Sequence of events: Bed cooling: Wash adjacent tube: Repair procedure: Root cause: Future prevention: Last full inspection:</p>	<p>International Paper Company, Augusta, Georgia B&W Contract PR-89. Startup 1965 1.79 million ppd solids. Original design 1.2 million ppd solids. Steam flow 185,000 lb/hr. Operating @ 850 psig & 900F. Design @ 875 psig. Two drum boiler/direct contact evaporator September 28, 2003 Superheater – ¼” by ½” hole in bottom of 180 bend to secondary SH outlet tube. This is innermost loop of 4 loops at front of 2nd bank in superheater. Total downtime 62 hours. No Non-critical Incident Operator hearing noise during walkdown None installed. Operator on rounds at the 6th floor level heard a noise from the secondary superheater. Liquor was diverted and a door opened to confirm the leak location. Bed burned out and oil fire pulled. No No Loop replaced Corrosion related to tube temperatures and high carryover rate. SH loops are NDT'd annually. As failure off-center at 3 o'clock position, testing may have missed it. Stationary firing trials have lowered carry-over but resulted in unstable operation (severe blackouts) Last inspection 2003 Chemical cleaned in April 1999</p>
--	--

<p>2004 April – 20 Location: Unit: Size: Incident Date: Leak/Incident Loc: Downtime hrs due to leak/total: ESP? Classification: How discovered: Leak detection: Sequence of events: Bed cooling: Wash adjacent tube: Repair procedure: Root cause: Future prevention: Last full inspection:</p>	<p>International Paper Company, Roanoke Rapids, North Carolina No. 6 Recovery Boiler. CE Contract 17455. Startup 1956 1.286 million ppd solids. Steam flow 188,000 lb/hr. Operation @ 820 psig & 760F. Design @ 1000 psig. Two drum boiler/ Direct Contact Evaporator August 8, 2003 Superheater – 2” circumferential crack in 4th pendant from left wall of primary superheater inlet tube just below the penetration through flat studs of roofline. SH loops have no support. Total downtime 45 hrs 50 minutes ESP performed Non-critical Incident Operator heard a noise in generating bank ash hopper when walking boiler down and opening hopper door An in-house mass balance system in operation did not detect leak. System noted as unreliable Operator did not observe water when opening other doors to verify location & there was no indication of leak by boiler feedwater test or by FW/steam differential. Unable to identify source, boiler was ESP'd. Cooling with sodium bicarbonate and nitrogen attributed with 6 to 8 hours time savings No Dutchman installed Fatigue resulting from tubes swinging during sootblowing. Gemini nozzles installed 2001. Poppet valve pressure at 200 psig lowered to 175 psig after observing swinging of pendants with camera. Other leak in same area in 2001. <u>Boiler will be retired in June 2004.</u> Last inspected May 2003. Unit has never been chemically cleaned.</p>
--	--

**APPENDIX A
SUMMARY OF RECOVERY BOILER INCIDENTS**

<p>2004 April – 21 Location: Unit: Size: Incident Date: Leak/Incident Loc: Downtime hrs due to leak/total: ESP? Classification: How discovered: Leak detection: Sequence of events: Bed cooling: Wash adjacent tube: Repair procedure: Root cause: Future prevention: Last full inspection:</p>	<p>International Paper Company Franklin, Virginia No. 6 Recovery Boiler. B&W Contract PR-185. Startup 1977 3.6 million ppd solids. Steam flow 600,000 lb/hr. Operating @ 1500 psig & 875F. Design @ 1700 psig. Two drum boiler/large economizer May 19, 2003 Superheater – fishmouth failure on bottom of primary superheater loop at primary SH inlet 105' above floor. PSH inlet is at the flue gas inlet to superheater. Total downtime 73 hours ESP performed Non-critical Incident Operator heard leak blowing during a normal walkdown Mass balance system in operation at time of incident did not detect but did confirm a leak. Roaring noise heard by operator was accompanied by substantial feedwater/steam differential, without loss of drum level. Boiler immediately ESP'd. No No Replaced superheater loop. Bottom of loop thinned by smelt corrosion at a smelt drip point. Ash is high in potassium. Higher sulfidity levels have increased water wash frequency to every 6 weeks and corrosion is more active with clean tube. Initiated purging some ash to reduce chloride and potassium and plan to implement a purge system for a larger volumetric quantity. Started sewerage some spent acid to lower sulfidity. Water wash frequency has improved to every 3 months. Program is to determine by NDT bends requiring replacement and install chromized tube bends. Last inspection November 2002. Acid cleaned with HCl February 2000.</p>
--	---

<p>2003 April – 22 Location: Unit: Size: Incident Date: Leak/Incident Loc: Downtime hrs due to leak/total: ESP? Classification: How discovered: Leak detection: Sequence of events: Bed cooling: Wash adjacent tube: Repair procedure: Root cause: Future prevention: Last full inspection:</p>	<p>International Paper Company, Franklin, Virginia No. 6 Recovery Boiler. B&W Contract PR-185. Startup 1977 3.6 million ppd solids. Steam flow 600,000 lb/hr. Operating @ 1500 psig & 875F. Design @ 1700 psig. Two drum boiler/large economizer August 26, 2003 Superheater – fishmouth failure on bottom of primary superheater loop at primary SH inlet 105' above floor. PSH inlet is at flue gas inlet to SH. Total downtime 86 hours ESP performed Non-critical Incident Operator heard leak blowing during a normal walkdown Mass balance system in operation at time of incident did not detect but did confirm a leak. Roaring noise heard by operator was accompanied by substantial feedwater/steam differential, without loss of drum level. Boiler immediately ESP'd. No No Replaced superheater loop. Bottom of loop thinned by smelt corrosion at a smelt drip point. Ash is high in potassium. Higher sulfidity levels have increased water wash frequency to every 6 weeks and corrosion is more active with clean tube. Initiated purging some ash to reduce chloride and potassium and plan to implement a purge system for a larger volumetric quantity. Started sewerage some spent acid to lower sulfidity. Water wash frequency has improved to every 3 months. Completed program to NDT bends and replace bends as required. Last inspection November 2002. Acid cleaned with HCl February 2000.</p>
--	---

APPENDIX A
SUMMARY OF RECOVERY BOILER INCIDENTS

<p>2004 April – 23</p> <p>Location:</p> <p>Unit:</p> <p>Size:</p> <p>Incident Date:</p> <p>Leak/Incident Loc:</p> <p>Downtime hrs due to leak/total:</p> <p>ESP?</p> <p>Classification:</p> <p>How discovered:</p> <p>Leak detection:</p> <p>Sequence of events:</p> <p>Bed cooling:</p> <p>Wash adjacent tube:</p> <p>Repair procedure:</p> <p>Root cause:</p> <p>Future prevention:</p> <p>Last full inspection:</p>	<p>Smurfit-Stone Container Corporation, Brewton, Alabama</p> <p>Recovery Boiler No. 2. B&W Contract PR-79. Startup 1963.</p> <p>1.2 million ppd solids. Steam flow 184,000 lb/hr. Operating @880 psig & 830F. Design @ 975 psig. Two drum boiler/small horizontal tube economizer/direct contact evaporator. This boiler operates with all air admitted below the liquor guns; there is no tertiary air.</p> <p>October 13, 2003</p> <p>Superheater – primary SH tube (adjacent to sootblower path through cavity) in 16th platen from right sidewall. Break about 4' below roof was just below a weld line in the bent tube that bridges the sootblower cavity.</p> <p>Downtime due to ESP 31 hrs 5 min steam to steam. /Total downtime 32 hr 10 min liquor to liquor</p> <p>ESP performed. Mill has a standard 8-hour waiting period to stay out of boiler house.</p> <p>Non-critical Incident</p> <p>Recovery Operator observed upward swing in drum level and heard a blowing sound.</p> <p>None installed</p> <p>On hearing the noise, an ESP was immediately initiated.</p> <p>No</p> <p>No</p> <p>Installed a 2' long Dutchman</p> <p>Stress fatigue due to cyclic stress caused by sootblowers in the area. This is general location of earlier failures.</p> <p>Inspected April 2003. Chemical cleaned in 1983</p>
--	---

<p>2004 April – 24</p> <p>Location:</p> <p>Unit:</p> <p>Size:</p> <p>Incident Date:</p> <p>Leak/Incident Loc:</p> <p>Downtime hrs due to leak/total:</p> <p>ESP?</p> <p>Classification:</p> <p>How discovered:</p> <p>Leak detection:</p> <p>Sequence of events:</p> <p>Bed cooling:</p> <p>Wash adjacent tube:</p> <p>Repair procedure:</p> <p>Root cause:</p> <p>Future prevention:</p> <p>Last full inspection:</p>	<p>Smurfit-Stone Container Corporation, Brewton, Alabama</p> <p>Recovery Boiler No. 2. B&W Contract PR-79. Startup 1963.</p> <p>1.2 million ppd solids. Steam flow 184,000 lb/hr. Operating @880 psig & 830F. Design @ 975 psig. Two drum boiler/small horizontal tube economizer/direct contact evaporator. This boiler operates with all air admitted below the liquor guns; there is no tertiary air.</p> <p>November 30, 2003</p> <p>Superheater – primary SH tube adjacent to sootblower path through cavity in 2nd tube from south wall separated about 1 ft below roof. Break was just below a weld line in the bent tube that bridges the sootblower cavity.</p> <p>Downtime due to ESP 32 hrs 55 min steam to steam. /Total downtime 34 hr 7 min liquor to liquor</p> <p>ESP performed. Mill has a standard 8-hour waiting period to stay out of boiler house.</p> <p>Recovery Operator observed upward swing in drum level and a downward swing in steam flow rate, and heard a blowing sound.</p> <p>None installed</p> <p>On hearing the noise, an ESP was immediately initiated.</p> <p>No</p> <p>No</p> <p>Installed a 4' long Dutchman</p> <p>Stress fatigue due to cyclic stress caused by sootblowers in the area. This is general location of earlier failures.</p> <p>Vibration bar added to link the repaired tube to adjacent superheater tubes.</p> <p>Inspected April 2003. Chemical cleaned in 1983</p>
--	--

**APPENDIX A
SUMMARY OF RECOVERY BOILER INCIDENTS**

<p>2004 April – 25</p> <p>Location:</p> <p>Unit:</p> <p>Size:</p> <p>Incident Date:</p> <p>Leak/Incident Loc:</p> <p>Downtime hrs due to leak/total:</p> <p>ESP?</p> <p>Classification:</p> <p>How discovered:</p> <p>Leak detection:</p> <p>Sequence of events:</p> <p>Bed cooling:</p> <p>Wash adjacent tube:</p> <p>Repair procedure:</p> <p>Root cause:</p> <p>Future prevention:</p> <p>Last full inspection:</p>	<p>Smurfit-Stone Container Corporation, Brewton, Alabama</p> <p>Recovery Boiler No. 2. B&W Contract PR-79. Startup 1963.</p> <p>1.2 million ppd solids. Steam flow 184,000 lb/hr. Operating @880 psig & 830F. Design @ 975 psig. Two drum boiler/small horizontal tube economizer/direct contact evaporator. This boiler operates with all air admitted below the liquor guns; there is no tertiary air.</p> <p>December 30, 2003</p> <p>Superheater – 3rd primary SH tube from south wall adjacent to sootblower path through cavity sheared off about 4 ft below roof. Break was just above a weld line in the bent tube that bridges the sootblower cavity. Break above weld on “new tube” side; loops bridging cavity replaced in 2001 to 4 ft below roof</p> <p>Downtime due to ESP 26 hrs 30 min steam to steam. /Total downtime 29 hr 8 min liquor to liquor</p> <p>ESP performed. Mill has a standard 8-hour waiting period to stay out of boiler house. One drain line required alternate means to open rapid drain valves.</p> <p>Non-critical Industry</p> <p>Recovery Operator observed upward swing in drum level and blowing sound.</p> <p>None installed</p> <p>On hearing the noise, an ESP was immediately initiated.</p> <p>No</p> <p>No</p> <p>Installed a 4' long Dutchman</p> <p>Stress fatigue due to cyclic stress caused by sootblowers in the area. This is general location of earlier failures.</p> <p>Those tubes bridging the cavity not previously replaced will be replaced in May 2004. The steam cooled spacer tube removed in 1980 will be replaced to restrain tube movement.</p> <p>Inspected June 2003. Chemical cleaned in 1983</p>
--	---

<p>2004 April – 26</p> <p>Location:</p> <p>Unit:</p> <p>Size:</p> <p>Incident Date:</p> <p>Leak/Incident Loc:</p> <p>Downtime hrs due to leak/total:</p> <p>ESP?</p> <p>Classification:</p> <p>How discovered:</p> <p>Leak detection:</p> <p>Sequence of events:</p> <p>Bed cooling:</p> <p>Wash adjacent tube:</p> <p>Repair procedure:</p> <p>Root cause:</p> <p>Future prevention:</p> <p>Last full inspection:</p>	<p>International Paper Company, Pine Bluff, Arkansas</p> <p>No. 3 Recovery Boiler. B&W Contract PR-60. B&W Superheater Revamp (new superheater) Contract 546-1383 in 1998. Startup 1960.</p> <p>1.5 million ppd solids. Steam flow 202,000 lb/ hr. Operating @1275 psig & 900F. Design @ 1425 psig. Two drum boiler/direct contact evaporator</p> <p>September 26, 2003</p> <p>Superheater – rupture of SA213-T22 secondary SH outlet tube at an area of wastage on leading edge of 2nd platen from left sidewall at IK elevation. Fish mouth shaped opening approx 9” long and the full width of tube, with thin edges. Localized thinning of tube for almost total length roof to bottom loop</p> <p>Total downtime 50.07 hours</p> <p>ESP was performed. Current irrevocable policy is to stay out of recovery area for 4 hours</p> <p>Non-critical Incident</p> <p>Operator heard sound of failure in the control room</p> <p>None installed</p> <p>Outlet tube failed and caused high furnace pressure and rapid loss of drum level. Operator heard the roar of the failure in the control room and observed the furnace pressure/drum level changes. ESP actuated immediately. .</p> <p>No</p> <p>No</p> <p>. Installed straight length of tube from just below roof to 3' above loop, plus installed hairpin loop with 3' of straight.</p> <p>Tube wall thinning by high temperature sulfidation</p> <p>Chromizing of leading edge tube in platen, air system upgrades to reduce mechanical carryover and additional sootblowers to clean primary superheater. PSH plugging and unbalancing gas flow.</p> <p>Last inspection June 2003. Cleaned with HCl (bromate stage canceled) in May 2001</p>
--	--

**APPENDIX A
SUMMARY OF RECOVERY BOILER INCIDENTS**

<p>2004 April - 27</p> <p>Location:</p> <p>Unit:</p> <p>Size:</p> <p>Incident Date:</p> <p>Leak/Incident Loc:</p> <p>Downtime hrs due to leak/total:</p> <p>ESP?</p> <p>Classification:</p> <p>How discovered:</p> <p>Leak detection:</p> <p>Sequence of events:</p> <p>Bed cooling:</p> <p>Wash adjacent tube:</p> <p>Repair procedure:</p> <p>Root cause:</p> <p>Future prevention:</p> <p>Last full inspection:</p>	<p>International Paper Company, Pine Bluff, Arkansas</p> <p>No. 3 Recovery Boiler. B&W Contract PR-60. B&W Superheater Revamp Contract 546-1383 in 1998. Startup 1960.</p> <p>1.5 million ppd solids. Steam flow 202,000 lb/ hr. Operating @1275 psig & 900F. Design @ 1425 psig. Two drum boiler/direct contact evaporator</p> <p>November 19, 2003</p> <p>Superheater – small ¼” hole in secondary SH outlet bank on trailing edge of a tube that is the rearmost tube in the bank</p> <p>Total downtime 30.67 hours</p> <p>ESP was performed. Current irrevocable policy is to stay out of recovery area for 4 hours</p> <p>Non-critical Incident</p> <p>Operator making his rounds heard the failure. An ESP was immediately initiated because the sound was not located to the rear if the generating bank.</p> <p>None installed</p> <p>Liquor flow diverted requiring operators to fire auxiliary gas to maintain steaming rate. Outlet tube failed and fuels tripped caused high furnace pressure and drum level swing. ESP actuated.</p> <p>No</p> <p>No</p> <p>Repaired by pad welding. Tube section will be installed during next outage.</p> <p>Sootblower chaffing of tube. The Secondary SH outlet tube that supports the front of the pendant is lengthening due to sulfidation attack causing platen to swing back into the sootblower.</p> <p>Chromizing of leading edge of tube, air system upgrades and more sootblowers</p> <p>Last inspection June 2003. Cleaned with HCl (bromate stage canceled) in May 2001</p>
--	--

<p>2004 April – 28</p> <p>Location:</p> <p>Unit:</p> <p>Size:</p> <p>Incident Date:</p> <p>Leak/Incident Loc:</p> <p>Downtime hrs due to leak/total:</p> <p>ESP?</p> <p>Classification:</p> <p>How discovered:</p> <p>Leak detection:</p> <p>Sequence of events:</p> <p>Bed cooling:</p> <p>Wash adjacent tube:</p> <p>Repair procedure:</p> <p>Root cause:</p> <p>Future prevention:</p> <p>Last full inspection:</p>	<p>International Paper Company, Pine Bluff, Arkansas</p> <p>No. 3 Recovery Boiler. B&W Contract PR-60. B&W Superheater Revamp (new superheater) Contract 546-1383 in 1998. Startup 1960.</p> <p>1.5 million ppd solids. Steam flow 202,000 lb/ hr. Operating @1275 psig & 900F. Design @ 1425 psig. Two drum boiler/direct contact evaporator.</p> <p>December 24, 2003</p> <p>Superheater – large fishmouth rupture approx 7.5” in length & extending one-third of way around the tube. Vertical edges of failure very thin; leading edge noticeably thinned by external metal loss. 3rd secondary SH pendant from left wall.</p> <p>Total downtime 26.13 hours.</p> <p>ESP was performed. Current irrevocable policy is to stay out of recovery area for 4 hours</p> <p>Non-critical Incident</p> <p>Rupture caused over pressurization of the furnace and a rapid loss in drum level. Fuels (gas and liquor) tripped immediately. ESP was immediately initiated</p> <p>None installed</p> <p>See “How Discovered”</p> <p>No</p> <p>No</p> <p>Tube section installed</p> <p>High steam and flue gas temperatures causing tube wastage</p> <p>Chromizing of leading edge of tube, air system upgrades and more sootblowers</p> <p>Last inspection June 2003. Cleaned with HCl (bromate stage canceled) in May 2001</p>
--	---

APPENDIX A
SUMMARY OF RECOVERY BOILER INCIDENTS

<p>2004 April - 29</p> <p>Location:</p> <p>Unit:</p> <p>Size:</p> <p>Incident Date:</p> <p>Leak/Incident Loc:</p> <p>Downtime hrs due to leak/total:</p> <p>ESP?</p> <p>Classification:</p> <p>How discovered:</p> <p>Leak detection:</p> <p>Sequence of events:</p> <p>Bed cooling:</p> <p>Wash adjacent tube:</p> <p>Repair procedure:</p> <p>Root cause:</p> <p>Future prevention:</p> <p>Last full inspection:</p>	<p>International Paper Company, Pine Bluff, Arkansas</p> <p>No. 3 Recovery Boiler. B&W Contract PR-60. B&W Superheater Revamp Contract 546-1383 in 1998. Startup 1960.</p> <p>1.5 million ppd solids. Steam flow 202,000 lb/ hr. Operating @1275 psig & 900F. Design @ 1425 psig. Two drum boiler/direct contact evaporator</p> <p>January 7, 2004</p> <p>Superheater – large fishmouth rupture approx 5.5” in length & extending three quarters of way around the tube. Vertical edges of failure very thin; leading edge noticeably thinned by external metal loss. Failure in outlet tube of 25th secondary SH pendant from left wall (3rd from right wall). Tube material SA 213-T22</p> <p>Total downtime 98.05 hours.</p> <p>ESP was performed. Current irrevocable policy is to stay out of recovery area for 4 hours</p> <p>Non-critical Incident</p> <p>Rupture caused over pressurization of the furnace and a rapid loss in drum level. An ESP was immediately initiated</p> <p>None installed</p> <p>Outlet tube failed caused high furnace pressure and drum level swing. Gas and liquor fuels tripped immediately. ESP actuated.</p> <p>No</p> <p>No</p> <p>Failed tube repaired by installing a straight section. NDT identified 17 additional thinned tubes and sections were replaced</p> <p>High steam and flue gas temperatures causing wastage. High level of mechanical carryover creates localized reducing condition.</p> <p>Chromizing of leading edge of tube, air system upgrades and more sootblowers upstream of Primary SH. (Ash pluggage in PSH results in steam temperature in tubes 2 and 3 from both sides of SSH outlet to be “couple hundred degrees” higher</p> <p>Last inspection June 2003. Cleaned with HCl (bromate stage canceled) in May 2001</p>
--	--

<p>2004 April – 30</p> <p>Location:</p> <p>Unit:</p> <p>Size:</p> <p>Incident Date:</p> <p>Leak/Incident Loc:</p> <p>Downtime hrs due to leak/total:</p> <p>ESP?</p> <p>Classification:</p> <p>How discovered:</p> <p>Leak detection:</p> <p>Sequence of events:</p> <p>Bed cooling:</p> <p>Wash adjacent tube:</p> <p>Repair procedure:</p> <p>Root cause:</p> <p>Future prevention:</p> <p>Last full inspection:</p>	<p>International Paper Company, Pine Bluff, Arkansas</p> <p>No. 3 Recovery Boiler. B&W Contract PR-60. B&W Superheater Revamp Contract 546-1383 in 1998. Startup 1960.</p> <p>1.5 million ppd solids. Steam flow 202,000 lb/ hr. Operating @1275 psig & 900F. Design @ 1425 psig. Two drum boiler/direct contact evaporator</p> <p>February 11, 2004</p> <p>Superheater – large fishmouth rupture approx 5.5” in length & extending three quarters of way around the tube. Vertical edges of failure very thin; leading edge noticeably thinned by external metal loss. Failure in outlet tube of 26th secondary SH pendant from left wall (2nd from right wall). Tube material SA 213-T22</p> <p>Total downtime 72.53 hours.</p> <p>ESP was performed. Current irrevocable policy is to stay out of recovery area for 4 hours</p> <p>Non-critical Incident</p> <p>Rupture caused over pressurization of the furnace and a rapid loss in drum level. Gas and liquor fuels immediately tripped. An ESP was immediately initiated</p> <p>None installed</p> <p>See “How discovered”.</p> <p>No</p> <p>No</p> <p>Failed tube repaired by installing a straight section and a 180-degree lower bend. NDT identified 5 additional thinned tubes and sections were replaced</p> <p>High steam and flue gas temperatures causing wastage. High level of mechanical carryover creates localized reducing condition.</p> <p>Chromizing of leading edge of tube, air system upgrades and more sootblowers</p> <p>Last inspection June 2003. Cleaned with HCl (bromate stage canceled) in May 2001</p>
--	--

**APPENDIX A
SUMMARY OF RECOVERY BOILER INCIDENTS**

<p>2004 April - 31 Location: Unit: Size: Incident Date: Leak/Incident Loc: Downtime hrs due to leak/total: ESP? Classification: How discovered: Leak detection: Sequence of events: Bed cooling: Wash adjacent tube: Repair procedure: Root cause: Future prevention: Last full inspection:</p>	<p>Critical Incident No. 585 International Paper Company, Pine Bluff, Arkansas No. 4 Recovery Boiler. B&W Contract PR-113. B&W Revamp Contracts SC-1174 and SC-1248 in 1990. Startup 1967. 4.19 million ppd solids. Steam flow 514,000-lb/ hr. Operating @1275 psig & 925F. Design @ 1450 psig. Two drum boiler /direct contact evaporator February 16, 2004 Boiler Bank – 39th tube from right wall in the 5th row from bank outlet (cold side) sheared at lower drum. The 38th tube in the same row was leaking and washed the failed tube. Total downtime 55.98 hours ESP initiated. Current irrevocable policy is the stay out of recovery area 4 hours. Critical Incident Operator heard sound of failure and observed loss of drum level and furnace back pressure None installed On basis of sound and observations, operator tripped gas and liquor fuels immediately and actuated the ESP No Tube failure resulted from washing from an adjacent tube that failed due to near drum corrosion Failed tube plugged at both drums. NDT identified 10 additional tubes, which were plugged. Near drum corrosion Reduced lower generating bank sootblower pressures. Longer-term response included installing leak detection, weekly ash sampling, combustion tuning and scheduling a partial tube bank replacement during the next annual outage. Last inspection June 2003. Near drum NDT in 1999. Acid cleaned September 2003 with HCl and Bromate</p>
--	---

<p>2004 April – 32 Location: Unit: Size: Incident Date: Leak/Incident Loc: Downtime hrs due to leak/total: ESP? Classification: How discovered: Leak detection: Sequence of events: Bed cooling: Wash adjacent tube: Repair procedure: Root cause: Future prevention: Last full inspection:</p>	<p>Smurfit-Stone Container Corporation, Brewton, Alabama No. 1 Recovery Boiler. B&W Contract PR-32. Startup 1957. 1.2 million ppd solids. Steam flow 184,000 lb/hr. Operating @ 880 psig & 830F. Design @ 975 psig. Two drum boiler / 3 pass boiler bank/small horizontal tube economizer/DCE January 18, 2004 Boiler Bank – 6th tube in row 12 sheared off next to steam drum. Downtime due to ESP 50 hrs 52 min steam to steam. /Total downtime 55 hr 25 min liquor to liquor ESP Performed Non-critical Incident (the tube that sheared was to the rear of a flat stud baffle reported to extend to the drum shell plate leaving no gap. The baffle is tube row 13, counting from outlet) Helper noticed that the steam flow and the drum level dropped, and the boiler began to blow back. None installed Helper observing the level and flow drops called for the operator and the boiler was ESP'd No The 5th tube in the 11th row, which blistered and cracked, restrained the failed tube. Two additional tubes were found damaged on hydro. Tubes were plugged in steam and mud drums Bank is with original tubes from 1957 and no appreciable wear has been noticed in the past. The area will be checked closely on next outage. Last inspection June 2003. Chemically cleaned in 1983.</p>
--	---

**APPENDIX A
SUMMARY OF RECOVERY BOILER INCIDENTS**

<p>2004 April – 33</p> <p>Location:</p> <p>Unit:</p> <p>Size:</p> <p>Incident Date:</p> <p>Leak/Incident Loc:</p> <p>Downtime hrs due to leak/total:</p> <p>ESP?</p> <p>Classification:</p> <p>How discovered:</p> <p>Leak detection:</p> <p>Sequence of events:</p> <p>Bed cooling:</p> <p>Wash adjacent tube:</p> <p>Repair procedure:</p> <p>Root cause:</p> <p>Future prevention:</p> <p>Last full inspection:</p>	<p>Norske Canada, Crofton, British Columbia</p> <p>No. 4 Recovery Boiler. CE/ABB Contract CA-88105. Startup 1991.</p> <p>4.0 million ppd solids. Steam flow 588,700 lb/hr. Operating @ 600 psig and 750F. Design @ 800 psig. Single drum/large economizer</p> <p>December 29, 2003</p> <p>Boiler Bank – cracks in two ESP drain lines from bottom header of generating bank</p> <p>Total downtime 55 hours</p> <p>No</p> <p>Non-critical Incident</p> <p>Water noticed in ash conveyor</p> <p>Trasar leak detection system</p> <p>Mill had been down for Christmas curtailment. Boiler was warming up on oil and near line pressure when water was noticed running from generating bank conveyor</p> <p>No</p> <p>Not applicable</p> <p>Cracks were ground out and welded</p> <p>Expansion joints on ash hopper were binding causing drain lines to stress</p> <p>Check expansion guides on all drains from headers</p> <p>Acid fill and soak in 1996</p>
---	--

<p>2004 April – 34</p> <p>Location:</p> <p>Unit:</p> <p>Size:</p> <p>Incident Date:</p> <p>Leak/Incident Loc:</p> <p>Downtime hrs due to leak/total:</p> <p>ESP?</p> <p>Classification:</p> <p>How discovered:</p> <p>Leak detection:</p> <p>Sequence of events:</p> <p>Bed cooling:</p> <p>Wash adjacent tube:</p> <p>Repair procedure:</p> <p>Root cause:</p> <p>Future prevention:</p> <p>Last full inspection:</p>	<p>Critical Incident No. 586</p> <p>International Paper Company. Pine Bluff, Arkansas</p> <p>No. 4 Recovery Boiler. B&W Contract PR-113. B&W Revamp Contracts SC-1174 and SC-1248 in 1990. Startup 1967. Tubes installed this area in 1980 (SA178C, 0.165" wall)</p> <p>4.19 million ppd solids. Steam flow 514,000-lb/ hr. Operating @1275 psig & 925F. Design @ 1450 psig. Two drum boiler /direct contact evaporator</p> <p>January 11, 2004</p> <p>Boiler Bank – ¾" hole in the tube at the lower drum surface. 6th row from the bank gas outlet, 26th tube from the right sidewall</p> <p>Total downtime 55.25 hours</p> <p>No. Operators believed water was not entering the furnace because of the leak location (confirmed to be correct after shutdown)</p> <p>Critical Incident</p> <p>Operator looking for cause of a MFT found the leak.</p> <p>None installed</p> <p>Boiler tripped on high furnace pressure; all 3 FD fans shutdown. Shortly thereafter, low drum level alarmed and drum level indication went below range. Feedwater valve closed, liquor guns removed. SH drains opened & sootblowers retracted. Inspection found water running down rear of boiler bank hopper; nose arch determined to be dry. Boiler was secured</p> <p>Not applicable</p> <p>Four additional tubes were thinned</p> <p>Failed tube and the four thinned tubes were plugged.</p> <p>Near drum corrosion</p> <p>Reduced sootblower pressures in the generating bank. Partial retube scheduled for June 2004.</p> <p>Last inspection June 2003. Acid cleaned with HCl and Bromate September 2003</p>
---	---

**APPENDIX A
SUMMARY OF RECOVERY BOILER INCIDENTS**

<p>2004 April – 35 Location: Unit: Size: Incident Date: Leak/Incident Loc: Downtime hrs due to leak/total: ESP? Classification: How discovered: Leak detection: Sequence of events: Bed cooling: Wash adjacent tube: Repair procedure: Root cause: Future prevention: Last full inspection:</p>	<p>Critical Incident No. 587 International Paper Company, Pine Bluff, Arkansas No. 4 Recovery Boiler. B&W Contract PR-113. B&W Revamp Contracts SC-1174 and SC-1248 included lower furnace replacement in 1990. Startup 1967. 4.19 million ppd solids. Steam flow 514,000-lb/ hr. Operating @1275 psig & 925F. Design @ 1450 psig. Two drum boiler /direct contact evaporator September 6, 2003 Upper Furnace – irregular shaped hole ¾” long and ¼” wide in the right sidewall just above the tertiary airport level (54’ – 2” above floor) 9” above the composite tube weld line Total downtime 242 hours ESP initiated. Current irrevocable policy is to stay out of area 4 hours minimum Critical Incident – Note that this incident occurred prior to Incidents No. 31 and 34) Operator found the failure while looking for cause of a boiler water chemistry imbalance that operators suspected was caused by a leak. None installed Gas burners put in service to shutdown boiler to determine location of a suspected boiler bank leak. When burners shutdown, detailed walkdown began. Moisture observed on furnace wall and ESP initiated because there was a small char/salt cake accumulation in one corner of furnace No No Failed and thinned furnace wall tubes (20) identified by NDT to extend to approx 4 feet above the composite to carbon steel weld line and were replaced with sections of length as required. Some wastage under arch. Internal under deposit caustic corrosion Boiler acid cleaned. Water treatment will be changed to coordinated phosphate Last inspection June 2003. Acid cleaned with HCl and Bromate October 1999.</p>
--	---

<p>2004 April – 36 Location: Unit: Size: Incident Date: Leak/Incident Loc: Downtime hrs due to leak/total: ESP? Classification: How discovered: Leak detection: Sequence of events: Bed cooling: Wash adjacent tube: Repair procedure: Root cause: Future prevention: Last full inspection:</p>	<p>Georgia-Pacific, Leaf River Pulp Operations, New Augusta, Mississippi Gotaverken Contract No. 551-992. Startup 1984. 6.3 million ppd solids. Steam flow 898,000 lb/hr. Operating @ 1250 psig & 900F. Design @ 1490 psig. Single drum/large economizer November 8, 2003 Upper Furnace (cold side of lower side of nose arch) – 4” longitudinal split in the center of the outer radius of tube bend where lower side of arch joins the furnace wall. Arch tube in the corner along the left sidewall.~ 96 ft above the centerline of floor header Total downtime 107.67 hours ESP was performed. Non-critical Incident Operator on walkdown noticed steam coming out from behind insulation of dead space area inside the nose arch. ? --- Southland started 10 hours after ESP to apply sodium bicarbonate to a bed height several feet above the bottom of primary air ports. Application for 30 hours credited with saving 24 hours No Tube sectioned and replaced with new tubing. Water side stress assisted corrosion at site of a very heavy field weld Plan x-ray selected bends during 2004 annual outage to look for possible defects and linear indications Last inspection January 31, 2003. Chemical cleaned in 1999.</p>
--	---

Note: Flash-to-the-sky system did not have a positive drain to assure water draining to 8’ level. Feedwater flow was only partially stopped and water backfilled-raising level to 40’.

**APPENDIX A
SUMMARY OF RECOVERY BOILER INCIDENTS**

<p>2004 April – 37</p> <p>Location:</p> <p>Unit:</p> <p>Size:</p> <p>Incident Date:</p> <p>Leak/Incident Loc:</p> <p>Downtime hrs due to leak/total:</p> <p>ESP?</p> <p>Classification:</p> <p>How discovered:</p> <p>Leak detection:</p> <p>Sequence of events:</p> <p>Bed cooling:</p> <p>Wash adjacent tube:</p> <p>Repair procedure:</p> <p>Root cause:</p> <p>Future prevention:</p> <p>Last full inspection:</p>	<p>International Paper Company, Texarkana, Texas</p> <p>Recovery Boiler No. 2. B&W Contract PR-186. Startup 1986</p> <p>4.55 million ppd solids. Steam flow 763.000 lb/hr. Operating @ 1050 psig & 813F Design @ 1200 psig. Two drum boiler/large economizer</p> <p>January 2, 2004</p> <p>Upper furnace (above tertiary level) – ¼” longitudinal crack at front wall penthouse scallop bar attachment weld (tack weld) external to membrane wall furnace. Tube 16 from right sidewall.</p> <p>Total downtime 22.5 hours</p> <p>No</p> <p>Non-critical Incident</p> <p>Sootblower mechanic saw steam escaping from under the insulation</p> <p>None installed</p> <p>Mechanic called assistant operator and they removed insulation and lagging to determine that the steam was from an external tube leak.</p> <p>No</p> <p>No</p> <p>Crack ground and weld repaired</p> <p>To be determined.</p> <p>Last inspection April 2003. Cleaned in 1996 with HCl.</p>
--	--

Note: ESP Subcommittee questions that this should have been a continuous weld. A bar tack welded to the face of each tube can result in high stresses

<p>2004 April – 38</p> <p>Location:</p> <p>Unit:</p> <p>Size:</p> <p>Incident Date:</p> <p>Leak/Incident Loc:</p> <p>Downtime hrs due to leak/total:</p> <p>ESP?</p> <p>Classification:</p> <p>How discovered:</p> <p>Leak detection:</p> <p>Sequence of events:</p> <p>Bed cooling:</p> <p>Wash adjacent tube:</p> <p>Repair procedure:</p> <p>Root cause:</p> <p>Future prevention:</p> <p>Last full inspection:</p>	<p>Critical Incident No. 588</p> <p>International Paper Company, Roanoke Rapids, North Carolina</p> <p>No. 6 Recovery Boiler. CE Contract No. 17455. Startup 1956</p> <p>1.286 million ppd solids. Steam flow 188,000 lb/hr. Operating @ 820 psig & 760F. Design @ 1000 psig. Two drum boiler/direct contact evaporator</p> <p>September 1, 2003</p> <p>Upper Furnace – 1-½” linear indication at bottom of membrane weld on 2nd sidewall tube from rear wall at screen tube header just below arch</p> <p>Total downtime 50 hours</p> <p>ESP performed. Current irrevocable policy is to stay out of recovery area for 4 hours following ESP.</p> <p>Critical Incident</p> <p>Operator making scheduled rounds of boiler noticed water coming from under the insulation at corner of boiler</p> <p>Mass balance system in operation did not detect nor confirm leak. System noted as unreliable</p> <p>Water source traced to next higher floor. No evident external source. Inspection covers in insulation removed and insulation found wet. Door closest to water opened and whistling sound heard. Boiler was ESP'd.</p> <p>Sodium bicarbonate with nitrogen used and estimated to save 6-8 hours</p> <p>No</p> <p>Crack ground out and welded/ Membrane welded completely around the end.</p> <p>Stress crack resulting from improper modification of membrane weld to tube when weld removed at an earlier time; leak occurred where weld terminated</p> <p>Emphasize procedures that weld must be terminated properly at end of membrane bar</p> <p>Last inspection May 2003. Unit indicated as never chemically cleaned</p>
--	---

**APPENDIX A
SUMMARY OF RECOVERY BOILER INCIDENTS**

<p>2004 April – 39</p> <p>Location:</p> <p>Unit:</p> <p>Size:</p> <p>Incident Date:</p> <p>Leak/Incident Loc:</p> <p>Downtime hrs due to leak/total:</p> <p>ESP?</p> <p>Classification:</p> <p>How discovered:</p> <p>Leak detection:</p> <p>Sequence of events:</p> <p>Bed cooling:</p> <p>Wash adjacent tube:</p> <p>Repair procedure:</p> <p>Root cause:</p> <p>Future prevention:</p> <p>Last full inspection:</p>	<p>Smurfit-Stone Container Corporation, Florence, South Carolina</p> <p>No. 2 Recovery Boiler. B&W Contract PR-159.</p> <p>3.8 million ppd solids. Steam flow 560,000 lb/he. Operating @ 650 psig & 750F. Design at 950 psig. Two drum boiler/large economizer</p> <p>December 21, 2003</p> <p>Upper Furnace – ½” circumferential crack at welded attachment for insulation on mud drum level wall tube at dead air space formed by nose arch. Leak external to membrane wall enclosure</p> <p>Total downtime 19.5 hours</p> <p>No</p> <p>Non-critical Incident</p> <p>Weekend mechanic checking equipment in 7th floor area noticed steam and water coming from under insulation near the mud drum</p> <p>None installed</p> <p>Leak was on exterior of membrane wall furnace so orderly shutdown and bed burnout performed</p> <p>No</p> <p>No</p> <p>Ground out crack and repaired with carbon steel TIG wire.</p> <p>Improper attachment weld for insulation</p> <p>Last inspection November 2003. Unit indicated as never chemically cleaned.</p>
--	--

<p>2004 April – 40</p> <p>Location:</p> <p>Unit:</p> <p>Size:</p> <p>Incident Date:</p> <p>Leak/Incident Loc:</p> <p>Downtime hrs due to leak/total:</p> <p>ESP?</p> <p>Classification:</p> <p>How discovered:</p> <p>Leak detection:</p> <p>Sequence of events:</p> <p>Bed cooling:</p> <p>Wash adjacent tube:</p> <p>Repair procedure:</p> <p>Root cause:</p> <p>Future prevention:</p> <p>Last full inspection:</p>	<p>Critical Incident No. 589</p> <p>Pope & Talbot, Harmac Pulp Operations, Nanaimo, British Columbia</p> <p>Site Unit ID PV-S005. CE Contract No. CA 48108. Startup 1949</p> <p>1.0 million ppd solids. Steam flow 120,000 pph. Operating @ 600 psig & 750F. Design @ 675 psig. Three drum boiler/large horizontal tube economizer with water coil air heater</p> <p>January 6, 2004</p> <p>Upper Furnace – 1-½” longitudinal crack in 1” OD left sidewall tube No. 1 at approx 8 inches below the intermediate header located at approximately mud drum elevation. Boiler center supported by mud drum & intermediate headers. Header supports are cantilevered off of horizontal I – beams connected to boiler columns.</p> <p>Total downtime 96 hours</p> <p>ESP was performed. Area cleared for ~ 6 hrs.</p> <p>Critical Incident</p> <p>Operator and Shift Supervisor walking down the boiler.</p> <p>None installed</p> <p>Vapor noticed coming out of left sidewall header intermediate header cover. Cover opened and vapor noted as coming from behind casing. Operator and Supervisor returned to control room and ESP'd boiler. Bed cooled to “well below 1000F” before water washing started.</p> <p>No</p> <p>No</p> <p>Both sidewall tubes were replaced with a new section formed to clear the header.</p> <p>Waterside stress-assisted corrosion. (ESP Subcommittee suggests more likely fatigue failure) as The header had shifted over the years into the furnace approx 1 ½” forcing the 1st sidewall tubes out of line, thereby causing stress on the tube surface. The top flange of I-beam has tilted and header support plated bent and cracked allowing the header to move inward.</p> <p>Front wall header supports repaired to prevent further header movement. Plan to replace header and supports in the future.</p> <p>Last inspection June 2003. Acid cleaned in 1997.</p>
--	--

APPENDIX A
SUMMARY OF RECOVERY BOILER INCIDENTS

<p>2004 April – 41</p> <p>Location:</p> <p>Unit:</p> <p>Size:</p> <p>Incident Date:</p> <p>Leak/Incident Loc:</p> <p>Downtime hrs due to leak/total:</p> <p>ESP?</p> <p>Classification:</p> <p>How discovered:</p> <p>Leak detection:</p> <p>Sequence of events:</p> <p>Bed cooling:</p> <p>Wash adjacent tube:</p> <p>Repair procedure:</p> <p>Root cause:</p> <p>Future prevention:</p> <p>Last full inspection:</p>	<p>Critical Incident No. 590</p> <p>Bowater, Thunder Bay, Ontario, Canada</p> <p>“B” Recovery Boiler. CE Contract No. CA-74102. Startup 1976. Modifications 1999 & 2001. 3.5 million ppd solids. Steam flow 500,000 lb/hr. Operating at 850 psig & 900F. Design @ 1050 psig. Two drum boiler/small economizer/direct contact evaporator</p> <p>Mat 1, 2003</p> <p>Upper Furnace – ½” wide by 3 ¼” fish mouth rupture of front wall tube (48th from left wall) at 54’ above the floor. 16 ft length of tube affected by overhear</p> <p>Total downtime 80 hours</p> <p>ESP initiated. Current policy is to stay out of recovery area 12 hours</p> <p>Critical Incident</p> <p>Investigation by Shift Engineer of the noise of steam blowing discovered a leak</p> <p>None installed</p> <p>Operator instructed Assistant to check for a failed sootblower or one with bad packing. Boiler walkdown found no problem, so Operator shutdown sootblowers; noise continued. Another walkdown revealed sound of blowing steam to be internal to boiler. There were no problems with drum level, furnace pressure, boiler water, etc. Liquor was pulled & gas guns put in service. Inspected boiler starting in SH and working down. Leak identified in front wall tube above tertiary.</p> <p>No</p> <p>No</p> <p>16 ft tube section replaced</p> <p>Short term overhear. Circulation interrupted due to a 4” can lid blocking the tube at the lower header.</p> <p>Review incident with all outside contractors and with all recovery area O and M employees. Meetings with operators on ‘Indication of a Pressure Part Failure”. Better design of downcomer covers.</p> <p>No information</p>
--	--

<p>2004 April – 42</p> <p>Location:</p> <p>Unit:</p> <p>Size:</p> <p>Incident Date:</p> <p>Leak/Incident Loc:</p> <p>Downtime hrs due to leak/total:</p> <p>ESP?</p> <p>Classification:</p> <p>How discovered:</p> <p>Leak detection:</p> <p>Sequence of events:</p> <p>Bed cooling:</p> <p>Wash adjacent tube:</p> <p>Repair procedure:</p> <p>Root cause:</p> <p>Future prevention:</p> <p>Last full inspection:</p>	<p>Critical Incident No. 591</p> <p>Weyerhaeuser Company, Marlboro Mill, Bennettsville, South Carolina</p> <p>No. 1 Recovery Boiler. Ahlstrom Contract No. 5904. Startup 1990. Upgrade 1996. 4.4 million ppd solids. Steam flow 635,000 lb/hr. Operating @ 1080 psig & 850F. Design @ 1550 psig. Single drum boiler/large economizer. 1996 upgrade from 32. to 4.4 M ppd</p> <p>March 3, 2004</p> <p>Upper Furnace – ½” long circumferential crack with 2 tangential runners. Crack in the rear bent tube of lower crotch plate weld below #11 sootblower in superheater. Tube bent to form sootblower opening.</p> <p>Time from ESP to first fire 56 hours. /Total downtime 68 hours</p> <p>ESP initiated as orderly shutdown was progressing. Re-entry after 17 ½ hours (less than 24 requires Mill Manager approval)</p> <p>Critical Incident</p> <p>Operator on rounds saw vapor coming from sootblower wall box</p> <p>None installed</p> <p>Operator found no audible or visual signs of internal leak & instrumentation looked normal. Maintenance called to remove lagging. Vapor coming from refractory vent hole on wall box face. No signs of an internal leak and Manger cleared building and orderly shutdown started. Vapor flow increased even though pressure reduced. Mirror showed water entering the furnace and ESP initiated.</p> <p>No</p> <p>No</p> <p>Membrane removed and crack located with dye penetrant. Crack ground out, checked with dye penetrant, and TIG pad welded. Membrane was not replaced; filled with refractory.</p> <p>Crack in crotch plate membrane propagated into tube</p> <p>Continue to inspect and repair per manufacturer’s and inspectors’ recommendations.</p> <p>Inspected April 2003. Acid cleaned with HCl during 1990 startup</p>
--	---

Note: Report includes data for ESP initiation when pressure was 170 psig on boiler with flash-to-the-sky system to which low point drains were added in 2003. Water boiled for 27 hrs before level stabilized.

**APPENDIX A
SUMMARY OF RECOVERY BOILER INCIDENTS**

<p>2004 April – 43</p> <p>Location:</p> <p>Unit:</p> <p>Size:</p> <p>Incident Date:</p> <p>Leak/Incident Loc:</p> <p>Downtime hrs due to leak/total:</p> <p>ESP?</p> <p>Classification:</p> <p>How discovered:</p> <p>Leak detection:</p> <p>Sequence of events:</p> <p>Bed cooling:</p> <p>Wash adjacent tube:</p> <p>Repair procedure:</p> <p>Root cause:</p> <p>Future prevention:</p> <p>Last full inspection:</p>	<p>Critical Incident No. 592</p> <p>International Paper Company, Franklin, Virginia</p> <p>No. 4 Recovery Boiler. ABB-CE Contract No. 1263. Startup 1964</p> <p>1.75 million ppd solids. Steam flow 273,500 lb/hr. Operating @ 600 psig & 750F. Design @ 700 psig. Two drum boiler/small economizer/direct contact evaporator. Tangent tube furnace.</p> <p>December 4, 2003</p> <p>Lower Furnace – pinhole leak in the cold side of a front wall tube at the bend on the lower corner of a secondary airport 25 feet above the furnace floor.</p> <p>Total downtime 142 hours</p> <p>ESP initiated</p> <p>Critical Incident</p> <p>An operator saw steam and water dripping on a buckstay at the lower burner elevation on the front wall of the furnace</p> <p>Mass Balance System installed in 1998 was in operation but neither detected nor confirmed leak</p> <p>Due to the presence of water and the tangent tube wall construction, the decision was made to ESP</p> <p>No</p> <p>No</p> <p>Tested leak area for cracks; none found. Area ground out and welded. Area again tested.</p> <p>Waterside pitting (as there were no cracks, this was not believed to be SAC)</p> <p>Inspect lower furnace at buckstay locations for stress cracking at next annual outage.</p> <p>Last inspection June 2003. Acid cleaned with HCl January 2000</p>
--	--

<p>2004 April – 44</p> <p>Location:</p> <p>Unit:</p> <p>Size:</p> <p>Incident Date:</p> <p>Leak/Incident Loc:</p> <p>Downtime hrs due to leak/total:</p> <p>ESP?</p> <p>Classification:</p> <p>How discovered:</p> <p>Leak detection:</p> <p>Sequence of events:</p> <p>Bed cooling:</p> <p>Wash adjacent tube:</p> <p>Repair procedure:</p> <p>Root cause:</p> <p>Future prevention:</p> <p>Last full inspection:</p>	<p>International Paper Company, Riverdale Mill, Alabama</p> <p>No. 2 Recovery Boiler. CE Contract No. 28679. Startup 1980.</p> <p>2.7 million ppd solids. Steam flow 425,000 lb/hr. Operating @ 1500 psig & 900F. Design @ 1720 psig. Two drum boiler/large economizer</p> <p>August 4, 2003</p> <p>Smelt Spout – damage sustained over the course of a year from rodding at the spout discharge</p> <p>Total downtime 31.5 hours</p> <p>No</p> <p>Non-critical Incident</p> <p>Boiler Tender noticed a thin stream of water spraying from the smelt discharge end of the No. 2 smelt spout during a normal round</p> <p>Not applicable</p> <p>Water stream was not contacting smelt. Cooling water was shutoff and liquor removed from the boiler. Char burned out and boiler taken down normally</p> <p>Not applicable</p> <p>Not applicable</p> <p>Second spout also damaged. Both spouts replaced</p> <p>Behavioral training issue. Physical damage from blunt trauma force when rodding the spout and knocking frozen smelt from the discharge.</p> <p>All tenders shown damaged spouts and instructed on not beating the end of the spout with the rod and alerted to importance of inspecting spouts for damage</p>
--	---

APPENDIX A
SUMMARY OF RECOVERY BOILER INCIDENTS

<p>2004 April – 46</p> <p>Location:</p> <p>Unit:</p> <p>Size:</p> <p>Incident Date:</p> <p>Leak/Incident Loc:</p> <p>Downtime hrs due to leak/total:</p> <p>ESP?</p> <p>Classification:</p> <p>How discovered:</p> <p>Leak detection:</p> <p>Sequence of events:</p> <p>Bed cooling:</p> <p>Wash adjacent tube:</p> <p>Repair procedure:</p> <p>Root cause:</p> <p>Future prevention:</p> <p>Last full inspection:</p>	<p>Critical Incident No. 593</p> <p>Canadian Forest Products Ltd., Northwood Pulp, Prince George, British Columbia</p> <p>No. 1 Recovery Boiler. Alstom/CE Contract No. CA-64127. Startup 1966.</p> <p>3.3 million ppd solids. Steam flow 428,000 lb/hr. Design Pressure 750 psig. Two drum boiler/Direct contact evaporator</p> <p>December 16, 2003</p> <p>Furnace Screen – longitudinal hole ~ 1-5/8" long x 3/8" wide starting at a cut line weld in last tube of 12 tubes in the first platen from left wall. Tube wall had been thinned.</p> <p>Total downtime liquor to liquor 63 hours</p> <p>ESP initiated.</p> <p>Critical Incident</p> <p>Operator on walkdown with sootblowers off heard unexplained noise and observed vapor when a door was opened.</p> <p>None installed</p> <p>Boiler water residuals had been dropping for 2 days and walkdowns with sootblowers off and doors opened revealed no leak indication. Plant boiler trips revealed side-to-side drum level fluctuating differences and a noise on 7th floor was confirmed to not be sootblowers. ESP was initiated.</p> <p>No</p> <p>Yes. The opening faced the 2nd platen where 2 tubes were eroded. 2 adjacent tubes in platen #1 also thinned</p> <p>3 sections of tube replaced in screen platen # 1 and 2 in platen #2. Welds 100% x-rayed.</p> <p>Corrosion caused by water washing without firing to dry of an area where wet salt cake was not removed during cleaning and there was not drying procedure</p> <p>Inspect and repair any other damaged tubing. Conduct firing for drying</p> <p>Inspected October 2003. Last chemical cleaning date unknown</p>
--	---

APPENDIX A
SUMMARY OF RECOVERY BOILER INCIDENTS

<p>2004 April – INTL 1</p> <p>Location:</p> <p>Unit:</p> <p>Size:</p> <p>Incident Date:</p> <p>Leak/Incident Loc:</p> <p>Downtime hrs due to leak/total:</p> <p>ESP?</p> <p>Classification:</p> <p>How discovered:</p> <p>Leak detection:</p> <p>Sequence of events:</p> <p>Bed cooling:</p> <p>Wash adjacent tube:</p> <p>Repair procedure:</p> <p>Root cause:</p> <p>Future prevention:</p> <p>Last full inspection:</p>	<p>International Incident No. 1088</p> <p>Sappi Forest Products-Utusu, Swaziland-Bhunya</p> <p>Local Unit ID SB 10035. CE/ICAL Contract No. 38634. Startup September 29, 1961. Kvaerner revamp in 1996.</p> <p>516 t/d solids (1,138,000 ppd). Steam flow 60 t/h (132,000 lb/hr). Operation @ 620 psig. Design @ 750 psig. Two drum boiler/direct contact evaporator</p> <p>November 3, 2003</p> <p>Lower Furnace – several pinholes in an area 1 cm long in the rear wall at 1.8 meters (6 feet) above the floor</p> <p>Total downtime 151.75 hours</p> <p>ESP was performed. Current irrevocable policy is to stay out of recovery area for 24 hours.</p> <p>Poking rod came out of furnace wet from airports after observing local high bed. (Water was later observed spraying out onto and boiling on bed.)</p> <p>No special system.</p> <p>The char bed (estimated as 8 ft high) collapsed on the right rear corner blocking the air ports. Firing reduced to one-half and control restored two hours later. Bed collapse in the same corner occurred on the next shift and when ports were rodded, the port was wet. Boiler was ESP'd</p> <p>No</p> <p>No</p> <p>AF-IPK experts from Sweden flown in to do a UT scan of furnace tubes. 280 insert sections totaling 400 meters (1300 ft) were installed.</p> <p>Overheating due to a tube blockage by a foreign object</p> <p>NDT contractor told to equip themselves with UT equipment if they want to continue doing business with the mill. Believe paper toweling used by welders to enhance weld quality caused the partial blockage. Paper will not be permitted for future use.</p> <p>Last inspection May 2003. Acid washed over 15 years past.</p>
--	--

<p>2004 April – INTL 2</p> <p>Location:</p> <p>Unit:</p> <p>Size:</p> <p>Incident Date:</p> <p>Leak/Incident Loc:</p> <p>Downtime hrs due to leak/total:</p> <p>ESP?</p> <p>Classification:</p> <p>How discovered:</p> <p>Leak detection:</p> <p>Sequence of events:</p> <p>Bed cooling:</p> <p>Wash adjacent tube:</p> <p>Repair procedure:</p> <p>Root cause:</p> <p>Future prevention:</p> <p>Last full inspection:</p>	<p>International Incident No. 1089</p> <p>Carter Holt Harvey, Kinleith, Tokoroa, New Zealand</p> <p>Recovery Boiler No. 5. CE Canada Contract No. CE 8402. Startup 1985. Andritz Revamp Contract No. 782000 in 2002.</p> <p>1450 metric t/d (3.2 million ppd) solids. Steam flow 206 t/h (454,200 lb/hr). Operating @ 650 psig & 750F. Design at 870 psig. Two drum boiler/large economizer</p> <p>June 10, 2003</p> <p>Economizer – Two pinholes on supply header stub at 5-10 mm from the weld between header and stub. Stubs are 6.41" long and connected to element supply tubes. Internal surface eroded & full of cavities.</p> <p>Total downtime 87 hours</p> <p>No</p> <p>Operator inspection of economizer ash hopper found water.</p> <p>None installed</p> <p>Cold restart after 3-month outage. On finding water, feedwater/steam differential indicated 10-t/h leakage rate. Inspection failed to find location; operators confident was in lower end of economizer. Liquor firing continued due to RB4 not yet firing & difficulties getting RB5 "on liquor" RB5 taken off liquor approx 40 hours later. Leak determined to be on lower supply header.</p> <p>No</p> <p>No</p> <p>Header feed 9 elements through individual supply tubes. Full length of the 9 tubes was UT examined. Another 4 found below minimum wall. Also damage found to header. Five stubs cut off header. Seats prepared and new, longer stubs installed. Header welds stress relieved. Flow damage to header opening ground smooth.</p> <p>Flow assisted corrosion</p> <p>More frequent UT inspection. Next shutdown UT lower & upper headers and tubes.</p> <p>Last inspection July 2002. Chemically cleaned July 2002 – HCl Fill & Soak.</p>
--	--

APPENDIX A
SUMMARY OF RECOVERY BOILER INCIDENTS

<p>2004 April – INTL 3 Location: Unit: Size: Incident Date: Leak/Incident Loc: Downtime hrs due to leak/total: ESP? Classification: How discovered: Leak detection: Sequence of events: Bed cooling: Wash adjacent tube: Repair procedure: Root cause: Future prevention: Last full inspection:</p>	<p>International Incident No. 1090 Votorantim Celulose e Papel – Jacareí, São Paulo State, Brazil CBC Industrias Pesadas SA. Startup 2002 5.5 million ppd solids (2500 MT/d). Steam flow 862,400 lb/hr (392 MT/hr). Operation at 1316 psig (92,5 Kgf/cm²) & 896F (480C). Single drum/large economizer. May 3, 2003 <p style="text-align: center;">Cable tray fire & convection bank tube leaks at hydro</p> Total downtime 305 hours No Non-critical Incident (Classified by BRBSC-Brazilian Recovery Boiler Safety Committee) Instruments failed, boiler was tripped, and local inspection was made. Acoustic leak detection installed but not applicable in this area. After repairs of boiler shutdown, while getting ready for the hydro, a suspicious area was found at the convection bank hopper at the lower header. With 85 Kgf/cm² leaks were detected at the welded plugs of panel 01 and 02. No No Area at the two welded plugs was ground, cleaned and rewelded by CBC. Weld cracks at plugs. Next shutdown all insulation plates covering the plugs will be removed, refractory as well, and dye check in all welds will be made. CBC will check the welding procedures used during erection. June 2002</p>
--	---

<p>2004 April – INTL 4 Location: Unit: Size: Incident Date: Leak/Incident Loc: Downtime hrs due to leak/total: ESP? Classification: How discovered: Leak detection: Sequence of events: Bed cooling: Wash adjacent tube: Repair procedure: Root cause: Future prevention: Last full inspection:</p>	<p style="text-align: center;">International Incident No. 1091 Celulose Nipo-Brasileira S/A – CENIBRA – Belo Oriente, Minas Gerais State, Brazil CBC – Industrias Pesadas S/A . Startup 1992 4.5 million ppd solids (2050 MT/d). Steam flow 807,400 lb/hr (367 MT/hr). Operation at 924 psig (65 Kgf/cm²) & 842F(450C). Two-drums/large economizer. June 9, 2003 Economizer – tube No. 94 of 4th panel of No.2 economizer, exit gas direction, presented an air bubble pore. Total downtime 37 hours. No Non-critical Incident (Classified by BRBSC- Brazilian Recovery Safety Committee). Operator noticed wet ash in the economizer hopper during inspection. None installed. After finding wet ash, oil burners were placed in service as liquor burners removed. Economizer doors at lower header elevation opened. Visual inspection determined leak location. Boiler taken off line and cooled. No No Weld was cleaned, dye check performed, new weld made and last dye checked. Weld porosity. More detailed inspection at welds next shutdown. May 2003</p>
--	--

APPENDIX A
SUMMARY OF RECOVERY BOILER INCIDENTS

<p>2004 April – INTL 5 Location: Unit: Size: Incident Date: Leak/Incident Loc: Downtime hrs due to leak/total: ESP? Classification: How discovered: Leak detection: Sequence of events: Bed cooling: Wash adjacent tube: Repair procedure: Root cause: Future prevention: Last full inspection:</p>	<p>International Incident No. 1092 Votorantim Celulose e Papel – Jacareí, São Paulo State, Brazil CBC Industrias Pesadas S/A. Startup 2002 5.5 million ppd solids (2500 MT/d). Steam flow 862,400 lb/hr (392 MT/hr). Operation at 1316 psig (92,5 Kgf/cm²) & 896F (480C). Single drum/large economizer. July 27, 2003 Economizer - inspection plug at upper header of No.1 economizer. Total downtime 33 hours No Non-critical Incident – (Classified by BRBSC-Brazilian Recovery Safety Committee). Local inspection by Operator detected wet ash. Acoustic leak detection installed, but not applicable in this area. After detecting the leak, reduction procedures to reduce the liquor were started, bed was reduced, and reduction of pressure was started in a coordinated way. No No Area at the welded plug was grinded, cleaned and rewelded again. Three more plugs showed penetration after dye check, found pores and cracks, grinded and rewelded. Weld cracks at inspection plugs. Next shutdown all plugs, 96 total, will be dye checked. Other similar points will be discussed with CBC in areas like convection bank, drum, etc. Install an inspection door at the top of economizers. Clean the plugs with hydro jets. Maintenance is studying better tools to optimize repair procedures. June 2002.</p>
---	---

<p>2004 April – INTL 6 Location: Unit: Size: Incident Date: Leak/Incident Loc: Downtime hrs due to leak/total: ESP? Classification: How discovered: Leak detection: Sequence of events: Bed cooling: Wash adjacent tube: Repair procedure: Root cause: Future prevention: Last full inspection:</p>	<p>International Incident No. 1093 Votorantim Celulose e Papel. – Jacareí, São Paulo State, Brazil. CBC Industrias Pesadas S/A. Startup 2002. 5.5 million ppd solids (2500 MT/d). Steam flow 862,400 lb/hr (392 MT/hr). Operation at 1316 psig (92,5 Kgf/cm²) & 896F (480C). Single drum/large economizer. December 7, 2003 Evaporator (Convactor or Boiler Bank)– Small leaks followed by rupture of tube No. 9, 1st row of tubes from left to right side wall, elevation 42,100 mm, lower part of evaporator. Total downtime 65.5 hours No Critical Incident – (Classified by BRBSC- Brazilian Recovery Boiler Safety Committee) Sudden variation of drum pressure and drum level. Boiler tripped by logic system. In the field, Operator noticed abnormalities. Acoustic leak detection installed but not applicable in this area. Boiler was burning only liquor, level and pressure variations started in the drum tripping the unit. Operator detected water at the feeding screw of convactor. No water in the furnace was noted. Reduction of pressure was significant. Level was difficult to maintain because of the great loss of water. Boiler was cooled in order to start repairs. No Leak of tubes No. 8 and 10 washed tube No.9 that ruptured. A total of 14 adjacent tubes were inspected. Seven (7) tube nipples were cut and changed. Hydro with 135 Kgf/cm² was applied and given as OK by official inspection company. Bad field welding job caused fatigue cracks in tubes No.8 and 10, which leaked and ruptured tube No. 9. Welding procedures will be checked at first opportunity and some changes at the original project will be made to avoid new incidents in this area. Repairs will be made in all 61 panels. Welds shall be inspected by dye-check and visually. July 2003</p>
---	--

APPENDIX A
SUMMARY OF RECOVERY BOILER INCIDENTS

<p>2004 April – INTL 7 Location: Unit: Size:</p> <p>Incident Date: Leak/Incident Loc: Downtime hrs due to leak/total: ESP? Classification: How discovered: Leak detection: Sequence of events:</p> <p>Bed cooling: Wash adjacent tube: Repair procedure:</p> <p>Root cause: Future prevention: Last full inspection:</p>	<p style="text-align: center;">International Incident No. 1094</p> <p style="text-align: center;">Votorantim Celulose e Papel – Luis Antonio, São Paulo State, Brazil</p> <p>CBC Indústrias Pesadas S/A . Startup 1991. 3.1 million ppd solids (1400 MT/d). Steam flow 473,000 lb/hr (215 MT/h). Operation at 959 psig (67 Kgf/cm²) & 842F (450C). Two-drums/large economizer. August 13, 2003</p> <p>Tertiary Superheater – Pit corrosion of 8 tubes at straight length of last tube. No downtime.</p> <p>No</p> <p>Non-critical Incident – (Classified by BRBSC-Brazilian Recovery Safety Committee) During local inspection at annual shutdown.</p> <p>No</p> <p>Inspection company noted pit corrosion at the tertiary SH. Hydrostatic test was made and the tubes were leaking. Repair was made, another hydro was performed and given OK.</p> <p>No</p> <p>No</p> <p>Replacement of tubes: one curve of No.13 SH coil; 18-ft straight parts of last tubes of SH coil No.10 to 16, and 6-ft of SH coil No.23.</p> <p>Corrosion of deposits at hottest coil of SH. Analysis of deposits should indicate a possible cause. More intense inspection of corroded tubes during next outage.</p> <p>May 2002</p>
--	---

<p>2002 April – INTL 8 Location: Unit: Size:</p> <p>Incident Date: Leak/Incident Loc: Downtime hrs due to leak/total: ESP? Classification:</p> <p>How discovered: Leak detection: Sequence of events:</p> <p>Bed cooling: Wash adjacent tube: Repair procedure:</p> <p>Root cause: Future prevention: Last full inspection:</p>	<p style="text-align: center;">International Incident No. 1095</p> <p style="text-align: center;">Klabin Papeis SC – Otacílio Costa, Santa Catarina State, Brazil</p> <p>CBC Industrias Pesadas S/A . Startup 1998. 2.4 million ppd solids (1100 MT/d). Steam flow 374,000 lb/hr (170 MT/h). Operation at 1262 psig (87 Mpa) & 901F (483C). Single drum/large economizer August 11, 2003</p> <p>Economizer – Crack at tube No° 20C in the upper header “D” high temperature coil. Total downtime 39-hours</p> <p>No</p> <p style="text-align: center;">Non-critical Incident. (Classified by BRBSC – Brazilian Recovery Boiler Safety Committee)</p> <p>Operator noted wet ash in the sulfate screw at bottom of economizer and steam-water relation changed in the DCS at control room.</p> <p>None installed.</p> <p>After finding wet ash, oil burners were lighted and liquor was stopped. Local inspection showed leak area, and boiler was taken off line and cooled.</p> <p>No</p> <p>Yes. Tube N° 21C at header C. Tubes No. 20C and 21C that leaked were welded at header D. Tube 22B header D, cracked and was welded. Tube 26D header D, had small crack, also welded. Rewelded tubes 44B header E and 55A at header F. CBC followed their welding procedure. Dye check was performed. Possible excessive vibration between tubes developed stress that caused the leaks. Inspection at next shutdown, considering addition of extra clamps to lower vibration factor.</p> <p>September 2002</p>
--	---

BRBSC


***BRAZILIAN RECOVERY
BOILER SAFETY
COMMITTEE***

5 years of activities

Chairman 2004: Guido Schreiber

BRBSC***OBJECTIVES OF THE BRAZILIAN
RECOVERY BOILER SAFETY
COMMITTEE (BRBSC)***

The main objective of the Committee is to increase the safety of the chemical recovery boilers by interchanging technical information, experiences and statistical data in order to optimize the boiler installations, its operating practices and maintenance procedures.



BRBSC

EMERGENCY SHUTDOWN

SUBCOMMITTEE

BRBSC**ACCOMPLISHED ACTIVITIES**

- ☪ **Updated List of Recovery Boilers in Brazil; (*)**
- ☪ **Incidents in 2002, 2003/04; (*)**
- ☪ **Classification of Incidents;**
- ☪ **Statistics; (*)**
- ☪ **Questionnaire of Incidents. (*)**

(*) Available for download on ABTCP site: www.abtcp.org.br

BRBSC**CHEMICAL RECOVERY BOILERS IN BRAZIL**

LIST OF RECOVERY BOILERS IN BRAZIL - Brazilian Recovery Boiler Safety Committee - Emergency Shutdown Subcommittee

#	Company	Supplier	Start up year	Revamp year	Size Mppd solids	Pressure psig	Temp °F	Steam tons/h	Observations
1	Aracruz Celulose	Kvaerner	2001		8.14	910	842	576	
2	Aracruz Celulose	Gotaverken	1991	2002	8.14	910	842	576	
3	Aracruz Celulose	Ahlstrom	1997	2000	6.82	910	842	500	
4	Aracruz - Guaíba	Gotaverken	1972		2.64	1010	860	176	out of operation
5	Aracruz - Guaíba	Babcock & Wilcox	2002		4.29	910	860	330	
6	Bacell	CBC	1995		1.98	896	842	119	
7	Bahia Sul Celulose	Gotaverken	1992	2001	7.04	1209	903	462	
8	CENIBRA	CBC	1977	2003	3.96	924	842	275	
9	CENIBRA	CBC	1992		6.16	924	842	462	
10	COCELPA	Gotaverken	1988		.48	634	797	33	
11	Iguacu	São Caetano	1972		.23	228	399	26	
12	International Paper	B&W	1976		.69	412	662	38	
13	International Paper	B&W	1985		2.31	412	662	154	
14	IPB	Conservit	1981		.62	299	421	44	out of operation
15	Itapagé Artefatos	CBC	1972		.39	597	752	16	
16	Jarí Celulose	B&W/Gotaverken	1979	1988	3.41	924	842	231	
17	Klabin-Correa Pinto	CBC	1987		1.76	1209	896	105	
18	Klabin-Telemaco Borba	Gotaverken	1977	2000	3.74	654	806	146	
19	Klabin-Otacílio Costa	Gotaverken	1987		.92	584	752	59	
20	Klabin-Otacílio Costa	CBC	1998		2.20	1240	901	159	
21	Lwarcel	CBC	2002		.99	1209	896	61	
22	Nobrecel		1999						Informations being sent
23	Orsa	Gotaverken	1982		.57	270	392	33	
24	Rigesa	B&W	1987		.55	597	698	39	
25	Rigesa	Ahlstrom	1999		1.87	597	860	139	
26	Ripasa	Gotaverken	1972		1.14	597	752	79	
27	Ripasa	Gotaverken	1981	2001	1.16	597	752	79	
28	Ripasa	CBC	2002		2.42	597	752	198	
29	Suzano	Gotaverken	1973		1.65	711	788	110	
30	Suzano	CBC	1987	2002	2.11	711	788	159	
31	Trombini	BW/Orcepa	1989	2000	.41	299	752	28	
32	VCP- Luiz Antonio	CBC	1991	1995	3.30	910	842	245	
33	VCP- Jacarei	CBC	1994		3.74	1251	896	270	
34	VCP- Jacarei	CBC	2002		6.07	1251	896	431	
35	Veracel Celulose	Kvaerner	2005		8.80	1337	914	662	Project Phase

Obs - Boilers no. 11 and 19 are out of operation
- Updated in March 2004

BRBSC***STATUS OF REC BOILERS***

- Ç **35 Recovery Boilers;**
 - **32 in operation**
 - **02 not in operation**
 - **01 in project phase**
- Ç **13 new boilers or overhauled in the last 2 years;**
- Ç **Average age of boilers : 14 years;**
- Ç **Average production per boiler: 2.84 million ppd solids**

BRBSC***INCIDENTS IN 2002***

Company	Incident number	Date of event	Incident questionnaire	Presented in session	Incident description
Klabin Bancel	1	Jan 1,02	yes	yes	Screen tube rupture
CENIBRA	2	Jan 23,02	yes	yes	Crack in superheater
Rigesa	3	Apr 4,02	yes	yes	Crack in superheater
VCP-Jacarei	4	Apr 4,02	yes	yes	Dissolving tank explosion
Orsa	5	Jun 27,02	yes	yes	Dissolving tank explosion
Bahia Sul	6	Aug 26,02	yes	yes	Economizer leak
VCP-LA	7	Jul 20,02	yes	yes	Superheater leak
Aracruz	8	Sep 10,02	yes	yes	Economizer leak- Boiler A
CENIBRA	9	Oct 20,02	yes	yes	Superheater leak


BRBSC**INCIDENTES IN 2003/04**

Company	Incident Number	Date of Incident	Incident Questionnaire	Presented in session	Incident Description
VCP - Jacarei	1	May 2,03	yes	yes	fire in cable tray and convector tube leak
CENIBRA	2	Jun 6,03	yes	no	leak in economizer (weld pore)
VCP - Jacarei	3	Jul 20,03	yes	no	leak in economizer (inspection plug)
KLABIN - OC	4	Aug11,03	yes	no	economizer tube crack
VCP - Luis A	5	Aug13,03	yes	no	pit corrosion in economizer (leak during hydro)
VCP - Jacarei	6	Dec7,03	yes	no	evaporator tube rupture

BRBSC

STATISTICS

No. of incidents per year in Brazil



BRBSC**PERFORMED ACTIVITIES****Recovery Boiler Operator Seminars
in Brazil**

Year	Mill
2000-	CENIBRA
2001-	ARACRUZ
2002-	VCP -Luiz Antônio
2003-	RIPASA
2004-	LWARCEL (set for Nov/04)

Objective: Interchange of informations and experiences related to the day-a-day operation of a Recovery Boiler.

BRBSC

***THANK
YOU!***